

NC School District/830 Scotland County/High School

Scotland High

Final

Campus Assessment Report

March 11, 2017



Table of Contents

Campus Executive Summary	11
Campus Dashboard Summary	14
Campus Condition Summary	15
<u>1967 Football Pressbox</u>	17
Executive Summary	17
Dashboard Summary	18
Condition Summary	19
Photo Album	20
Condition Detail	21
System Listing	22
System Notes	23
Renewal Schedule	27
Forecasted Sustainment Requirement	29
Deficiency Summary By System	30
Deficiency Summary By Priority	31
Deficiency By Priority Investment	32
Deficiency Summary By Category	33
Deficiency Details By Priority	34
<u>1967 Gym Building</u>	35
Executive Summary	35
Dashboard Summary	36
Condition Summary	37
Photo Album	38
Condition Detail	39
System Listing	40
System Notes	42
Renewal Schedule	53
Forecasted Sustainment Requirement	56
Deficiency Summary By System	57

Campus Assessment Report

Deficiency Summary By Priority	58
Deficiency By Priority Investment	59
Deficiency Summary By Category	60
Deficiency Details By Priority	61
<u>1967 Restroom Building</u>	65
Executive Summary	65
Dashboard Summary	66
Condition Summary	67
Photo Album	68
Condition Detail	69
System Listing	70
System Notes	71
Renewal Schedule	76
Forecasted Sustainment Requirement	78
Deficiency Summary By System	79
Deficiency Summary By Priority	80
Deficiency By Priority Investment	81
Deficiency Summary By Category	82
Deficiency Details By Priority	83
<u>1967 Storage Building</u>	84
Executive Summary	84
Dashboard Summary	85
Condition Summary	86
Photo Album	87
Condition Detail	88
System Listing	89
System Notes	90
Renewal Schedule	96
Forecasted Sustainment Requirement	98
Deficiency Summary By System	99
Deficiency Summary By Priority	100

Campus Assessment Report

Deficiency By Priority Investment	101
Deficiency Summary By Category	102
Deficiency Details By Priority	103
<u>1967, 1977 Main Building</u>	105
Executive Summary	105
Dashboard Summary	106
Condition Summary	107
Photo Album	108
Condition Detail	109
System Listing	110
System Notes	112
Renewal Schedule	126
Forecasted Sustainment Requirement	129
Deficiency Summary By System	130
Deficiency Summary By Priority	131
Deficiency By Priority Investment	132
Deficiency Summary By Category	133
Deficiency Details By Priority	134
<u>1977 Baseball Pressbox</u>	142
Executive Summary	142
Dashboard Summary	143
Condition Summary	144
Photo Album	145
Condition Detail	146
System Listing	147
System Notes	148
Renewal Schedule	151
Forecasted Sustainment Requirement	153
Deficiency Summary By System	154
Deficiency Summary By Priority	155
Deficiency By Priority Investment	156

Campus Assessment Report

Deficiency Summary By Category	157
Deficiency Details By Priority	158
<u>1977 Technology Building</u>	159
Executive Summary	159
Dashboard Summary	160
Condition Summary	161
Photo Album	162
Condition Detail	163
System Listing	164
System Notes	165
Renewal Schedule	173
Forecasted Sustainment Requirement	175
Deficiency Summary By System	176
Deficiency Summary By Priority	177
Deficiency By Priority Investment	178
Deficiency Summary By Category	179
Deficiency Details By Priority	180
<u>1979 Fieldhouse</u>	181
Executive Summary	181
Dashboard Summary	182
Condition Summary	183
Photo Album	184
Condition Detail	185
System Listing	186
System Notes	187
Renewal Schedule	195
Forecasted Sustainment Requirement	197
Deficiency Summary By System	198
Deficiency Summary By Priority	199
Deficiency By Priority Investment	200
Deficiency Summary By Category	201

Campus Assessment Report

Deficiency Details By Priority	202
<u>1991 Addition</u>	203
Executive Summary	203
Dashboard Summary	204
Condition Summary	205
Photo Album	206
Condition Detail	207
System Listing	208
System Notes	210
Renewal Schedule	219
Forecasted Sustainment Requirement	221
Deficiency Summary By System	222
Deficiency Summary By Priority	223
Deficiency By Priority Investment	224
Deficiency Summary By Category	225
Deficiency Details By Priority	226
<u>1999 Visitor Concession Stand</u>	227
Executive Summary	227
Dashboard Summary	228
Condition Summary	229
Photo Album	230
Condition Detail	231
System Listing	232
System Notes	233
Renewal Schedule	240
Forecasted Sustainment Requirement	242
Deficiency Summary By System	243
Deficiency Summary By Priority	244
Deficiency By Priority Investment	245
Deficiency Summary By Category	246
Deficiency Details By Priority	247

Campus Assessment Report

<u>2005 Weight Room</u>	248
Executive Summary	248
Dashboard Summary	249
Condition Summary	250
Photo Album	251
Condition Detail	252
System Listing	253
System Notes	254
Renewal Schedule	261
Forecasted Sustainment Requirement	263
Deficiency Summary By System	264
Deficiency Summary By Priority	265
Deficiency By Priority Investment	266
Deficiency Summary By Category	267
Deficiency Details By Priority	268
<u>2008 Storage Building</u>	269
Executive Summary	269
Dashboard Summary	270
Condition Summary	271
Photo Album	272
Condition Detail	273
System Listing	274
System Notes	275
Renewal Schedule	278
Forecasted Sustainment Requirement	279
Deficiency Summary By System	280
Deficiency Summary By Priority	281
Deficiency By Priority Investment	282
Deficiency Summary By Category	283
Deficiency Details By Priority	284
<u>2009 Soccer Storage Building</u>	285

Campus Assessment Report

Executive Summary	285
Dashboard Summary	286
Condition Summary	287
Photo Album	288
Condition Detail	289
System Listing	290
System Notes	291
Renewal Schedule	297
Forecasted Sustainment Requirement	299
Deficiency Summary By System	300
Deficiency Summary By Priority	301
Deficiency By Priority Investment	302
Deficiency Summary By Category	303
Deficiency Details By Priority	304
<u>2009 Softball Pressbox</u>	305
Executive Summary	305
Dashboard Summary	306
Condition Summary	307
Photo Album	308
Condition Detail	309
System Listing	310
System Notes	311
Renewal Schedule	315
Forecasted Sustainment Requirement	317
Deficiency Summary By System	318
Deficiency Summary By Priority	319
Deficiency By Priority Investment	320
Deficiency Summary By Category	321
Deficiency Details By Priority	322
<u>2012 Concession Building</u>	323
Executive Summary	323

Campus Assessment Report

Dashboard Summary	324
Condition Summary	325
Photo Album	326
Condition Detail	327
System Listing	328
System Notes	329
Renewal Schedule	335
Forecasted Sustainment Requirement	337
Deficiency Summary By System	338
Deficiency Summary By Priority	339
Deficiency By Priority Investment	340
Deficiency Summary By Category	341
Deficiency Details By Priority	342
<u>2015 Baseball Pressbox</u>	343
Executive Summary	343
Dashboard Summary	344
Condition Summary	345
Photo Album	346
Condition Detail	347
System Listing	348
System Notes	349
Renewal Schedule	353
Forecasted Sustainment Requirement	355
Deficiency Summary By System	356
Deficiency Summary By Priority	357
Deficiency By Priority Investment	358
Deficiency Summary By Category	359
Deficiency Details By Priority	360
<u>2015 Laundromat Building</u>	361
Executive Summary	361
Dashboard Summary	362

Campus Assessment Report

Condition Summary	363
Photo Album	364
Condition Detail	365
System Listing	366
System Notes	367
Renewal Schedule	375
Forecasted Sustainment Requirement	377
Deficiency Summary By System	378
Deficiency Summary By Priority	379
Deficiency By Priority Investment	380
Deficiency Summary By Category	381
Deficiency Details By Priority	382
Site	383
Executive Summary	383
Dashboard Summary	384
Condition Summary	385
Photo Album	386
Condition Detail	387
System Listing	388
System Notes	389
Renewal Schedule	395
Forecasted Sustainment Requirement	396
Deficiency Summary By System	397
Deficiency Summary By Priority	398
Deficiency By Priority Investment	399
Deficiency Summary By Category	400
Deficiency Details By Priority	401

Campus Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Gross Area (SF):	285,240
Year Built:	1967
Last Renovation:	
Replacement Value:	\$67,064,418
Repair Cost:	\$13,538,819.91
Total FCI:	20.19 %
Total RSLI:	34.80 %
FCA Score:	79.81



Description:

GENERAL:

Scotland High School is located at 100 West Church Street in Laurinburg, North Carolina. The 2 story, 178,900 square foot building was originally constructed in 1967. There have been 4 additions or no major renovations. In 1967 a gym building was constructed, in 1977 a technology building was constructed, in 1991 an addition was constructed which houses a gymnasium, and in 2015 a new laundromat building was constructed. In addition to the main building, the campus contains ancillary buildings; storage, pressbox, concession/restrooms, and fieldhouse.

This report contains condition and adequacy data collected during the 2016 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report for the site and building elements.

A. SUBSTRUCTURE

Campus Assessment Report - Scotland High

The building rests on footings and foundation walls and is assumed to have standard cast-in-place concrete foundations. The building does not have a basement.

B. SUPERSTRUCTURE

Floor construction is metal pan deck with lightweight fill. Roof construction is metal pan deck with lightweight fill. The exterior envelope is composed of walls of brick veneer over CMU. Exterior windows are aluminum frame with fixed panes. Exterior doors are hollow metal steel mostly with glazing. Roofing is typically low slope built-up and pitched standing metal roof. Roof openings include roof hatches with fixed ladder access. Most building entrances appear to comply with ADA requirements.

C. INTERIORS

Interior partitions are typically CMU and drywall. Interior doors are generally hollow core wood with wood frames and mostly without glazing. Interior fittings include the following items: white boards, graphics and identifying devices, lockers, toilet accessories, storage shelving, handrails, and fabricated toilet partitions. Stair construction includes steel risers and concrete treads with terrazzo and epoxy finishes. The interior wall finishes are typically painted CMU and painted drywall. Floor finishes in common areas are typically terrazzo. Floor finishes in assignable spaces is typically vinyl composition tile, carpet, ceramic tiles, quarry tiles, and wood. Ceiling finishes in common areas are typically suspended acoustical tile. Ceiling finishes in assignable areas are typically painted drywall.

CONVEYING:

The building does include conveying equipment. Conveying equipment includes 1 geared traction elevators, and no wheelchair lifts.

D. SERVICES

PLUMBING: Plumbing fixtures are typically low-flow water fixtures with manual control valves. Domestic water distribution is combination of copper and galvanized steel with gas hot water heating. Sanitary waste system is cast iron. Rain water drainage system is internal with roof drains. Other plumbing systems is supplied by natural gas.

HVAC:

Heating is provided by 3 gas fired boilers. Cooling is supplied by water cooled chillers and cooling towers. The heating/cooling distribution system is a ductwork system utilizing air handling units. Fresh air is supplied by air handling units. Ceiling mounted exhaust fans are installed in bathrooms and other required areas. Controls and instrumentation are digital and are centrally controlled by an energy management system. This building has a remote Building Automation System.

FIRE PROTECTION:

The building does not have a fire sprinkler system. The building does not have additional fire suppression systems. Standpipes are not included within fire stairs. Fire extinguishers and cabinets are distributed near fire exits and corridors.

ELECTRICAL:

The main electrical service is fed from a pad mounted transformer to the main switchboard/distribution panel located in the building. Lighting is lay-in type, fluorescent light fixtures. Branch circuit wiring is typically copper serving electrical switches and receptacles. Emergency and life safety egress lighting systems are installed and exit signs are present at exit doors and near stairways and are typically illuminated.

COMMUNICATIONS AND SECURITY:

The fire alarm system consists of audible/visual strobe annunciators in all common spaces. The system is activated by manual pull stations and smoke detectors and the system is centrally monitored. The telephone and data systems are segregated and include dedicated equipment closets. This building does have a local area network (LAN). The building includes an internal security system that is actuated by the following items: contacts, infrared, optical or a combination of all devices. The building has controlled entry doors access provided by camera access at the main door; entry doors are secured with magnetic door locks. The security system has CCTV cameras and is centrally monitored; this building has a public address and paging system combined with the telephone system.

OTHER ELECTRICAL SYSTEMS:

This building does have a separately derived emergency power system. There is 1 natural gas emergency generator.

E. EQUIPMENT & FURNISHINGS:

This building includes the following items and equipment: fixed food service, library equipment, athletic equipment, theater and stage, audio-visual, laboratory, vehicle equipment, fixed casework, and multiple seating furnishings.

G. SITE

Campus site features include paved driveways and parking lots, pedestrian pavement, flag pole, landscaping, play areas, and fencing. Site mechanical and electrical features include water, sewer, natural gas, and site lighting.

Campus Assessment Report - Scotland High

Attributes:

General Attributes:





Condition Assessor: Somnath Das Assessment Date:
Suitability Assessor:

School Information:

HS Attendance Area:		LEA School No.:	
No. of Mobile Units:	0	No. of Bldgs.:	1
SF of Mobile Units:		Status:	
School Grades:	65	Site Acreage:	65

Campus Dashboard Summary

Gross Area:	285,240	Last Renovation:	
Year Built:	1967	Replacement Value:	\$67,064,418
Repair Cost:	\$13,538,820	RSLI%:	34.80 %
FCI:	20.19 %		



Campus Condition Summary

The Table below shows the RSLI and FCI for each major system shown at the UNIFORMAT II classification Level 2. Note that Systems with lower FCIs require less investment than systems with higher FCIs.


Current Investment Requirement and Condition by Uniformat Classification

UNIFORMAT Classification	RSLI%	FCI %	Current Repair
A10 - Foundations	61.69 %	0.00 %	\$0.00
A20 - Basement Construction	53.27 %	0.00 %	\$0.00
B10 - Superstructure	53.75 %	0.00 %	\$0.00
B20 - Exterior Enclosure	32.60 %	9.09 %	\$625,716.37
B30 - Roofing	41.43 %	21.64 %	\$383,296.00
C10 - Interior Construction	31.11 %	3.99 %	\$106,013.00
C20 - Stairs	50.21 %	0.00 %	\$0.00
C30 - Interior Finishes	53.73 %	3.41 %	\$243,309.54
D10 - Conveying	0.00 %	110.00 %	\$192,854.00
D20 - Plumbing	14.65 %	44.07 %	\$1,737,656.00
D30 - HVAC	18.63 %	61.75 %	\$5,949,353.00
D40 - Fire Protection	1.53 %	97.39 %	\$1,085,129.00
D50 - Electrical	51.01 %	0.43 %	\$33,049.94
E10 - Equipment	51.93 %	23.82 %	\$1,054,794.00
E20 - Furnishings	4.43 %	92.54 %	\$1,216,116.00
G20 - Site Improvements	23.13 %	12.42 %	\$911,533.06
G30 - Site Mechanical Utilities	8.21 %	0.00 %	\$0.00
G40 - Site Electrical Utilities	13.07 %	0.00 %	\$0.00
Totals:	34.80 %	20.19 %	\$13,538,819.91

Condition Deficiency Priority

Facility Name	Gross Area (S.F.)	FCI %	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance
1967 Football Pressbox	320	2.25	\$0.00	\$0.00	\$1,260.00	\$0.00	\$0.00
1967 Gym Building	43,100	35.19	\$0.00	\$0.00	\$3,028,551.00	\$0.00	\$0.00
1967 Restroom Building	450	8.14	\$0.00	\$0.00	\$4,717.00	\$0.00	\$0.00
1967 Storage Building	460	11.71	\$0.00	\$0.00	\$10,808.00	\$0.00	\$0.00
1967, 1977 Main Building	178,900	25.90	\$26,400.00	\$0.00	\$9,018,066.68	\$0.00	\$0.00
1977 Baseball Pressbox	430	15.43	\$0.00	\$0.00	\$10,631.84	\$0.00	\$0.00
1977 Technology Building	14,000	2.74	\$0.00	\$0.00	\$64,372.00	\$0.00	\$0.00
1979 Fieldhouse	6,000	2.55	\$0.00	\$0.00	\$37,843.00	\$0.00	\$0.00
1991 Addition	28,500	7.16	\$0.00	\$0.00	\$380,219.00	\$0.00	\$0.00
1999 Visitor Concession Stand	1,200	18.21	\$0.00	\$0.00	\$32,155.00	\$0.00	\$0.00
2005 Weight Room	5,700	0.77	\$0.00	\$0.00	\$10,546.80	\$0.00	\$0.00
2008 Storage Building	1,620	0.85	\$1,716.53	\$0.00	\$0.00	\$0.00	\$0.00
2009 Soccer Storage Building	435	0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2009 Softball Pressbox	490	0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2012 Concession Building	1,400	0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2015 Baseball Pressbox	235	0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2015 Laundromat Building	2,000	0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
Site	285,240	7.94	\$12,696.06	\$0.00	\$898,837.00	\$0.00	\$0.00
Total:		20.19	\$40,812.59	\$0.00	\$13,498,007.32	\$0.00	\$0.00

Deficiencies By Priority



Budget Estimate Total: \$13,538,819.91

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	320
Year Built:	1967
Last Renovation:	
Replacement Value:	\$56,112
Repair Cost:	\$1,260.00
Total FCI:	2.25 %
Total RSLI:	34.90 %
FCA Score:	97.75







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	320
Year Built:	1967	Last Renovation:	
Repair Cost:	\$1,260	Replacement Value:	\$56,112
FCI:	2.25 %	RSLI%:	34.90 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	50.00 %	0.00 %	\$0.00
B10 - Superstructure	50.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	32.97 %	0.00 %	\$0.00
B30 - Roofing	16.00 %	0.00 %	\$0.00
C30 - Interior Finishes	22.37 %	0.00 %	\$0.00
D50 - Electrical	9.69 %	24.74 %	\$1,260.00
Totals:	34.90 %	2.25 %	\$1,260.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). North Elevation - Jan 10, 2017



2). East Elevation - Jan 10, 2017



3). West Elevation - Jan 10, 2017



4). Northeast Elevation - Jan 10, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$20.13	S.F.	320	100	1967	2067		50.00 %	0.00 %	50			\$6,442
A1030	Slab on Grade	\$19.75	S.F.	320	100	1967	2067		50.00 %	0.00 %	50			\$6,320
B1010	Floor Construction	\$11.44	S.F.	320	100	1967	2067		50.00 %	0.00 %	50			\$3,661
B1020	Roof Construction	\$16.26	S.F.	320	100	1967	2067		50.00 %	0.00 %	50			\$5,203
B2010	Exterior Walls	\$29.79	S.F.	320	100	1967	2067		50.00 %	0.00 %	50			\$9,533
B2020	Exterior Windows	\$17.17	S.F.	320	30	1967	1997	2021	13.33 %	0.00 %	4			\$5,494
B2030	Exterior Doors	\$8.66	S.F.	320	30	1967	1997	2021	13.33 %	0.00 %	4			\$2,771
B3010105	Built-Up	\$8.95	S.F.	320	25	1967	1992	2021	16.00 %	0.00 %	4			\$2,864
B3020	Roof Openings	\$0.29	S.F.	320	25	1967	1992	2021	16.00 %	0.00 %	4			\$93
C3010	Wall Finishes	\$5.11	S.F.	320	10	1967	1977	2021	40.00 %	0.00 %	4			\$1,635
C3020	Floor Finishes	\$12.37	S.F.	320	20	1967	1987	2021	20.00 %	0.00 %	4			\$3,958
C3030	Ceiling Finishes	\$9.52	S.F.	320	25	1967	1992	2021	16.00 %	0.00 %	4			\$3,046
D5010	Electrical Service/Distribution	\$3.09	S.F.	320	40	1967	2007	2021	10.00 %	0.00 %	4			\$989
D5020	Branch Wiring	\$9.24	S.F.	320	30	1967	1997	2021	13.33 %	0.00 %	4			\$2,957
D5020	Lighting	\$3.58	S.F.	320	30	1967	1997		0.00 %	109.95 %	-20		\$1,260.00	\$1,146
Total									34.90 %	2.25 %			\$1,260.00	\$56,112

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls



Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:

Campus Assessment Report - 1967 Football Pressbox

System: B3010105 - Built-Up




Note:

System: B3020 - Roof Openings



Note:

System: C3010 - Wall Finishes



Note:

Campus Assessment Report - 1967 Football Pressbox

System: C3020 - Floor Finishes



Note:

System: C3030 - Ceiling Finishes



Note:

System: D5010 - Electrical Service/Distribution



Note:

Campus Assessment Report - 1967 Football Pressbox

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Campus Assessment Report - 1967 Football Pressbox


Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$1,260	\$0	\$0	\$0	\$30,377	\$0	\$0	\$0	\$0	\$0	\$0	\$31,637
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$6,803	\$0	\$0	\$0	\$0	\$0	\$0	\$6,803
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$3,431	\$0	\$0	\$0	\$0	\$0	\$0	\$3,431
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010105 - Built-Up	\$0	\$0	\$0	\$0	\$4,448	\$0	\$0	\$0	\$0	\$0	\$0	\$4,448
B3020 - Roof Openings	\$0	\$0	\$0	\$0	\$115	\$0	\$0	\$0	\$0	\$0	\$0	\$115
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$2,025	\$0	\$0	\$0	\$0	\$0	\$0	\$2,025
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$4,900	\$0	\$0	\$0	\$0	\$0	\$0	\$4,900
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$3,772	\$0	\$0	\$0	\$0	\$0	\$0	\$3,772
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$1,225	\$0	\$0	\$0	\$0	\$0	\$0	\$1,225
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$3,660	\$0	\$0	\$0	\$0	\$0	\$0	\$3,660
D5020 - Lighting	\$1,260	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,260

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.




Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$1,260.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
D5020	Lighting	\$0.00	\$0.00	\$1,260.00	\$0.00	\$0.00	\$1,260.00
	Total:	\$0.00	\$0.00	\$1,260.00	\$0.00	\$0.00	\$1,260.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: D5020 - Lighting



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 320.00
Unit of Measure: S.F.
Estimate: \$1,260.00
Assessor Name: Eduardo Lopez
Date Created: 01/10/2017

Notes: The lighting system is beyond its service life and should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	43,100
Year Built:	1967
Last Renovation:	
Replacement Value:	\$8,607,011
Repair Cost:	\$3,028,551.00
Total FCI:	35.19 %
Total RSLI:	32.15 %
FCA Score:	64.81







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	43,100
Year Built:	1967	Last Renovation:	
Repair Cost:	\$3,028,551	Replacement Value:	\$8,607,011
FCI:	35.19 %	RSLI%:	32.15 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	50.00 %	0.00 %	\$0.00
A20 - Basement Construction	50.00 %	0.00 %	\$0.00
B10 - Superstructure	50.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	20.19 %	62.68 %	\$605,900.00
B30 - Roofing	42.93 %	0.00 %	\$0.00
C10 - Interior Construction	25.38 %	0.00 %	\$0.00
C30 - Interior Finishes	55.48 %	0.00 %	\$0.00
D20 - Plumbing	13.33 %	0.00 %	\$0.00
D30 - HVAC	9.56 %	87.33 %	\$1,988,375.00
D40 - Fire Protection	0.00 %	110.00 %	\$198,174.00
D50 - Electrical	51.08 %	0.00 %	\$0.00
E10 - Equipment	72.62 %	0.00 %	\$0.00
E20 - Furnishings	0.00 %	110.00 %	\$236,102.00
Totals:	32.15 %	35.19 %	\$3,028,551.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). North Elevation - Feb 14, 2017



2). West Elevation - Feb 14, 2017



3). Southwest Elevation - Feb 14, 2017



4). Northeast Elevation - Feb 14, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.


Campus Assessment Report - 1967 Gym Building

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$2.18	S.F.	43,100	100	1967	2067		50.00 %	0.00 %	50			\$93,958
A1030	Slab on Grade	\$4.08	S.F.	43,100	100	1967	2067		50.00 %	0.00 %	50			\$175,848
A2010	Basement Excavation	\$0.83	S.F.	43,100	100	1967	2067		50.00 %	0.00 %	50			\$35,773
A2020	Basement Walls	\$5.74	S.F.	43,100	100	1967	2067		50.00 %	0.00 %	50			\$247,394
B1020	Roof Construction	\$7.60	S.F.	43,100	100	1967	2067		50.00 %	0.00 %	50			\$327,560
B2010	Exterior Walls	\$8.84	S.F.	43,100	100	1967	2067		50.00 %	0.00 %	50			\$381,004
B2020	Exterior Windows	\$12.78	S.F.	43,100	30	1967	1997		0.00 %	110.00 %	-20		\$605,900.00	\$550,818
B2030	Exterior Doors	\$0.81	S.F.	43,100	30	1967	1997	2021	13.33 %	0.00 %	4			\$34,911
B3010120	Single Ply Membrane	\$6.98	S.F.	28,005	20	2010	2030		65.00 %	0.00 %	13			\$195,475
B3010130	Preformed Metal Roofing	\$9.66	S.F.	15,095	30	1967	1997	2021	13.33 %	0.00 %	4			\$145,818
C1010	Partitions	\$4.70	S.F.	43,100	75	1967	2042		33.33 %	0.00 %	25			\$202,570
C1020	Interior Doors	\$2.44	S.F.	43,100	30	1967	1997	2021	13.33 %	0.00 %	4			\$105,164
C1030	Fittings	\$1.48	S.F.	43,100	20	1967	1987	2021	20.00 %	0.00 %	4			\$63,788
C3010	Wall Finishes	\$2.56	S.F.	43,100	10	1967	1977	2021	40.00 %	0.00 %	4			\$110,336
C3020	Floor Finishes	\$10.94	S.F.	43,100	20	1967	1987	2021	20.00 %	0.00 %	4			\$471,514
C3030	Ceiling Finishes	\$10.56	S.F.	43,100	25	2016	2041		96.00 %	0.00 %	24			\$455,136
D2010	Plumbing Fixtures	\$8.83	S.F.	43,100	30	1967	1997	2021	13.33 %	0.00 %	4			\$380,573
D2020	Domestic Water Distribution	\$1.64	S.F.	43,100	30	1967	1997	2021	13.33 %	0.00 %	4			\$70,684
D2030	Sanitary Waste	\$2.59	S.F.	43,100	30	1967	1997	2021	13.33 %	0.00 %	4			\$111,629
D2040	Rain Water Drainage	\$0.63	S.F.	43,100	30	1967	1997	2021	13.33 %	0.00 %	4			\$27,153
D3020	Heat Generating Systems	\$6.93	S.F.	43,100	30	1967	1997		0.00 %	110.00 %	-20		\$328,551.00	\$298,683
D3030	Cooling Generating Systems	\$7.18	S.F.	43,100	25	2007	2032		60.00 %	0.00 %	15			\$309,458
D3040	Distribution Systems	\$8.37	S.F.	43,100	30	1967	1997		0.00 %	110.00 %	-20		\$396,822.00	\$360,747
D3050	Terminal & Package Units	\$26.64	S.F.	43,100	15	1967	1982		0.00 %	110.00 %	-35		\$1,263,002.00	\$1,148,184
D3060	Controls & Instrumentation	\$2.65	S.F.	43,100	20	1967	1987	2021	20.00 %	0.00 %	4			\$114,215
D3090	Other HVAC Systems/Equip	\$1.06	S.F.	43,100	20	1967	1987	2021	20.00 %	0.00 %	4			\$45,686
D4010	Sprinklers	\$3.63	S.F.	43,100	30	1967	1997		0.00 %	110.00 %	-20		\$172,098.00	\$156,453
D4020	Standpipes	\$0.55	S.F.	43,100	30	1967	1997		0.00 %	110.00 %	-20		\$26,076.00	\$23,705
D5010	Electrical Service/Distribution	\$1.60	S.F.	43,100	40	1967	2007	2021	10.00 %	0.00 %	4			\$68,960
D5020	Branch Wiring	\$4.55	S.F.	43,100	30	1967	1997	2021	13.33 %	0.00 %	4			\$196,105
D5020	Lighting	\$10.64	S.F.	43,100	30	2016	2046		96.67 %	0.00 %	29			\$458,584
D5030810	Security & Detection Systems	\$1.97	S.F.	43,100	15	1967	1982	2021	26.67 %	0.00 %	4			\$84,907
D5030910	Fire Alarm Systems	\$3.56	S.F.	43,100	15	1967	1982	2021	26.67 %	0.00 %	4			\$153,436
D5030920	Data Communication	\$4.61	S.F.	43,100	15	1967	1982	2021	26.67 %	0.00 %	4			\$198,691
E1010	Commercial Equipment	\$0.59	S.F.	43,100	20	1967	1987	2021	20.00 %	0.00 %	4			\$25,429
E1020	Institutional Equipment	\$13.04	S.F.	43,100	20	2012	2032		75.00 %	0.00 %	15			\$562,024
E2010	Fixed Furnishings	\$4.98	S.F.	43,100	20	1967	1987		0.00 %	110.00 %	-30		\$236,102.00	\$214,638
Total									32.15 %	35.19 %			\$3,028,551.00	\$8,607,011

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B1020 - Roof Construction



Note:

System: B2010 - Exterior Walls



Note:


System: B2020 - Exterior Windows



Note: The exterior windows are beyond their service life and should be replaced.

Campus Assessment Report - 1967 Gym Building

System: B2030 - Exterior Doors



Note:

System: B3010120 - Single Ply Membrane



Note:


System: B3010130 - Preformed Metal Roofing



Note:

Campus Assessment Report - 1967 Gym Building

System: C1010 - Partitions




Note:

System: C1020 - Interior Doors



Note:


System: C1030 - Fittings



Note:


Campus Assessment Report - 1967 Gym Building

System: C3010 - Wall Finishes




Note:

System: C3020 - Floor Finishes



Note:


System: C3030 - Ceiling Finishes



Note:

Campus Assessment Report - 1967 Gym Building

System: D2010 - Plumbing Fixtures



Note:

System: D2020 - Domestic Water Distribution



Note:

System: D2030 - Sanitary Waste



Note:

Campus Assessment Report - 1967 Gym Building

System: D2040 - Rain Water Drainage



Note:

System: D3020 - Heat Generating Systems



Note: The heat generating systems are beyond their service life and should be replaced.


System: D3030 - Cooling Generating Systems



Note:

Campus Assessment Report - 1967 Gym Building

System: D3040 - Distribution Systems



Note: The distribution system is beyond its service life and should be replaced.

System: D3050 - Terminal & Package Units



Note: The terminal and package units are beyond their service life and should be replaced.

System: D3060 - Controls & Instrumentation



Note:

Campus Assessment Report - 1967 Gym Building

System: D3090 - Other HVAC Systems/Equip



Note:

System: D4010 - Sprinklers

This system contains no images


Note: The building does not have a fire protection system and it should be installed.

System: D4020 - Standpipes

This system contains no images


Note: The building does not have a fire protection system and it should be installed.

System: D5010 - Electrical Service/Distribution



Note:

System: D5020 - Branch Wiring



Note:

Campus Assessment Report - 1967 Gym Building

System: D5020 - Lighting




Note:

System: D5030810 - Security & Detection Systems



Note:


System: D5030910 - Fire Alarm Systems



Note:

Campus Assessment Report - 1967 Gym Building

System: D5030920 - Data Communication





Note:

System: E1010 - Commercial Equipment



Note:

System: E1020 - Institutional Equipment



Note:

Campus Assessment Report - 1967 Gym Building

System: E2010 - Fixed Furnishings



Note: The fixed furnishings are beyond their service life and should be replaced.

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$3,028,551	\$0	\$0	\$0	\$3,028,438	\$0	\$0	\$0	\$0	\$0	\$0	\$6,056,989
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$605,900	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$605,900
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$43,222	\$0	\$0	\$0	\$0	\$0	\$0	\$43,222
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010120 - Single Ply Membrane	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010130 - Preformed Metal Roofing	\$0	\$0	\$0	\$0	\$226,484	\$0	\$0	\$0	\$0	\$0	\$0	\$226,484
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$130,199	\$0	\$0	\$0	\$0	\$0	\$0	\$130,199
C1030 - Fittings	\$0	\$0	\$0	\$0	\$78,974	\$0	\$0	\$0	\$0	\$0	\$0	\$78,974
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$136,603	\$0	\$0	\$0	\$0	\$0	\$0	\$136,603


Campus Assessment Report - 1967 Gym Building

C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$583,762	\$0	\$0	\$0	\$0	\$0	\$0	\$583,762
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$471,172	\$0	\$0	\$0	\$0	\$0	\$0	\$471,172
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$87,511	\$0	\$0	\$0	\$0	\$0	\$0	\$87,511
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$138,203	\$0	\$0	\$0	\$0	\$0	\$0	\$138,203
D2040 - Rain Water Drainage	\$0	\$0	\$0	\$0	\$33,617	\$0	\$0	\$0	\$0	\$0	\$0	\$33,617
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$328,551	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$328,551
D3030 - Cooling Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$396,822	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$396,822
D3050 - Terminal & Package Units	\$1,263,002	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,263,002
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$141,406	\$0	\$0	\$0	\$0	\$0	\$0	\$141,406
D3090 - Other HVAC Systems/Equip	\$0	\$0	\$0	\$0	\$56,562	\$0	\$0	\$0	\$0	\$0	\$0	\$56,562
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$172,098	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$172,098
D4020 - Standpipes	\$26,076	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$26,076
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$85,377	\$0	\$0	\$0	\$0	\$0	\$0	\$85,377
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$242,790	\$0	\$0	\$0	\$0	\$0	\$0	\$242,790
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$105,120	\$0	\$0	\$0	\$0	\$0	\$0	\$105,120
D5030910 - Fire Alarm Systems	\$0	\$0	\$0	\$0	\$189,963	\$0	\$0	\$0	\$0	\$0	\$0	\$189,963
D5030920 - Data Communication	\$0	\$0	\$0	\$0	\$245,991	\$0	\$0	\$0	\$0	\$0	\$0	\$245,991
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1010 - Commercial Equipment	\$0	\$0	\$0	\$0	\$31,483	\$0	\$0	\$0	\$0	\$0	\$0	\$31,483
E1020 - Institutional Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$236,102	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$236,102

** Indicates non-renewable system*


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$3,028,551.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$3,028,551.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
B2020	Exterior Windows	\$0.00	\$0.00	\$605,900.00	\$0.00	\$0.00	\$605,900.00
D3020	Heat Generating Systems	\$0.00	\$0.00	\$328,551.00	\$0.00	\$0.00	\$328,551.00
D3040	Distribution Systems	\$0.00	\$0.00	\$396,822.00	\$0.00	\$0.00	\$396,822.00
D3050	Terminal & Package Units	\$0.00	\$0.00	\$1,263,002.00	\$0.00	\$0.00	\$1,263,002.00
D4010	Sprinklers	\$0.00	\$0.00	\$172,098.00	\$0.00	\$0.00	\$172,098.00
D4020	Standpipes	\$0.00	\$0.00	\$26,076.00	\$0.00	\$0.00	\$26,076.00
E2010	Fixed Furnishings	\$0.00	\$0.00	\$236,102.00	\$0.00	\$0.00	\$236,102.00
	Total:	\$0.00	\$0.00	\$3,028,551.00	\$0.00	\$0.00	\$3,028,551.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: B2020 - Exterior Windows



Location: Exterior Walls
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 43,100.00
Unit of Measure: S.F.
Estimate: \$605,900.00
Assessor Name: Eduardo Lopez
Date Created: 02/13/2017

Notes: The exterior windows are beyond their service life and should be replaced.

System: D3020 - Heat Generating Systems



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 43,100.00
Unit of Measure: S.F.
Estimate: \$328,551.00
Assessor Name: Eduardo Lopez
Date Created: 02/13/2017

Notes: The heat generating systems are beyond their service life and should be replaced.

System: D3040 - Distribution Systems



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 43,100.00
Unit of Measure: S.F.
Estimate: \$396,822.00
Assessor Name: Eduardo Lopez
Date Created: 02/13/2017

Notes: The distribution system is beyond its service life and should be replaced.

System: D3050 - Terminal & Package Units



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 43,100.00
Unit of Measure: S.F.
Estimate: \$1,263,002.00
Assessor Name: Eduardo Lopez
Date Created: 02/13/2017

Notes: The terminal and package units are beyond their service life and should be replaced.

System: D4010 - Sprinklers

This deficiency has no image.

Location: Throughout Building
Distress: Missing
Category: Building Code Compliance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 43,100.00
Unit of Measure: S.F.
Estimate: \$172,098.00
Assessor Name: Eduardo Lopez
Date Created: 02/13/2017

Notes: The building does not have a fire protection system and it should be installed.


System: D4020 - Standpipes

This deficiency has no image.

Location: Throughout Building
Distress: Missing
Category: Building Code Compliance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 43,100.00
Unit of Measure: S.F.
Estimate: \$26,076.00
Assessor Name: Eduardo Lopez
Date Created: 02/13/2017

Notes: The building does not have a fire protection system and it should be installed.

System: E2010 - Fixed Furnishings



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 43,100.00
Unit of Measure: S.F.
Estimate: \$236,102.00
Assessor Name: Eduardo Lopez
Date Created: 02/13/2017

Notes: The fixed furnishings are beyond their service life and should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	450
Year Built:	1967
Last Renovation:	
Replacement Value:	\$57,919
Repair Cost:	\$4,717.00
Total FCI:	8.14 %
Total RSLI:	28.76 %
FCA Score:	91.86







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	450
Year Built:	1967	Last Renovation:	
Repair Cost:	\$4,717	Replacement Value:	\$57,919
FCI:	8.14 %	RSLI%:	28.76 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	50.00 %	0.00 %	\$0.00
B10 - Superstructure	50.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	48.24 %	0.00 %	\$0.00
B30 - Roofing	20.00 %	0.00 %	\$0.00
C10 - Interior Construction	27.33 %	0.00 %	\$0.00
C30 - Interior Finishes	18.61 %	35.26 %	\$4,717.00
D20 - Plumbing	13.33 %	0.00 %	\$0.00
D30 - HVAC	26.67 %	0.00 %	\$0.00
D50 - Electrical	12.22 %	0.00 %	\$0.00
Totals:	28.76 %	8.14 %	\$4,717.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). East Elevation - Jan 10, 2017



2). South Elevation - Jan 10, 2017



3). West Elevation - Jan 10, 2017



4). North Elevation - Jan 10, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

Campus Assessment Report - 1967 Restroom Building

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$6.93	S.F.	450	100	1967	2067		50.00 %	0.00 %	50			\$3,119
A1030	Slab on Grade	\$7.37	S.F.	450	100	1967	2067		50.00 %	0.00 %	50			\$3,317
B1020	Roof Construction	\$5.98	S.F.	450	100	1967	2067		50.00 %	0.00 %	50			\$2,691
B2010	Exterior Walls	\$18.04	S.F.	450	100	1967	2067		50.00 %	0.00 %	50			\$8,118
B2030	Exterior Doors	\$0.91	S.F.	450	30	1967	1997	2021	13.33 %	0.00 %	4			\$410
B3010140	Asphalt Shingles	\$4.32	S.F.	450	20	1967	1987	2021	20.00 %	0.00 %	4			\$1,944
C1010	Partitions	\$10.34	S.F.	450	75	1967	2042		33.33 %	0.00 %	25			\$4,653
C1030	Fittings	\$8.47	S.F.	450	20	1967	1987	2021	20.00 %	0.00 %	4			\$3,812
C3010	Wall Finishes	\$7.46	S.F.	450	10	1967	1977	2021	40.00 %	0.00 %	4			\$3,357
C3020	Floor Finishes	\$12.74	S.F.	450	20	1967	1987	2021	20.00 %	0.00 %	4			\$5,733
C3030	Ceiling Finishes	\$9.53	S.F.	450	25	1967	1992		0.00 %	109.98 %	-25		\$4,717.00	\$4,289
D2010	Plumbing Fixtures	\$9.98	S.F.	450	30	1967	1997	2021	13.33 %	0.00 %	4			\$4,491
D2020	Domestic Water Distribution	\$0.84	S.F.	450	30	1967	1997	2021	13.33 %	0.00 %	4			\$378
D2030	Sanitary Waste	\$5.94	S.F.	450	30	1967	1997	2021	13.33 %	0.00 %	4			\$2,673
D3050	Terminal & Package Units	\$10.63	S.F.	450	15	1967	1982	2021	26.67 %	0.00 %	4			\$4,784
D5010	Electrical Service/Distribution	\$3.09	S.F.	450	40	1967	2007	2021	10.00 %	0.00 %	4			\$1,391
D5020	Branch Wiring	\$2.55	S.F.	450	30	1967	1997	2021	13.33 %	0.00 %	4			\$1,148
D5020	Lighting	\$3.58	S.F.	450	30	1967	1997	2021	13.33 %	0.00 %	4			\$1,611
Total									28.76 %	8.14 %			\$4,717.00	\$57,919

System Notes


The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls



Note:

System: B2030 - Exterior Doors



Note:




System: B3010140 - Asphalt Shingles



Note:



Campus Assessment Report - 1967 Restroom Building

System: C1010 - Partitions






Note:

System: C1030 - Fittings



Note:




System: C3010 - Wall Finishes



Note:


Campus Assessment Report - 1967 Restroom Building

System: C3020 - Floor Finishes






Note:

System: C3030 - Ceiling Finishes



Note: The ceiling finishes are beyond their service life and should be replaced.




System: D2010 - Plumbing Fixtures



Note:



Campus Assessment Report - 1967 Restroom Building

System: D2020 - Domestic Water Distribution



Note:

System: D2030 - Sanitary Waste



Note:


System: D3050 - Terminal & Package Units



Note:


Campus Assessment Report - 1967 Restroom Building

System: D5010 - Electrical Service/Distribution





Note:

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$4,717	\$0	\$0	\$0	\$40,070	\$0	\$0	\$0	\$0	\$0	\$0	\$44,787
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$506	\$0	\$0	\$0	\$0	\$0	\$0	\$506
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010140 - Asphalt Shingles	\$0	\$0	\$0	\$0	\$3,194	\$0	\$0	\$0	\$0	\$0	\$0	\$3,194
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$0	\$0	\$0	\$0	\$4,719	\$0	\$0	\$0	\$0	\$0	\$0	\$4,719
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$4,157	\$0	\$0	\$0	\$0	\$0	\$0	\$4,157
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$7,097	\$0	\$0	\$0	\$0	\$0	\$0	\$7,097
C3030 - Ceiling Finishes	\$4,717	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$4,717
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$5,560	\$0	\$0	\$0	\$0	\$0	\$0	\$5,560
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$468	\$0	\$0	\$0	\$0	\$0	\$0	\$468


Campus Assessment Report - 1967 Restroom Building

D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$3,309	\$0	\$0	\$0	\$0	\$0	\$0	\$3,309
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$5,922	\$0	\$0	\$0	\$0	\$0	\$0	\$5,922
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$1,722	\$0	\$0	\$0	\$0	\$0	\$0	\$1,722
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$1,420	\$0	\$0	\$0	\$0	\$0	\$0	\$1,420
D5020 - Lighting	\$0	\$0	\$0	\$0	\$1,994	\$0	\$0	\$0	\$0	\$0	\$0	\$1,994

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.




Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$4,717.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
C3030	Ceiling Finishes	\$0.00	\$0.00	\$4,717.00	\$0.00	\$0.00	\$4,717.00
	Total:	\$0.00	\$0.00	\$4,717.00	\$0.00	\$0.00	\$4,717.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:




Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: C3030 - Ceiling Finishes



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 450.00
Unit of Measure: S.F.
Estimate: \$4,717.00
Assessor Name: Eduardo Lopez
Date Created: 01/10/2017

Notes: The ceiling finishes are beyond their service life and should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	460
Year Built:	1967
Last Renovation:	
Replacement Value:	\$92,322
Repair Cost:	\$10,808.00
Total FCI:	11.71 %
Total RSLI:	29.90 %
FCA Score:	88.29







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	460
Year Built:	1967	Last Renovation:	
Repair Cost:	\$10,808	Replacement Value:	\$92,322
FCI:	11.71 %	RSLI%:	29.90 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	50.00 %	0.00 %	\$0.00
B10 - Superstructure	50.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	37.65 %	0.00 %	\$0.00
B30 - Roofing	20.00 %	0.00 %	\$0.00
C10 - Interior Construction	29.82 %	0.00 %	\$0.00
C30 - Interior Finishes	16.03 %	12.58 %	\$2,586.00
D20 - Plumbing	13.33 %	0.00 %	\$0.00
D50 - Electrical	0.00 %	109.99 %	\$8,222.00
E20 - Furnishings	20.00 %	0.00 %	\$0.00
Totals:	29.90 %	11.71 %	\$10,808.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). South Elevation - Jan 10, 2017



2). West Elevation - Jan 10, 2017



3). North Elevation - Jan 10, 2017



4). East Elevation - Jan 10, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

Campus Assessment Report - 1967 Storage Building

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$20.13	S.F.	460	100	1967	2067		50.00 %	0.00 %	50			\$9,260
A1030	Slab on Grade	\$19.75	S.F.	460	100	1967	2067		50.00 %	0.00 %	50			\$9,085
B1020	Roof Construction	\$16.26	S.F.	460	100	1967	2067		50.00 %	0.00 %	50			\$7,480
B2010	Exterior Walls	\$29.79	S.F.	460	100	1967	2067		50.00 %	0.00 %	50			\$13,703
B2020	Exterior Windows	\$6.47	S.F.	460	30	1967	1997	2021	13.33 %	0.00 %	4			\$2,976
B2030	Exterior Doors	\$8.66	S.F.	460	30	1967	1997	2021	13.33 %	0.00 %	4			\$3,984
B3010140	Asphalt Shingles	\$4.32	S.F.	460	20	1967	1987	2021	20.00 %	0.00 %	4			\$1,987
C1010	Partitions	\$10.34	S.F.	460	75	1967	2042		33.33 %	0.00 %	25			\$4,756
C1020	Interior Doors	\$2.20	S.F.	460	30	1967	1997	2021	13.33 %	0.00 %	4			\$1,012
C3010	Wall Finishes	\$5.11	S.F.	460	10	1967	1977		0.00 %	110.00 %	-40		\$2,586.00	\$2,351
C3020	Floor Finishes	\$20.82	S.F.	460	20	1967	1987	2021	20.00 %	0.00 %	4			\$9,577
C3030	Ceiling Finishes	\$18.76	S.F.	460	25	1967	1992	2021	16.00 %	0.00 %	4			\$8,630
D2010	Plumbing Fixtures	\$9.98	S.F.	460	30	1967	1997	2021	13.33 %	0.00 %	4			\$4,591
D2020	Domestic Water Distribution	\$0.84	S.F.	460	30	1967	1997	2021	13.33 %	0.00 %	4			\$386
D2030	Sanitary Waste	\$5.94	S.F.	460	30	1967	1997	2021	13.33 %	0.00 %	4			\$2,732
D5010	Electrical Service/Distribution	\$3.09	S.F.	460	40	1967	2007		0.00 %	110.06 %	-10		\$1,564.00	\$1,421
D5020	Branch Wiring	\$3.58	S.F.	460	30	1967	1997		0.00 %	109.96 %	-20		\$1,811.00	\$1,647
D5020	Lighting	\$9.58	S.F.	460	30	1967	1997		0.00 %	109.98 %	-20		\$4,847.00	\$4,407
E2010	Fixed Furnishings	\$5.08	S.F.	460	20	1967	1987	2021	20.00 %	0.00 %	4			\$2,337
Total									29.90 %	11.71 %			\$10,808.00	\$92,322

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls




Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:

Campus Assessment Report - 1967 Storage Building

System: B3010140 - Asphalt Shingles



Note:

System: C1010 - Partitions



Note:




System: C1020 - Interior Doors



Note:

Campus Assessment Report - 1967 Storage Building

System: C3010 - Wall Finishes



Note: The wall finishes are beyond their service life and should be replaced.

System: C3020 - Floor Finishes



Note:

System: C3030 - Ceiling Finishes



Note:

Campus Assessment Report - 1967 Storage Building

System: D2010 - Plumbing Fixtures



Note:

System: D2020 - Domestic Water Distribution



Note:


System: D2030 - Sanitary Waste



Note:


Campus Assessment Report - 1967 Storage Building

System: D5010 - Electrical Service/Distribution



Note: The electrical service distribution is beyond its service life and should be replaced.

System: D5020 - Branch Wiring



Note: The branch wiring is beyond its service life and should be replaced.


System: D5020 - Lighting



Note: The lighting system is beyond its service life and should be replaced.

Campus Assessment Report - 1967 Storage Building

System: E20 - Furnishings



Note:

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$10,808	\$0	\$0	\$0	\$48,114	\$0	\$0	\$0	\$0	\$0	\$3,475	\$62,398
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$3,685	\$0	\$0	\$0	\$0	\$0	\$0	\$3,685
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$4,932	\$0	\$0	\$0	\$0	\$0	\$0	\$4,932
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010140 - Asphalt Shingles	\$0	\$0	\$0	\$0	\$3,265	\$0	\$0	\$0	\$0	\$0	\$0	\$3,265
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$1,253	\$0	\$0	\$0	\$0	\$0	\$0	\$1,253
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$2,586	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$3,475	\$6,061
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$11,857	\$0	\$0	\$0	\$0	\$0	\$0	\$11,857
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$10,684	\$0	\$0	\$0	\$0	\$0	\$0	\$10,684
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$5,684	\$0	\$0	\$0	\$0	\$0	\$0	\$5,684


Campus Assessment Report - 1967 Storage Building

D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$478	\$0	\$0	\$0	\$0	\$0	\$0	\$478
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$3,383	\$0	\$0	\$0	\$0	\$0	\$0	\$3,383
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$1,564	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,564
D5020 - Branch Wiring	\$1,811	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,811
D5020 - Lighting	\$4,847	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$4,847
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$0	\$2,893	\$0	\$0	\$0	\$0	\$0	\$0	\$2,893

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$10,808.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$10,808.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
C3010	Wall Finishes	\$0.00	\$0.00	\$2,586.00	\$0.00	\$0.00	\$2,586.00
D5010	Electrical Service/Distribution	\$0.00	\$0.00	\$1,564.00	\$0.00	\$0.00	\$1,564.00
D5020	Branch Wiring	\$0.00	\$0.00	\$1,811.00	\$0.00	\$0.00	\$1,811.00
D5020	Lighting	\$0.00	\$0.00	\$4,847.00	\$0.00	\$0.00	\$4,847.00
	Total:	\$0.00	\$0.00	\$10,808.00	\$0.00	\$0.00	\$10,808.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: C3010 - Wall Finishes



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 460.00
Unit of Measure: S.F.
Estimate: \$2,586.00
Assessor Name: Terence Davis
Date Created: 01/10/2017

Notes: The wall finishes are beyond its service life and should be replaced.

System: D5010 - Electrical Service/Distribution



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 460.00
Unit of Measure: S.F.
Estimate: \$1,564.00
Assessor Name: Terence Davis
Date Created: 01/10/2017

Notes: The electrical service distribution is beyond its service life and should be replaced.

System: D5020 - Branch Wiring



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 460.00
Unit of Measure: S.F.
Estimate: \$1,811.00
Assessor Name: Terence Davis
Date Created: 01/10/2017

Notes: The branch wiring is beyond its service life and should be replaced.

System: D5020 - Lighting



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 460.00
Unit of Measure: S.F.
Estimate: \$4,847.00
Assessor Name: Terence Davis
Date Created: 01/10/2017

Notes: The lighting system is beyond its service life and should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	178,900
Year Built:	1967
Last Renovation:	
Replacement Value:	\$34,920,145
Repair Cost:	\$9,044,466.68
Total FCI:	25.90 %
Total RSLI:	36.78 %
FCA Score:	74.10







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	178,900
Year Built:	1967	Last Renovation:	
Repair Cost:	\$9,044,467	Replacement Value:	\$34,920,145
FCI:	25.90 %	RSLI%:	36.78 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	50.00 %	0.00 %	\$0.00
A20 - Basement Construction	50.00 %	0.00 %	\$0.00
B10 - Superstructure	50.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	27.78 %	0.33 %	\$13,200.00
B30 - Roofing	52.99 %	4.25 %	\$41,326.00
C10 - Interior Construction	25.38 %	1.57 %	\$24,189.00
C20 - Stairs	50.00 %	0.00 %	\$0.00
C30 - Interior Finishes	55.48 %	4.85 %	\$208,642.74
D10 - Conveying	0.00 %	110.00 %	\$192,854.00
D20 - Plumbing	11.11 %	70.18 %	\$1,737,656.00
D30 - HVAC	16.32 %	71.28 %	\$3,945,640.00
D40 - Fire Protection	0.00 %	110.00 %	\$822,583.00
D50 - Electrical	51.05 %	0.48 %	\$23,567.94
E10 - Equipment	52.12 %	31.05 %	\$1,054,794.00
E20 - Furnishings	0.00 %	110.00 %	\$980,014.00
Totals:	36.78 %	25.90 %	\$9,044,466.68

Photo Album

The photo album consists of the various cardinal directions of the building..

1). South Elevation - Jan 11, 2017



2). Southwest Elevation - Jan 11, 2017



3). East Elevation - Jan 11, 2017



4). North Elevation - Jan 11, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$2.18	S.F.	178,900	100	1967	2067		50.00 %	0.00 %	50			\$390,002
A1030	Slab on Grade	\$4.08	S.F.	178,900	100	1967	2067		50.00 %	0.00 %	50			\$729,912
A2010	Basement Excavation	\$0.83	S.F.	178,900	100	1967	2067		50.00 %	0.00 %	50			\$148,487
A2020	Basement Walls	\$5.74	S.F.	178,900	100	1967	2067		50.00 %	0.00 %	50			\$1,026,886
B1010	Floor Construction	\$11.42	S.F.	178,900	100	1967	2067		50.00 %	0.00 %	50			\$2,043,038
B1020	Roof Construction	\$7.60	S.F.	178,900	100	1967	2067		50.00 %	0.00 %	50			\$1,359,640
B2010	Exterior Walls	\$8.84	S.F.	178,900	100	1967	2067		50.00 %	0.83 %	50		\$13,200.00	\$1,581,476
B2020	Exterior Windows	\$12.78	S.F.	178,900	30	1967	1997	2021	13.33 %	0.00 %	4			\$2,286,342
B2030	Exterior Doors	\$0.81	S.F.	178,900	30	1967	1997	2021	13.33 %	0.00 %	4			\$144,909
B3010120	Single Ply Membrane	\$6.98	S.F.	108,270	20	2010	2030		65.00 %	0.00 %	13			\$755,725
B3010130	Preformed Metal Roofing	\$9.66	S.F.	18,508	30	1977	2007	2021	13.33 %	0.00 %	4			\$178,787
B3020	Roof Openings	\$0.21	S.F.	178,900	25	1967	1992		0.00 %	110.00 %	-25		\$41,326.00	\$37,569
C1010	Partitions	\$4.70	S.F.	178,900	75	1967	2042		33.33 %	1.57 %	25		\$13,200.00	\$840,830
C1020	Interior Doors	\$2.44	S.F.	178,900	30	1967	1997	2021	13.33 %	0.00 %	4			\$436,516
C1030	Fittings	\$1.48	S.F.	178,900	20	1967	1987	2021	20.00 %	4.15 %	4		\$10,989.00	\$264,772
C2010	Stair Construction	\$1.29	S.F.	178,900	100	1967	2067		50.00 %	0.00 %	50			\$230,781
C3010	Wall Finishes	\$2.56	S.F.	178,900	10	1967	1977	2021	40.00 %	0.00 %	4			\$457,984
C3020	Floor Finishes	\$10.94	S.F.	178,900	20	1967	1987	2021	20.00 %	8.09 %	4		\$158,238.80	\$1,957,166
C3030	Ceiling Finishes	\$10.56	S.F.	178,900	25	2016	2041		96.00 %	2.67 %	24		\$50,403.94	\$1,889,184
D1010	Elevators and Lifts	\$0.98	S.F.	178,900	30	1967	1997		0.00 %	110.00 %	-20		\$192,854.00	\$175,322
D2010	Plumbing Fixtures	\$8.83	S.F.	178,900	30	1967	1997		0.00 %	110.00 %	-20		\$1,737,656.00	\$1,579,687
D2020	Domestic Water Distribution	\$1.64	S.F.	178,900	30	2007	2037		66.67 %	0.00 %	20			\$293,396
D2030	Sanitary Waste	\$2.59	S.F.	178,900	30	1967	1997	2021	13.33 %	0.00 %	4			\$463,351
D2040	Rain Water Drainage	\$0.63	S.F.	178,900	30	1967	1997	2021	13.33 %	0.00 %	4			\$112,707
D2090	Other Plumbing Systems -Nat Gas	\$0.15	S.F.	178,900	40	1967	2007	2021	10.00 %	0.00 %	4			\$26,835
D3020	Heat Generating Systems	\$6.93	S.F.	178,900	30	1967	1997		0.00 %	110.00 %	-20		\$1,363,755.00	\$1,239,777
D3030	Cooling Generating Systems	\$7.18	S.F.	178,900	25	2007	2032		60.00 %	0.00 %	15			\$1,284,502
D3040	Distribution Systems	\$8.37	S.F.	178,900	30	1967	1997		0.00 %	110.00 %	-20		\$1,647,132.00	\$1,497,393
D3050	Terminal & Package Units	\$4.75	S.F.	178,900	15	1967	1982		0.00 %	110.00 %	-35		\$934,753.00	\$849,775
D3060	Controls & Instrumentation	\$2.65	S.F.	178,900	20	1967	1987	2021	20.00 %	0.00 %	4			\$474,085
D3090	Other HVAC Systems/Equip	\$1.06	S.F.	178,900	20	1967	1987	2021	20.00 %	0.00 %	4			\$189,634
D4010	Sprinklers	\$3.63	S.F.	178,900	30	1967	1997		0.00 %	110.00 %	-20		\$714,348.00	\$649,407
D4020	Standpipes	\$0.55	S.F.	178,900	30	1967	1997		0.00 %	110.00 %	-20		\$108,235.00	\$98,395
D5010	Electrical Service/Distribution	\$1.60	S.F.	178,900	40	1967	2007	2021	10.00 %	0.00 %	4			\$286,240


Campus Assessment Report - 1967, 1977 Main Building

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
D5020	Branch Wiring	\$4.55	S.F.	178,900	30	1967	1997	2021	13.33 %	0.00 %	4			\$813,995
D5020	Lighting	\$10.64	S.F.	178,900	30	2016	2046		96.67 %	1.24 %	29		\$23,567.94	\$1,903,496
D5030810	Security & Detection Systems	\$1.97	S.F.	178,900	15	1967	1982	2021	26.67 %	0.00 %	4			\$352,433
D5030910	Fire Alarm Systems	\$3.56	S.F.	178,900	15	1967	1982	2021	26.67 %	0.00 %	4			\$636,884
D5030920	Data Communication	\$4.61	S.F.	178,900	15	1967	1982	2021	26.67 %	0.00 %	4			\$824,729
D5090	Other Electrical Systems	\$0.67	S.F.	178,900	20	2007	2027		50.00 %	0.00 %	10			\$119,863
E1010	Commercial Equipment	\$0.59	S.F.	178,900	20	1967	1987	2021	20.00 %	0.00 %	4			\$105,551
E1020	Institutional Equipment	\$13.04	S.F.	178,900	20	2012	2032		75.00 %	0.00 %	15			\$2,332,856
E1090	Other Equipment	\$5.36	S.F.	178,900	20	1967	1987		0.00 %	110.00 %	-30		\$1,054,794.00	\$958,904
E2010	Fixed Furnishings	\$4.98	S.F.	178,900	20	1967	1987		0.00 %	110.00 %	-30		\$980,014.00	\$890,922
Total									36.78 %	25.90 %			\$9,044,466.68	\$34,920,145

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B1010 - Floor Construction



Note:

System: B1020 - Roof Construction



Note:

System: B2010 - Exterior Walls



Note:

Campus Assessment Report - 1967, 1977 Main Building

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:


System: B3010120 - Single Ply Membrane



Note:

Campus Assessment Report - 1967, 1977 Main Building

System: B3010130 - Preformed Metal Roofing




Note:

System: B3020 - Roof Openings



Note: The roof openings are beyond their service life and should be replaced.



System: C1010 - Partitions



Note:



Campus Assessment Report - 1967, 1977 Main Building

System: C1020 - Interior Doors



Note:


System: C1030 - Fittings



Note:







Campus Assessment Report - 1967, 1977 Main Building

System: C2010 - Stair Construction



Note:



System: C3010 - Wall Finishes



Note:




Campus Assessment Report - 1967, 1977 Main Building

System: C3020 - Floor Finishes



Note:


System: C3030 - Ceiling Finishes



Note:


Campus Assessment Report - 1967, 1977 Main Building

System: D1010 - Elevators and Lifts



Note:

System: D2010 - Plumbing Fixtures



Note: The plumbing fixtures are beyond their service life and should be replaced.

System: D2020 - Domestic Water Distribution



Note:

Campus Assessment Report - 1967, 1977 Main Building

System: D2030 - Sanitary Waste




Note:

System: D2040 - Rain Water Drainage



Note:

System: D2090 - Other Plumbing Systems -Nat Gas



Note:

Campus Assessment Report - 1967, 1977 Main Building

System: D3020 - Heat Generating Systems



Note: The heat generating systems are beyond their service life and should be replaced.

System: D3030 - Cooling Generating Systems



Note:


System: D3040 - Distribution Systems



Note: The distribution system is beyond its service life and should be replaced.

Campus Assessment Report - 1967, 1977 Main Building

System: D3050 - Terminal & Package Units



Note: The terminal and package units are beyond their service life and should be replaced.

System: D3060 - Controls & Instrumentation



Note:

System: D3090 - Other HVAC Systems/Equip



Note:

System: D4010 - Sprinklers

This system contains no images

Note: The building does not have a fire protection system and it should be installed.

System: D4020 - Standpipes

This system contains no images

Note: The building does not have a fire protection system and it should be installed.

Campus Assessment Report - 1967, 1977 Main Building

System: D5010 - Electrical Service/Distribution



Note:

System: D5020 - Branch Wiring



Note:


System: D5020 - Lighting



Note:

Campus Assessment Report - 1967, 1977 Main Building

System: D5030810 - Security & Detection Systems




Note:

System: D5030910 - Fire Alarm Systems



Note:

System: D5030920 - Data Communication



Note:

Campus Assessment Report - 1967, 1977 Main Building

System: D5090 - Other Electrical Systems






Note:

System: E1010 - Commercial Equipment



Note: The commercial equipment is beyond its service life and should be replaced.

System: E1020 - Institutional Equipment



Note:

Campus Assessment Report - 1967, 1977 Main Building

System: E1090 - Other Equipment



Note: The kitchen equipment is beyond its service life and should be replaced.

System: E2010 - Fixed Furnishings



Note: The fixed furnishings are beyond their service life and should be replaced.

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$9,044,467	\$0	\$0	\$0	\$12,452,937	\$0	\$0	\$0	\$0	\$0	\$177,194	\$21,674,597
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$13,200	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$13,200
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$2,830,628	\$0	\$0	\$0	\$0	\$0	\$0	\$2,830,628
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$179,406	\$0	\$0	\$0	\$0	\$0	\$0	\$179,406
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010120 - Single Ply Membrane	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010130 - Preformed Metal Roofing	\$0	\$0	\$0	\$0	\$277,692	\$0	\$0	\$0	\$0	\$0	\$0	\$277,692
B3020 - Roof Openings	\$41,326	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$41,326
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$13,200	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$13,200
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$540,433	\$0	\$0	\$0	\$0	\$0	\$0	\$540,433
C1030 - Fittings	\$10,989	\$0	\$0	\$0	\$327,803	\$0	\$0	\$0	\$0	\$0	\$0	\$338,792

Campus Assessment Report - 1967, 1977 Main Building

C20 - Stairs	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C2010 - Stair Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$567,011	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$567,011
C3020 - Floor Finishes	\$158,239	\$0	\$0	\$0	\$2,423,089	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,581,328
C3030 - Ceiling Finishes	\$50,404	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$50,404
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D10 - Conveying	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D1010 - Elevators and Lifts	\$192,854	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$192,854
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$1,737,656	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,737,656
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$573,656	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$573,656
D2040 - Rain Water Drainage	\$0	\$0	\$0	\$0	\$139,538	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$139,538
D2090 - Other Plumbing Systems -Nat Gas	\$0	\$0	\$0	\$0	\$33,224	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$33,224
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$1,363,755	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,363,755
D3030 - Cooling Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$1,647,132	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,647,132
D3050 - Terminal & Package Units	\$934,753	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$934,753
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$586,946	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$586,946
D3090 - Other HVAC Systems/Equip	\$0	\$0	\$0	\$0	\$234,778	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$234,778
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$714,348	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$714,348
D4020 - Standpipes	\$108,235	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$108,235
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$354,382	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$354,382
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$1,007,775	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,007,775
D5020 - Lighting	\$23,568	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$23,568
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$436,333	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$436,333
D5030910 - Fire Alarm Systems	\$0	\$0	\$0	\$0	\$788,500	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$788,500
D5030920 - Data Communication	\$0	\$0	\$0	\$0	\$1,021,064	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,021,064


Campus Assessment Report - 1967, 1977 Main Building

D5090 - Other Electrical Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$177,194	\$177,194
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1010 - Commercial Equipment	\$0	\$0	\$0	\$0	\$130,678	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$130,678
E1020 - Institutional Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1090 - Other Equipment	\$1,054,794	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,054,794
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$980,014	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$980,014

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$9,044,466.68

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$9,044,466.68


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
B2010	Exterior Walls	\$13,200.00	\$0.00	\$0.00	\$0.00	\$0.00	\$13,200.00
B3020	Roof Openings	\$0.00	\$0.00	\$41,326.00	\$0.00	\$0.00	\$41,326.00
C1010	Partitions	\$13,200.00	\$0.00	\$0.00	\$0.00	\$0.00	\$13,200.00
C1030	Fittings	\$0.00	\$0.00	\$10,989.00	\$0.00	\$0.00	\$10,989.00
C3020	Floor Finishes	\$0.00	\$0.00	\$158,238.80	\$0.00	\$0.00	\$158,238.80
C3030	Ceiling Finishes	\$0.00	\$0.00	\$50,403.94	\$0.00	\$0.00	\$50,403.94
D1010	Elevators and Lifts	\$0.00	\$0.00	\$192,854.00	\$0.00	\$0.00	\$192,854.00
D2010	Plumbing Fixtures	\$0.00	\$0.00	\$1,737,656.00	\$0.00	\$0.00	\$1,737,656.00
D3020	Heat Generating Systems	\$0.00	\$0.00	\$1,363,755.00	\$0.00	\$0.00	\$1,363,755.00
D3040	Distribution Systems	\$0.00	\$0.00	\$1,647,132.00	\$0.00	\$0.00	\$1,647,132.00
D3050	Terminal & Package Units	\$0.00	\$0.00	\$934,753.00	\$0.00	\$0.00	\$934,753.00
D4010	Sprinklers	\$0.00	\$0.00	\$714,348.00	\$0.00	\$0.00	\$714,348.00
D4020	Standpipes	\$0.00	\$0.00	\$108,235.00	\$0.00	\$0.00	\$108,235.00
D5020	Lighting	\$0.00	\$0.00	\$23,567.94	\$0.00	\$0.00	\$23,567.94
E1090	Other Equipment	\$0.00	\$0.00	\$1,054,794.00	\$0.00	\$0.00	\$1,054,794.00
E2010	Fixed Furnishings	\$0.00	\$0.00	\$980,014.00	\$0.00	\$0.00	\$980,014.00
	Total:	\$26,400.00	\$0.00	\$9,018,066.68	\$0.00	\$0.00	\$9,044,466.68

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$9,044,466.68

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 1 - Currently Critical (Immediate):


System: B2010 - Exterior Walls



Location: Exterior Walls
Distress: Damaged
Category: Safety / Building Code Compliance
Priority: 1 - Currently Critical (Immediate)
Correction: Engineering Study-2016-11-15 17:41:59
Qty: 1.00
Unit of Measure: Ea.
Estimate: \$13,200.00
Assessor Name: Terence Davis
Date Created: 01/06/2017

Notes: There are visible cracks on the exterior walls and it should be studied by a professional engineer.

System: C1010 - Partitions



Location: Media Center
Distress: Failing
Category: Safety / Building Code Compliance
Priority: 1 - Currently Critical (Immediate)
Correction: Engineering Study
Qty: 1.00
Unit of Measure: Ea.
Estimate: \$13,200.00
Assessor Name: Terence Davis
Date Created: 01/06/2017

Notes: There are visible cracks on the partition wall and should be studied by a professional engineer.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: B3020 - Roof Openings



Location: Roof
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 178,900.00
Unit of Measure: S.F.
Estimate: \$41,326.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The roof openings are beyond their service life and should be replaced by OSHA complaint access.

System: C1030 - Fittings



Location: Throughout Building
Distress: Inadequate
Category: Building Code Compliance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Replace signage and toilet partitions
Qty: 150.00
Unit of Measure: Ea.
Estimate: \$10,989.00
Assessor Name: Terence Davis
Date Created: 02/14/2017

Notes: The signage is not ADA compliant and should be replaced.

System: C3020 - Floor Finishes



Location: Throughout building
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Replace carpet
Qty: 1,851.11
Unit of Measure: S.Y.
Estimate: \$158,238.80
Assessor Name: Terence Davis
Date Created: 01/06/2017

Notes: The carpet is beyond its service life and should be replaced.

System: C3030 - Ceiling Finishes



Location: Throughout building
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Acoustic tile repairs - (2% of ceilings)
Qty: 47.20
Unit of Measure: C.S.F.
Estimate: \$50,403.94
Assessor Name: Terence Davis
Date Created: 01/06/2017

Notes: The acoustical ceiling tiles are beyond their service life and should be replaced.

System: D1010 - Elevators and Lifts



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 178,900.00
Unit of Measure: S.F.
Estimate: \$192,854.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The elevators and lifts are beyond their service life and should be replaced.

System: D2010 - Plumbing Fixtures



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 178,900.00
Unit of Measure: S.F.
Estimate: \$1,737,656.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The plumbing fixtures are beyond their service life and should be replaced.

System: D3020 - Heat Generating Systems



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 178,900.00
Unit of Measure: S.F.
Estimate: \$1,363,755.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The heat generating systems are beyond their service life and should be replaced.

System: D3040 - Distribution Systems



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 178,900.00
Unit of Measure: S.F.
Estimate: \$1,647,132.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The distribution system is beyond its service life and should be replaced.

System: D3050 - Terminal & Package Units



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 178,900.00
Unit of Measure: S.F.
Estimate: \$934,753.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The terminal and package units are beyond their service life and should be replaced.

System: D4010 - Sprinklers

This deficiency has no image.

Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 178,900.00
Unit of Measure: S.F.
Estimate: \$714,348.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The building does not have a fire protection system and it should be installed.


System: D4020 - Standpipes

This deficiency has no image.

Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 178,900.00
Unit of Measure: S.F.
Estimate: \$108,235.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The building does not have a fire protection system and it should be installed.

System: D5020 - Lighting



Location: Throughout building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Replace fluorescent fixture, lay-in, recess mtd, 2' x 4', two 40 W
Qty: 75.00
Unit of Measure: Ea.
Estimate: \$23,567.94
Assessor Name: Terence Davis
Date Created: 01/06/2017

Notes: The lighting fixtures are beyond their service life and should be replaced.

System: E1090 - Other Equipment



Location: Cafeteria and Home Economics Classrooms
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 178,900.00
Unit of Measure: S.F.
Estimate: \$1,054,794.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The kitchen equipment is beyond its service life and should be replaced.

System: E2010 - Fixed Furnishings



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 178,900.00
Unit of Measure: S.F.
Estimate: \$980,014.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The fixed furnishings are beyond their service life and should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	430
Year Built:	1977
Last Renovation:	
Replacement Value:	\$68,887
Repair Cost:	\$10,631.84
Total FCI:	15.43 %
Total RSLI:	31.65 %
FCA Score:	84.57







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	430
Year Built:	1977	Last Renovation:	
Repair Cost:	\$10,632	Replacement Value:	\$68,887
FCI:	15.43 %	RSLI%:	31.65 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	60.00 %	0.00 %	\$0.00
B10 - Superstructure	60.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	8.33 %	20.49 %	\$4,899.84
B30 - Roofing	0.00 %	137.99 %	\$5,732.00
C20 - Stairs	60.00 %	0.00 %	\$0.00
C30 - Interior Finishes	40.00 %	0.00 %	\$0.00
D50 - Electrical	12.84 %	0.00 %	\$0.00
Totals:	31.65 %	15.43 %	\$10,631.84

Photo Album

The photo album consists of the various cardinal directions of the building..

1). North Elevation - Jan 11, 2017



2). West Elevation - Jan 11, 2017



3). South Elevation - Jan 11, 2017



4). East Elevation - Jan 11, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$20.13	S.F.	430	100	1977	2077		60.00 %	0.00 %	60			\$8,656
A1030	Slab on Grade	\$19.75	S.F.	430	100	1977	2077		60.00 %	0.00 %	60			\$8,493
B1010	Floor Construction	\$11.44	S.F.	430	100	1977	2077		60.00 %	0.00 %	60			\$4,919
B1020	Roof Construction	\$16.26	S.F.	430	100	1977	2077		60.00 %	0.00 %	60			\$6,992
B2010	Exterior Walls	\$29.79	S.F.	430	100	1977	2077	2021	4.00 %	38.25 %	4		\$4,899.84	\$12,810
B2020	Exterior Windows	\$17.17	S.F.	430	30	1977	2007	2021	13.33 %	0.00 %	4			\$7,383
B2030	Exterior Doors	\$8.66	S.F.	430	30	1977	2007	2021	13.33 %	0.00 %	4			\$3,724
B3010130	Preformed Metal Roofing	\$9.66	S.F.	430	30	1977	2007		0.00 %	137.99 %	-10		\$5,732.00	\$4,154
C2010	Stair Construction	\$1.32	S.F.	430	100	1977	2077		60.00 %	0.00 %	60			\$568
C3010	Wall Finishes	\$5.11	S.F.	430	10	1977	1987	2021	40.00 %	0.00 %	4			\$2,197
D5010	Electrical Service/Distribution	\$3.09	S.F.	430	40	1977	2017	2021	10.00 %	0.00 %	4			\$1,329
D5020	Branch Wiring	\$9.24	S.F.	430	30	1977	2007	2021	13.33 %	0.00 %	4			\$3,973
D5020	Lighting	\$8.58	S.F.	430	30	1977	2007	2021	13.33 %	0.00 %	4			\$3,689
Total									31.65 %	15.43 %			\$10,631.84	\$68,887

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls



Note:

System: B2020 - Exterior Windows



Note:


System: B2030 - Exterior Doors



Note:

Campus Assessment Report - 1977 Baseball Pressbox

System: B3010130 - Preformed Metal Roofing



Note:

System: C2010 - Stair Construction



Note:

System: C3010 - Wall Finishes



Note:

Campus Assessment Report - 1977 Baseball Pressbox

System: D5010 - Electrical Service/Distribution



Note:

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Campus Assessment Report - 1977 Baseball Pressbox


Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$10,632	\$0	\$0	\$0	\$27,603	\$0	\$0	\$0	\$0	\$0	\$0	\$38,235
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$4,900	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$4,900
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$9,140	\$0	\$0	\$0	\$0	\$0	\$0	\$9,140
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$4,610	\$0	\$0	\$0	\$0	\$0	\$0	\$4,610
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010130 - Preformed Metal Roofing	\$5,732	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$5,732
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C20 - Stairs	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C2010 - Stair Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$2,720	\$0	\$0	\$0	\$0	\$0	\$0	\$2,720
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$1,645	\$0	\$0	\$0	\$0	\$0	\$0	\$1,645
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$4,920	\$0	\$0	\$0	\$0	\$0	\$0	\$4,920
D5020 - Lighting	\$0	\$0	\$0	\$0	\$4,567	\$0	\$0	\$0	\$0	\$0	\$0	\$4,567

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$10,631.84

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$10,631.84


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
B2010	Exterior Walls	\$0.00	\$0.00	\$4,899.84	\$0.00	\$0.00	\$4,899.84
B3010130	Preformed Metal Roofing	\$0.00	\$0.00	\$5,732.00	\$0.00	\$0.00	\$5,732.00
	Total:	\$0.00	\$0.00	\$10,631.84	\$0.00	\$0.00	\$10,631.84

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$10,631.84

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: B2010 - Exterior Walls



Location: Exterior Walls
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Refinish aluminum siding, 2nd floor
Qty: 12.80
Unit of Measure: C.S.F.
Estimate: \$4,899.84
Assessor Name: Eduardo Lopez
Date Created: 01/11/2017

Notes: The exterior wall finish is in poor condition and should be replaced.

System: B3010130 - Preformed Metal Roofing



Location: Roof
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 430.00
Unit of Measure: S.F.
Estimate: \$5,732.00
Assessor Name: Eduardo Lopez
Date Created: 01/11/2017

Notes: The roof is beyond its service life and should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	14,000
Year Built:	1977
Last Renovation:	
Replacement Value:	\$2,353,260
Repair Cost:	\$64,372.00
Total FCI:	2.74 %
Total RSLI:	38.36 %
FCA Score:	97.26







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	14,000
Year Built:	1977	Last Renovation:	
Repair Cost:	\$64,372	Replacement Value:	\$2,353,260
FCI:	2.74 %	RSLI%:	38.36 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	60.00 %	0.00 %	\$0.00
A20 - Basement Construction	60.00 %	0.00 %	\$0.00
B10 - Superstructure	60.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	31.73 %	0.00 %	\$0.00
B30 - Roofing	13.33 %	0.00 %	\$0.00
C10 - Interior Construction	32.65 %	0.00 %	\$0.00
C30 - Interior Finishes	55.48 %	0.00 %	\$0.00
D20 - Plumbing	20.03 %	0.00 %	\$0.00
D30 - HVAC	29.15 %	0.00 %	\$0.00
D40 - Fire Protection	0.00 %	110.00 %	\$64,372.00
D50 - Electrical	51.08 %	0.00 %	\$0.00
Totals:	38.36 %	2.74 %	\$64,372.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). West Elevation - Feb 13, 2017



2). Northwest Elevation - Feb 13, 2017



3). North Elevation - Feb 13, 2017



4). East Elevation - Feb 13, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

Campus Assessment Report - 1977 Technology Building

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$2.18	S.F.	14,000	100	1977	2077		60.00 %	0.00 %	60			\$30,520
A1030	Slab on Grade	\$4.08	S.F.	14,000	100	1977	2077		60.00 %	0.00 %	60			\$57,120
A2010	Basement Excavation	\$0.83	S.F.	14,000	100	1977	2077		60.00 %	0.00 %	60			\$11,620
A2020	Basement Walls	\$5.74	S.F.	14,000	100	1977	2077		60.00 %	0.00 %	60			\$80,360
B1020	Roof Construction	\$7.60	S.F.	14,000	100	1977	2077		60.00 %	0.00 %	60			\$106,400
B2010	Exterior Walls	\$8.84	S.F.	14,000	100	1977	2077		60.00 %	0.00 %	60			\$123,760
B2020	Exterior Windows	\$12.78	S.F.	14,000	30	1977	2007	2021	13.33 %	0.00 %	4			\$178,920
B2030	Exterior Doors	\$0.81	S.F.	14,000	30	1977	2007	2021	13.33 %	0.00 %	4			\$11,340
B3010130	Preformed Metal Roofing	\$9.66	S.F.	14,000	30	1977	2007	2021	13.33 %	0.00 %	4			\$135,240
C1010	Partitions	\$4.70	S.F.	14,000	75	1977	2052		46.67 %	0.00 %	35			\$65,800
C1020	Interior Doors	\$2.44	S.F.	14,000	30	1977	2007	2021	13.33 %	0.00 %	4			\$34,160
C1030	Fittings	\$1.48	S.F.	14,000	20	1977	1997	2021	20.00 %	0.00 %	4			\$20,720
C3010	Wall Finishes	\$2.56	S.F.	14,000	10	1977	1987	2021	40.00 %	0.00 %	4			\$35,840
C3020	Floor Finishes	\$10.94	S.F.	14,000	20	1977	1997	2021	20.00 %	0.00 %	4			\$153,160
C3030	Ceiling Finishes	\$10.56	S.F.	14,000	25	2016	2041		96.00 %	0.00 %	24			\$147,840
D2010	Plumbing Fixtures	\$8.83	S.F.	14,000	30	1977	2007	2021	13.33 %	0.00 %	4			\$123,620
D2020	Domestic Water Distribution	\$1.64	S.F.	14,000	30	2007	2037		66.67 %	0.00 %	20			\$22,960
D2030	Sanitary Waste	\$2.59	S.F.	14,000	30	1977	2007	2021	13.33 %	0.00 %	4			\$36,260
D3040	Distribution Systems	\$8.37	S.F.	14,000	30	2000	2030		43.33 %	0.00 %	13			\$117,180
D3050	Terminal & Package Units	\$26.64	S.F.	14,000	15	2000	2015	2021	26.67 %	0.00 %	4			\$372,960
D3060	Controls & Instrumentation	\$2.65	S.F.	14,000	20	2000	2020		15.00 %	0.00 %	3			\$37,100
D3090	Other HVAC Systems/Equip	\$1.06	S.F.	14,000	20	2000	2020		15.00 %	0.00 %	3			\$14,840
D4010	Sprinklers	\$3.63	S.F.	14,000	30	1977	2007		0.00 %	110.00 %	-10		\$55,902.00	\$50,820
D4020	Standpipes	\$0.55	S.F.	14,000	30	1977	2007		0.00 %	110.00 %	-10		\$8,470.00	\$7,700
D5010	Electrical Service/Distribution	\$1.60	S.F.	14,000	40	1977	2017	2021	10.00 %	0.00 %	4			\$22,400
D5020	Branch Wiring	\$4.55	S.F.	14,000	30	1977	2007	2021	13.33 %	0.00 %	4			\$63,700
D5020	Lighting	\$10.64	S.F.	14,000	30	2016	2046		96.67 %	0.00 %	29			\$148,960
D5030810	Security & Detection Systems	\$1.97	S.F.	14,000	15	1977	1992	2021	26.67 %	0.00 %	4			\$27,580
D5030910	Fire Alarm Systems	\$3.56	S.F.	14,000	15	1977	1992	2021	26.67 %	0.00 %	4			\$49,840
D5030920	Data Communication	\$4.61	S.F.	14,000	15	1977	1992	2021	26.67 %	0.00 %	4			\$64,540
Total									38.36 %	2.74 %			\$64,372.00	\$2,353,260

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B1020 - Roof Construction



Note:

System: B2010 - Exterior Walls



Note:

System: B2020 - Exterior Windows



Note:

Campus Assessment Report - 1977 Technology Building

System: B2030 - Exterior Doors





Note:

System: B3010130 - Preformed Metal Roofing



Note:


System: C1010 - Partitions



Note:

Campus Assessment Report - 1977 Technology Building

System: C1020 - Interior Doors




Note:

System: C1030 - Fittings



Note:

System: C3010 - Wall Finishes



Note:

Campus Assessment Report - 1977 Technology Building

System: C3020 - Floor Finishes





Note:

System: C3030 - Ceiling Finishes



Note:


System: D2010 - Plumbing Fixtures



Note:



Campus Assessment Report - 1977 Technology Building

System: D2020 - Domestic Water Distribution



Note:

System: D2030 - Sanitary Waste



Note:


System: D3040 - Distribution Systems



Note:

Campus Assessment Report - 1977 Technology Building

System: D3050 - Terminal & Package Units



Note:

System: D3060 - Controls & Instrumentation



Note:

System: D3090 - Other HVAC Systems/Equip



Note:

System: D4010 - Sprinklers

This system contains no images

Note: The building does not have a fire protection system and it should be installed.


System: D4020 - Standpipes

This system contains no images

Note: The building does not have a fire protection system and it should be installed.



Campus Assessment Report - 1977 Technology Building

System: D5010 - Electrical Service/Distribution




Note:

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

Campus Assessment Report - 1977 Technology Building

System: D5030810 - Security & Detection Systems



Note:

System: D5030910 - Fire Alarm Systems



Note:

System: D5030920 - Data Communication



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$64,372	\$0	\$0	\$62,432	\$1,689,586	\$0	\$0	\$0	\$0	\$0	\$0	\$1,816,390
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$221,514	\$0	\$0	\$0	\$0	\$0	\$0	\$221,514
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$14,040	\$0	\$0	\$0	\$0	\$0	\$0	\$14,040
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010130 - Preformed Metal Roofing	\$0	\$0	\$0	\$0	\$210,055	\$0	\$0	\$0	\$0	\$0	\$0	\$210,055
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$42,292	\$0	\$0	\$0	\$0	\$0	\$0	\$42,292
C1030 - Fittings	\$0	\$0	\$0	\$0	\$25,653	\$0	\$0	\$0	\$0	\$0	\$0	\$25,653
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$44,372	\$0	\$0	\$0	\$0	\$0	\$0	\$44,372
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$189,621	\$0	\$0	\$0	\$0	\$0	\$0	\$189,621


Campus Assessment Report - 1977 Technology Building

C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$153,049	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$153,049
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$44,892	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$44,892
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$461,747	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$461,747
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$44,594	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$44,594
D3090 - Other HVAC Systems/Equip	\$0	\$0	\$0	\$17,838	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$17,838
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$55,902	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$55,902
D4020 - Standpipes	\$8,470	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$8,470
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$27,733	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$27,733
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$78,864	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$78,864
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$34,146	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$34,146
D5030910 - Fire Alarm Systems	\$0	\$0	\$0	\$0	\$61,705	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$61,705
D5030920 - Data Communication	\$0	\$0	\$0	\$0	\$79,904	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$79,904

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.




Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$64,372.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
D4010	Sprinklers	\$0.00	\$0.00	\$55,902.00	\$0.00	\$0.00	\$55,902.00
D4020	Standpipes	\$0.00	\$0.00	\$8,470.00	\$0.00	\$0.00	\$8,470.00
	Total:	\$0.00	\$0.00	\$64,372.00	\$0.00	\$0.00	\$64,372.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: D4010 - Sprinklers

This deficiency has no image.

Location: Throughout Building
Distress: Missing
Category: Building Code Compliance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 14,000.00
Unit of Measure: S.F.
Estimate: \$55,902.00
Assessor Name: Eduardo Lopez
Date Created: 02/13/2017

Notes: The building does not have a fire protection system and it should be installed.

System: D4020 - Standpipes

This deficiency has no image.

Location: Throughout Building
Distress: Missing
Category: Building Code Compliance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 14,000.00
Unit of Measure: S.F.
Estimate: \$8,470.00
Assessor Name: Eduardo Lopez
Date Created: 02/13/2017

Notes: The building does not have a fire protection system and it should be installed.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	6,000
Year Built:	1979
Last Renovation:	
Replacement Value:	\$1,482,480
Repair Cost:	\$37,843.00
Total FCI:	2.55 %
Total RSLI:	34.22 %
FCA Score:	97.45







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	6,000
Year Built:	1979	Last Renovation:	
Repair Cost:	\$37,843	Replacement Value:	\$1,482,480
FCI:	2.55 %	RSLI%:	34.22 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	62.00 %	0.00 %	\$0.00
B10 - Superstructure	62.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	39.40 %	0.00 %	\$0.00
B30 - Roofing	0.00 %	146.00 %	\$37,843.00
C10 - Interior Construction	33.74 %	0.00 %	\$0.00
C30 - Interior Finishes	20.61 %	0.00 %	\$0.00
D20 - Plumbing	13.33 %	0.00 %	\$0.00
D30 - HVAC	23.00 %	0.00 %	\$0.00
D50 - Electrical	13.53 %	0.00 %	\$0.00
E10 - Equipment	20.00 %	0.00 %	\$0.00
Totals:	34.22 %	2.55 %	\$37,843.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). East Elevation - Jan 11, 2017



2). North Elevation - Jan 11, 2017



3). West Elevation - Jan 11, 2017



4). South Elevation - Jan 11, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$20.13	S.F.	6,000	100	1979	2079		62.00 %	0.00 %	62			\$120,780
A1030	Slab on Grade	\$19.75	S.F.	6,000	100	1979	2079		62.00 %	0.00 %	62			\$118,500
B1020	Roof Construction	\$16.26	S.F.	6,000	100	1979	2079		62.00 %	0.00 %	62			\$97,560
B2010	Exterior Walls	\$29.79	S.F.	6,000	100	1979	2079		62.00 %	0.00 %	62			\$178,740
B2020	Exterior Windows	\$17.17	S.F.	6,000	30	1979	2009	2021	13.33 %	0.00 %	4			\$103,020
B2030	Exterior Doors	\$8.66	S.F.	6,000	30	1979	2009	2021	13.33 %	0.00 %	4			\$51,960
B3010140	Asphalt Shingles	\$4.32	S.F.	6,000	20	1979	1999		0.00 %	146.00 %	-18		\$37,843.00	\$25,920
C1010	Partitions	\$10.34	S.F.	6,000	75	1979	2054		49.33 %	0.00 %	37			\$62,040
C1020	Interior Doors	\$2.20	S.F.	6,000	30	1979	2009	2021	13.33 %	0.00 %	4			\$13,200
C1030	Fittings	\$8.47	S.F.	6,000	20	1979	1999	2021	20.00 %	0.00 %	4			\$50,820
C3010	Wall Finishes	\$5.11	S.F.	6,000	10	1979	1989	2021	40.00 %	0.00 %	4			\$30,660
C3020	Floor Finishes	\$20.82	S.F.	6,000	20	1979	1999	2021	20.00 %	0.00 %	4			\$124,920
C3030	Ceiling Finishes	\$18.76	S.F.	6,000	25	1979	2004	2021	16.00 %	0.00 %	4			\$112,560
D2010	Plumbing Fixtures	\$9.98	S.F.	6,000	30	1979	2009	2021	13.33 %	0.00 %	4			\$59,880
D2020	Domestic Water Distribution	\$0.84	S.F.	6,000	30	1979	2009	2021	13.33 %	0.00 %	4			\$5,040
D2030	Sanitary Waste	\$5.94	S.F.	6,000	30	1979	2009	2021	13.33 %	0.00 %	4			\$35,640
D3040	Distribution Systems	\$5.35	S.F.	6,000	30	1979	2009	2021	13.33 %	0.00 %	4			\$32,100
D3050	Terminal & Package Units	\$16.96	S.F.	6,000	15	1979	1994	2021	26.67 %	0.00 %	4			\$101,760
D3060	Controls & Instrumentation	\$3.48	S.F.	6,000	20	1979	1999	2021	20.00 %	0.00 %	4			\$20,880
D5010	Electrical Service/Distribution	\$3.09	S.F.	6,000	40	1979	2019		5.00 %	0.00 %	2			\$18,540
D5020	Branch Wiring	\$3.58	S.F.	6,000	30	1979	2009	2021	13.33 %	0.00 %	4			\$21,480
D5020	Lighting	\$9.58	S.F.	6,000	30	1979	2009	2021	13.33 %	0.00 %	4			\$57,480
D5030810	Security & Detection Systems	\$1.00	Ea.	6,000	15	1979	1994	2021	26.67 %	0.00 %	4			\$6,000
D5030910	Fire Alarm Systems	\$1.21	S.F.	6,000	15	1979	1994	2021	26.67 %	0.00 %	4			\$7,260
E1010	Commercial Equipment	\$3.30	S.F.	6,000	20	1979	1999	2021	20.00 %	0.00 %	4			\$19,800
E1020	Institutional Equipment	\$0.99	S.F.	6,000	20	1979	1999	2021	20.00 %	0.00 %	4			\$5,940
Total									34.22 %	2.55 %			\$37,843.00	\$1,482,480

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls




Note:

System: B2020 - Exterior Windows



Note:


System: B2030 - Exterior Doors



Note:



Campus Assessment Report - 1979 Fieldhouse

System: B3010140 - Asphalt Shingles




Note:

System: C1010 - Partitions



Note:



System: C1020 - Interior Doors



Note:



Campus Assessment Report - 1979 Fieldhouse

System: C1030 - Fittings



Note:

System: C3010 - Wall Finishes



Note:


System: C3020 - Floor Finishes



Note:


Campus Assessment Report - 1979 Fieldhouse

System: C3030 - Ceiling Finishes



Note:

System: D2010 - Plumbing Fixtures



Note:

System: D2020 - Domestic Water Distribution



Note:


Campus Assessment Report - 1979 Fieldhouse

System: D2030 - Sanitary Waste



Note:

System: D3040 - Distribution Systems



Note:

System: D3050 - Terminal & Package Units



Note:

Campus Assessment Report - 1979 Fieldhouse

System: D3060 - Controls & Instrumentation



Note:

System: D5010 - Electrical Service/Distribution



Note:


System: D5020 - Branch Wiring



Note:


Campus Assessment Report - 1979 Fieldhouse

System: D5020 - Lighting



Note:

System: D5030810 - Security & Detection Systems



Note:

System: D5030910 - Fire Alarm Systems



Note:


Campus Assessment Report - 1979 Fieldhouse

System: E1010 - Commercial Equipment



Note:

System: E1020 - Institutional Equipment



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$37,843	\$0	\$21,636	\$0	\$1,065,227	\$0	\$0	\$0	\$0	\$0	\$0	\$1,124,706
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$127,545	\$0	\$0	\$0	\$0	\$0	\$0	\$127,545
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$64,330	\$0	\$0	\$0	\$0	\$0	\$0	\$64,330
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010140 - Asphalt Shingles	\$37,843	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$37,843
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$16,342	\$0	\$0	\$0	\$0	\$0	\$0	\$16,342
C1030 - Fittings	\$0	\$0	\$0	\$0	\$62,918	\$0	\$0	\$0	\$0	\$0	\$0	\$62,918
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$37,959	\$0	\$0	\$0	\$0	\$0	\$0	\$37,959
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$154,658	\$0	\$0	\$0	\$0	\$0	\$0	\$154,658
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$139,356	\$0	\$0	\$0	\$0	\$0	\$0	\$139,356
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Campus Assessment Report - 1979 Fieldhouse

D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$74,135	\$0	\$0	\$0	\$0	\$0	\$0	\$74,135
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$6,240	\$0	\$0	\$0	\$0	\$0	\$0	\$6,240
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$44,124	\$0	\$0	\$0	\$0	\$0	\$0	\$44,124
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$39,742	\$0	\$0	\$0	\$0	\$0	\$0	\$39,742
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$125,985	\$0	\$0	\$0	\$0	\$0	\$0	\$125,985
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$25,851	\$0	\$0	\$0	\$0	\$0	\$0	\$25,851
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$21,636	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$21,636
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$26,594	\$0	\$0	\$0	\$0	\$0	\$0	\$26,594
D5020 - Lighting	\$0	\$0	\$0	\$0	\$71,164	\$0	\$0	\$0	\$0	\$0	\$0	\$71,164
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$7,428	\$0	\$0	\$0	\$0	\$0	\$0	\$7,428
D5030910 - Fire Alarm Systems	\$0	\$0	\$0	\$0	\$8,988	\$0	\$0	\$0	\$0	\$0	\$0	\$8,988
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1010 - Commercial Equipment	\$0	\$0	\$0	\$0	\$24,514	\$0	\$0	\$0	\$0	\$0	\$0	\$24,514
E1020 - Institutional Equipment	\$0	\$0	\$0	\$0	\$7,354	\$0	\$0	\$0	\$0	\$0	\$0	\$7,354

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.




Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$37,843.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
B3010140	Asphalt Shingles	\$0.00	\$0.00	\$37,843.00	\$0.00	\$0.00	\$37,843.00
	Total:	\$0.00	\$0.00	\$37,843.00	\$0.00	\$0.00	\$37,843.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: B3010140 - Asphalt Shingles



Location: Roof
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 6,000.00
Unit of Measure: S.F.
Estimate: \$37,843.00
Assessor Name: Eduardo Lopez
Date Created: 01/11/2017

Notes: The roof is beyond its service life and should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	28,500
Year Built:	1991
Last Renovation:	
Replacement Value:	\$5,307,555
Repair Cost:	\$380,219.00
Total FCI:	7.16 %
Total RSLI:	41.97 %
FCA Score:	92.84







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	28,500
Year Built:	1991	Last Renovation:	
Repair Cost:	\$380,219	Replacement Value:	\$5,307,555
FCI:	7.16 %	RSLI%:	41.97 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	74.00 %	0.00 %	\$0.00
A20 - Basement Construction	74.00 %	0.00 %	\$0.00
B10 - Superstructure	74.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	37.27 %	0.00 %	\$0.00
B30 - Roofing	0.00 %	150.00 %	\$298,395.00
C10 - Interior Construction	39.07 %	31.14 %	\$81,824.00
C30 - Interior Finishes	55.46 %	0.00 %	\$0.00
D20 - Plumbing	13.58 %	0.00 %	\$0.00
D30 - HVAC	43.05 %	0.00 %	\$0.00
D40 - Fire Protection	13.33 %	0.00 %	\$0.00
D50 - Electrical	52.56 %	0.00 %	\$0.00
E10 - Equipment	20.00 %	0.00 %	\$0.00
E20 - Furnishings	20.00 %	0.00 %	\$0.00
Totals:	41.97 %	7.16 %	\$380,219.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). Southwest Elevation - Jan 11, 2017



2). South Elevation - Jan 11, 2017



3). East Elevation - Jan 11, 2017



4). West Elevation - Jan 11, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

Campus Assessment Report - 1991 Addition

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$2.32	S.F.	28,500	100	1991	2091		74.00 %	0.00 %	74			\$66,120
A1030	Slab on Grade	\$4.36	S.F.	28,500	100	1991	2091		74.00 %	0.00 %	74			\$124,260
A2010	Basement Excavation	\$0.88	S.F.	28,500	100	1991	2091		74.00 %	0.00 %	74			\$25,080
A2020	Basement Walls	\$6.15	S.F.	28,500	100	1991	2091		74.00 %	0.00 %	74			\$175,275
B1020	Roof Construction	\$8.14	S.F.	28,500	100	1991	2091		74.00 %	0.00 %	74			\$231,990
B2010	Exterior Walls	\$9.48	S.F.	28,500	100	1991	2091		74.00 %	0.00 %	74			\$270,180
B2020	Exterior Windows	\$13.69	S.F.	28,500	30	1991	2021		13.33 %	0.00 %	4			\$390,165
B2030	Exterior Doors	\$0.86	S.F.	28,500	30	1991	2021		13.33 %	0.00 %	4			\$24,510
B3010120	Single Ply Membrane	\$6.98	S.F.	28,500	20	1991	2011		0.00 %	150.00 %	-6		\$298,395.00	\$198,930
C1010	Partitions	\$5.03	S.F.	28,500	75	1991	2066		65.33 %	0.00 %	49			\$143,355
C1020	Interior Doors	\$2.61	S.F.	28,500	30	1991	2021	2016	0.00 %	110.00 %	-1		\$81,824.00	\$74,385
C1030	Fittings	\$1.58	S.F.	28,500	20	1991	2011	2021	20.00 %	0.00 %	4			\$45,030
C3010	Wall Finishes	\$2.75	S.F.	28,500	10	1991	2001	2021	40.00 %	0.00 %	4			\$78,375
C3020	Floor Finishes	\$11.72	S.F.	28,500	20	1991	2011	2021	20.00 %	0.00 %	4			\$334,020
C3030	Ceiling Finishes	\$11.30	S.F.	28,500	25	2016	2041		96.00 %	0.00 %	24			\$322,050
D2010	Plumbing Fixtures	\$9.46	S.F.	28,500	30	1991	2021		13.33 %	0.00 %	4			\$269,610
D2020	Domestic Water Distribution	\$1.76	S.F.	28,500	30	1991	2021		13.33 %	0.00 %	4			\$50,160
D2030	Sanitary Waste	\$2.77	S.F.	28,500	30	1991	2021		13.33 %	0.00 %	4			\$78,945
D2090	Other Plumbing Systems -Nat Gas	\$0.16	S.F.	28,500	40	1991	2031		35.00 %	0.00 %	14			\$4,560
D3020	Heat Generating Systems	\$7.42	S.F.	28,500	30	1991	2021		13.33 %	0.00 %	4			\$211,470
D3030	Cooling Generating Systems	\$7.68	S.F.	28,500	25	2012	2037		80.00 %	0.00 %	20			\$218,880
D3040	Distribution Systems	\$8.96	S.F.	28,500	30	1991	2021		13.33 %	0.00 %	4			\$255,360
D3050	Terminal & Package Units	\$4.75	S.F.	28,500	15	2012	2027		66.67 %	0.00 %	10			\$135,375
D3060	Controls & Instrumentation	\$2.84	S.F.	28,500	20	2012	2032		75.00 %	0.00 %	15			\$80,940
D4010	Sprinklers	\$3.89	S.F.	28,500	30	1991	2021		13.33 %	0.00 %	4			\$110,865
D4020	Standpipes	\$0.59	S.F.	28,500	30	1991	2021		13.33 %	0.00 %	4			\$16,815
D5010	Electrical Service/Distribution	\$1.70	S.F.	28,500	40	1991	2031		35.00 %	0.00 %	14			\$48,450
D5020	Branch Wiring	\$4.87	S.F.	28,500	30	1991	2021		13.33 %	0.00 %	4			\$138,795
D5020	Lighting	\$11.38	S.F.	28,500	30	2016	2046		96.67 %	0.00 %	29			\$324,330
D5030810	Security & Detection Systems	\$2.10	S.F.	28,500	15	1991	2006	2021	26.67 %	0.00 %	4			\$59,850
D5030910	Fire Alarm Systems	\$3.83	S.F.	28,500	15	1991	2006	2021	26.67 %	0.00 %	4			\$109,155
D5030920	Data Communication	\$4.92	S.F.	28,500	15	1991	2006	2021	26.67 %	0.00 %	4			\$140,220
E1020	Institutional Equipment	\$13.97	S.F.	28,500	20	1991	2011	2021	20.00 %	0.00 %	4			\$398,145
E2010	Fixed Furnishings	\$5.33	S.F.	28,500	20	1991	2011	2021	20.00 %	0.00 %	4			\$151,905
Total									41.97 %	7.16 %			\$380,219.00	\$5,307,555

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls



Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:

Campus Assessment Report - 1991 Addition

System: B3010120 - Single Ply Membrane




Note: The roof is beyond its service life and should be replaced.

System: C1010 - Partitions



Note:



System: C1020 - Interior Doors



Note: The doors are in poor condition and should be replaced.

Campus Assessment Report - 1991 Addition

System: C1030 - Fittings



Note:

System: C3010 - Wall Finishes



Note:


System: C3020 - Floor Finishes



Note:


Campus Assessment Report - 1991 Addition

System: C3030 - Ceiling Finishes



Note:

System: D2010 - Plumbing Fixtures



Note:

System: D2020 - Domestic Water Distribution



Note:

Campus Assessment Report - 1991 Addition

System: D2030 - Sanitary Waste



Note:

System: D2090 - Other Plumbing Systems -Nat Gas



Note:

System: D3020 - Heat Generating Systems



Note:

Campus Assessment Report - 1991 Addition

System: D3030 - Cooling Generating Systems



Note:

System: D3040 - Distribution Systems



Note:

System: D3050 - Terminal & Package Units



Note:

Campus Assessment Report - 1991 Addition

System: D3060 - Controls & Instrumentation



Note:

System: D4010 - Sprinklers

This system contains no images

Note: The building does not have a fire protection system and it should be installed.

System: D4020 - Standpipes

This system contains no images

Note: The building does not have a fire protection system and it should be installed.

System: D5010 - Electrical Service/Distribution



Note:

System: D5020 - Branch Wiring



Note:

Campus Assessment Report - 1991 Addition

System: D5020 - Lighting




Note:

System: D5030810 - Security & Detection Systems



Note:

System: D5030910 - Fire Alarm Systems



Note:


Campus Assessment Report - 1991 Addition

System: D5030920 - Data Communication



Note:

System: E1020 - Institutional Equipment



Note:

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$380,219	\$0	\$0	\$0	\$3,545,059	\$0	\$0	\$0	\$0	\$0	\$200,127	\$4,125,405
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$483,048	\$0	\$0	\$0	\$0	\$0	\$0	\$483,048
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$30,345	\$0	\$0	\$0	\$0	\$0	\$0	\$30,345
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010120 - Single Ply Membrane	\$298,395	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$298,395
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$81,824	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$81,824
C1030 - Fittings	\$0	\$0	\$0	\$0	\$55,750	\$0	\$0	\$0	\$0	\$0	\$0	\$55,750
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$97,033	\$0	\$0	\$0	\$0	\$0	\$0	\$97,033
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$413,537	\$0	\$0	\$0	\$0	\$0	\$0	\$413,537


Campus Assessment Report - 1991 Addition

C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$333,793	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$333,793
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$62,101	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$62,101
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$97,739	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$97,739
D2090 - Other Plumbing Systems -Nat Gas	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$0	\$0	\$0	\$0	\$261,812	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$261,812
D3030 - Cooling Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$316,151	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$316,151
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$200,127	\$200,127
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$0	\$0	\$0	\$0	\$137,258	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$137,258
D4020 - Standpipes	\$0	\$0	\$0	\$0	\$20,819	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$20,819
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$171,837	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$171,837
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$74,098	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$74,098
D5030910 - Fire Alarm Systems	\$0	\$0	\$0	\$0	\$135,141	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$135,141
D5030920 - Data Communication	\$0	\$0	\$0	\$0	\$173,601	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$173,601
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$0	\$0	\$0	\$0	\$492,928	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$492,928
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$0	\$188,068	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$188,068

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$380,219.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$380,219.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
B3010120	Single Ply Membrane	\$0.00	\$0.00	\$298,395.00	\$0.00	\$0.00	\$298,395.00
C1020	Interior Doors	\$0.00	\$0.00	\$81,824.00	\$0.00	\$0.00	\$81,824.00
	Total:	\$0.00	\$0.00	\$380,219.00	\$0.00	\$0.00	\$380,219.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):


System: B3010120 - Single Ply Membrane



Location: Roof
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 28,500.00
Unit of Measure: S.F.
Estimate: \$298,395.00
Assessor Name: Terence Davis
Date Created: 01/05/2017

Notes: The roof is beyond its service life and should be replaced.

System: C1020 - Interior Doors



Location: Throughout Building
Distress: Damaged
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 28,500.00
Unit of Measure: S.F.
Estimate: \$81,824.00
Assessor Name: Terence Davis
Date Created: 01/06/2017

Notes: The doors are in poor condition and should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	1,200
Year Built:	1999
Last Renovation:	
Replacement Value:	\$176,604
Repair Cost:	\$32,155.00
Total FCI:	18.21 %
Total RSLI:	42.57 %
FCA Score:	81.79







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	1,200
Year Built:	1999	Last Renovation:	
Repair Cost:	\$32,155	Replacement Value:	\$176,604
FCI:	18.21 %	RSLI%:	42.57 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	82.00 %	0.00 %	\$0.00
B10 - Superstructure	82.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	69.81 %	0.00 %	\$0.00
B30 - Roofing	10.00 %	0.00 %	\$0.00
C10 - Interior Construction	45.62 %	0.00 %	\$0.00
C30 - Interior Finishes	19.01 %	47.14 %	\$16,817.00
D20 - Plumbing	40.00 %	0.00 %	\$0.00
D30 - HVAC	12.61 %	75.32 %	\$15,338.00
D50 - Electrical	42.90 %	0.00 %	\$0.00
E20 - Furnishings	10.00 %	0.00 %	\$0.00
Totals:	42.57 %	18.21 %	\$32,155.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). South Elevation - Jan 11, 2017



2). East Elevation - Jan 11, 2017



3). Northeast Elevation - Jan 11, 2017



4). West Elevation - Jan 11, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$6.93	S.F.	1,200	100	1999	2099		82.00 %	0.00 %	82			\$8,316
A1030	Slab on Grade	\$7.37	S.F.	1,200	100	1999	2099		82.00 %	0.00 %	82			\$8,844
B1020	Roof Construction	\$5.98	S.F.	1,200	100	1999	2099		82.00 %	0.00 %	82			\$7,176
B2010	Exterior Walls	\$18.04	S.F.	1,200	100	1999	2099		82.00 %	0.00 %	82			\$21,648
B2020	Exterior Windows	\$6.47	S.F.	1,200	30	1999	2029		40.00 %	0.00 %	12			\$7,764
B2030	Exterior Doors	\$0.91	S.F.	1,200	30	1999	2029		40.00 %	0.00 %	12			\$1,092
B3010140	Asphalt Shingles	\$4.32	S.F.	1,200	20	1999	2019		10.00 %	0.00 %	2			\$5,184
C1010	Partitions	\$10.34	S.F.	1,200	75	1999	2074		76.00 %	0.00 %	57			\$12,408
C1020	Interior Doors	\$2.20	S.F.	1,200	30	1999	2029		40.00 %	0.00 %	12			\$2,640
C1030	Fittings	\$8.47	S.F.	1,200	20	1999	2019		10.00 %	0.00 %	2			\$10,164
C3010	Wall Finishes	\$7.46	S.F.	1,200	10	1999	2009	2021	40.00 %	0.00 %	4			\$8,952
C3020	Floor Finishes	\$12.74	S.F.	1,200	20	1999	2019	2016	0.00 %	110.00 %	-1		\$16,817.00	\$15,288
C3030	Ceiling Finishes	\$9.53	S.F.	1,200	25	1999	2024		28.00 %	0.00 %	7			\$11,436
D2010	Plumbing Fixtures	\$9.98	S.F.	1,200	30	1999	2029		40.00 %	0.00 %	12			\$11,976
D2020	Domestic Water Distribution	\$0.84	S.F.	1,200	30	1999	2029		40.00 %	0.00 %	12			\$1,008
D2030	Sanitary Waste	\$5.94	S.F.	1,200	30	1999	2029		40.00 %	0.00 %	12			\$7,128
D3040	Distribution Systems	\$5.35	S.F.	1,200	30	1999	2029		40.00 %	0.00 %	12			\$6,420
D3050	Terminal & Package Units	\$11.62	S.F.	1,200	15	1999	2014		0.00 %	110.00 %	-3		\$15,338.00	\$13,944
D5010	Electrical Service/Distribution	\$1.47	S.F.	1,200	40	1999	2039		55.00 %	0.00 %	22			\$1,764
D5020	Branch Wiring	\$2.55	S.F.	1,200	30	1999	2029		40.00 %	0.00 %	12			\$3,060
D5020	Lighting	\$3.58	S.F.	1,200	30	1999	2029		40.00 %	0.00 %	12			\$4,296
E2010	Fixed Furnishings	\$5.08	S.F.	1,200	20	1999	2019		10.00 %	0.00 %	2			\$6,096
Total									42.57 %	18.21 %			\$32,155.00	\$176,604

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls




Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:



Campus Assessment Report - 1999 Visitor Concession Stand

System: B3010140 - Asphalt Shingles





Note:

System: C1010 - Partitions



Note:

System: C1020 - Interior Doors



Note:


Campus Assessment Report - 1999 Visitor Concession Stand

System: C1030 - Fittings



Note:

System: C3010 - Wall Finishes



Note:

System: C3020 - Floor Finishes



Note:



Campus Assessment Report - 1999 Visitor Concession Stand

System: C3030 - Ceiling Finishes




Note:

System: D2010 - Plumbing Fixtures



Note:

System: D2020 - Domestic Water Distribution



Note:

Campus Assessment Report - 1999 Visitor Concession Stand

System: D2030 - Sanitary Waste



Note:

System: D3040 - Distribution Systems



Note:


System: D3050 - Terminal & Package Units



Note:

Campus Assessment Report - 1999 Visitor Concession Stand

System: D5010 - Electrical Service/Distribution





Note:

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

Campus Assessment Report - 1999 Visitor Concession Stand

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$32,155	\$0	\$27,005	\$0	\$11,083	\$0	\$0	\$15,472	\$0	\$0	\$0	\$85,715
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010140 - Asphalt Shingles	\$0	\$0	\$8,030	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$8,030
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$0	\$0	\$11,861	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$11,861
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$11,083	\$0	\$0	\$0	\$0	\$0	\$0	\$11,083
C3020 - Floor Finishes	\$16,817	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$16,817
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$15,472	\$0	\$0	\$0	\$15,472
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Campus Assessment Report - 1999 Visitor Concession Stand

D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3050 - Terminal & Package Units	\$15,338	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$15,338
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$7,114	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$7,114

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$32,155.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$32,155.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
C3020	Floor Finishes	\$0.00	\$0.00	\$16,817.00	\$0.00	\$0.00	\$16,817.00
D3050	Terminal & Package Units	\$0.00	\$0.00	\$15,338.00	\$0.00	\$0.00	\$15,338.00
	Total:	\$0.00	\$0.00	\$32,155.00	\$0.00	\$0.00	\$32,155.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: C3020 - Floor Finishes



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 1,200.00
Unit of Measure: S.F.
Estimate: \$16,817.00
Assessor Name: Eduardo Lopez
Date Created: 01/11/2017

Notes: The floor finishes are beyond their service life and should be replaced.

System: D3050 - Terminal & Package Units



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 1,200.00
Unit of Measure: S.F.
Estimate: \$15,338.00
Assessor Name: Eduardo Lopez
Date Created: 01/11/2017

Notes: The terminal and package units are beyond their service life and should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	5,700
Year Built:	2005
Last Renovation:	
Replacement Value:	\$1,370,337
Repair Cost:	\$10,546.80
Total FCI:	0.77 %
Total RSLI:	63.05 %
FCA Score:	99.23







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	5,700
Year Built:	2005	Last Renovation:	
Repair Cost:	\$10,547	Replacement Value:	\$1,370,337
FCI:	0.77 %	RSLI%:	63.05 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	88.00 %	0.00 %	\$0.00
B10 - Superstructure	88.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	81.69 %	0.00 %	\$0.00
B30 - Roofing	60.00 %	0.00 %	\$0.00
C10 - Interior Construction	63.75 %	0.00 %	\$0.00
C30 - Interior Finishes	45.04 %	4.14 %	\$10,546.80
D20 - Plumbing	60.00 %	0.00 %	\$0.00
D30 - HVAC	31.00 %	0.00 %	\$0.00
D50 - Electrical	49.82 %	0.00 %	\$0.00
E20 - Furnishings	40.00 %	0.00 %	\$0.00
Totals:	63.05 %	0.77 %	\$10,546.80

Photo Album

The photo album consists of the various cardinal directions of the building..

1). East Elevation - Jan 11, 2017



2). North Elevation - Jan 11, 2017



3). West Elevation - Jan 11, 2017



4). South Elevation - Jan 11, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$20.13	S.F.	5,700	100	2005	2105		88.00 %	0.00 %	88			\$114,741
A1030	Slab on Grade	\$19.75	S.F.	5,700	100	2005	2105		88.00 %	0.00 %	88			\$112,575
B1020	Roof Construction	\$16.26	S.F.	5,700	100	2005	2105		88.00 %	0.00 %	88			\$92,682
B2010	Exterior Walls	\$29.79	S.F.	5,700	100	2005	2105		88.00 %	0.00 %	88			\$169,803
B2030	Exterior Doors	\$8.66	S.F.	5,700	30	2005	2035		60.00 %	0.00 %	18			\$49,362
B3010130	Preformed Metal Roofing	\$9.66	S.F.	5,700	30	2005	2035		60.00 %	0.00 %	18			\$55,062
C1010	Partitions	\$10.34	S.F.	5,700	75	2005	2080		84.00 %	0.00 %	63			\$58,938
C1020	Interior Doors	\$2.20	S.F.	5,700	30	2005	2035		60.00 %	0.00 %	18			\$12,540
C1030	Fittings	\$8.47	S.F.	5,700	20	2005	2025		40.00 %	0.00 %	8			\$48,279
C3010	Wall Finishes	\$5.11	S.F.	5,700	10	2005	2015	2021	40.00 %	0.00 %	4			\$29,127
C3020	Floor Finishes	\$20.82	S.F.	5,700	20	2005	2025		40.00 %	8.89 %	8		\$10,546.80	\$118,674
C3030	Ceiling Finishes	\$18.76	S.F.	5,700	25	2005	2030		52.00 %	0.00 %	13			\$106,932
D2010	Plumbing Fixtures	\$9.98	S.F.	5,700	30	2005	2035		60.00 %	0.00 %	18			\$56,886
D2020	Domestic Water Distribution	\$0.84	S.F.	5,700	30	2005	2035		60.00 %	0.00 %	18			\$4,788
D2030	Sanitary Waste	\$5.94	S.F.	5,700	30	2005	2035		60.00 %	0.00 %	18			\$33,858
D3040	Distribution Systems	\$5.35	S.F.	5,700	30	2005	2035		60.00 %	0.00 %	18			\$30,495
D3050	Terminal & Package Units	\$16.96	S.F.	5,700	15	2005	2020		20.00 %	0.00 %	3			\$96,672
D3060	Controls & Instrumentation	\$3.48	S.F.	5,700	20	2005	2025		40.00 %	0.00 %	8			\$19,836
D5010	Electrical Service/Distribution	\$3.09	S.F.	5,700	40	2005	2045		70.00 %	0.00 %	28			\$17,613
D5020	Branch Wiring	\$3.58	S.F.	5,700	30	2005	2035		60.00 %	0.00 %	18			\$20,406
D5020	Lighting	\$9.58	S.F.	5,700	30	2005	2035		60.00 %	0.00 %	18			\$54,606
D5030910	Security & Detection Systems	\$1.97	S.F.	5,700	15	2005	2020		20.00 %	0.00 %	3			\$11,229
D5030920	Data Communication	\$4.61	S.F.	5,700	15	2005	2020		20.00 %	0.00 %	3			\$26,277
E2010	Fixed Furnishings	\$5.08	S.F.	5,700	20	2005	2025		40.00 %	0.00 %	8			\$28,956
Total									63.05 %	0.77 %			\$10,546.80	\$1,370,337

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls



Note:

System: B2030 - Exterior Doors



Note:


System: B3010130 - Preformed Metal Roofing



Note:



Campus Assessment Report - 2005 Weight Room

System: C1010 - Partitions




Note:

System: C1020 - Interior Doors



Note:


System: C1030 - Fittings



Note:




Campus Assessment Report - 2005 Weight Room

System: C3010 - Wall Finishes




Note:

System: C3020 - Floor Finishes



Note: The epoxy in the boys restroom is in poor condition and should be replaced.

System: C3030 - Ceiling Finishes



Note: The acoustical ceiling tiles are beyond their service life and should be replaced.



Campus Assessment Report - 2005 Weight Room

System: D2010 - Plumbing Fixtures




Note:

System: D2020 - Domestic Water Distribution



Note:

System: D2030 - Sanitary Waste



Note:

Campus Assessment Report - 2005 Weight Room

System: D3040 - Distribution Systems



Note:

System: D3050 - Terminal & Package Units



Note:

System: D3060 - Controls & Instrumentation



Note:

Campus Assessment Report - 2005 Weight Room

System: D5010 - Electrical Service/Distribution




Note:

System: D5020 - Branch Wiring



Note:


System: D5020 - Lighting



Note:


Campus Assessment Report - 2005 Weight Room

System: D5030910 - Security & Detection Systems



Note:

System: D5030920 - Data Communication



Note:

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$10,547	\$0	\$0	\$161,282	\$36,061	\$0	\$0	\$0	\$300,630	\$0	\$0	\$508,520
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010130 - Preformed Metal Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$67,274	\$0	\$0	\$67,274
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$36,061	\$0	\$0	\$0	\$0	\$0	\$0	\$36,061
C3020 - Floor Finishes	\$10,547	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$165,365	\$0	\$0	\$175,912
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Campus Assessment Report - 2005 Weight Room

D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$116,199	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$116,199
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$27,641	\$0	\$0	\$27,641
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030910 - Security & Detection Systems	\$0	\$0	\$0	\$13,497	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$13,497
D5030920 - Data Communication	\$0	\$0	\$0	\$31,585	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$31,585
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$40,349	\$0	\$0	\$40,349

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.




Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$10,546.80


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
C3020	Floor Finishes	\$0.00	\$0.00	\$10,546.80	\$0.00	\$0.00	\$10,546.80
	Total:	\$0.00	\$0.00	\$10,546.80	\$0.00	\$0.00	\$10,546.80

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: C3020 - Floor Finishes



Location: Mens Restroom
Distress: Damaged
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Replace epoxy flooring
Qty: 5.00
Unit of Measure: C.S.F.
Estimate: \$10,546.80
Assessor Name: Eduardo Lopez
Date Created: 01/11/2017

Notes: The epoxy flooring in the restroom area is in poor condition and should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	1,620
Year Built:	2008
Last Renovation:	
Replacement Value:	\$201,869
Repair Cost:	\$1,716.53
Total FCI:	0.85 %
Total RSLI:	84.58 %
FCA Score:	99.15







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	1,620
Year Built:	2008	Last Renovation:	
Repair Cost:	\$1,717	Replacement Value:	\$201,869
FCI:	0.85 %	RSLI%:	84.58 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	91.00 %	0.00 %	\$0.00
B10 - Superstructure	91.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	86.27 %	2.76 %	\$1,716.53
B30 - Roofing	55.00 %	0.00 %	\$0.00
C10 - Interior Construction	76.18 %	0.00 %	\$0.00
D50 - Electrical	70.00 %	0.00 %	\$0.00
Totals:	84.58 %	0.85 %	\$1,716.53

Photo Album

The photo album consists of the various cardinal directions of the building..

1). East Elevation - Jan 11, 2017



2). Northeast Elevation - Jan 11, 2017



3). West Elevation - Jan 11, 2017



4). South Elevation - Jan 11, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$20.13	S.F.	1,620	100	2008	2108		91.00 %	0.00 %	91			\$32,611
A1030	Slab on Grade	\$19.75	S.F.	1,620	100	2008	2108		91.00 %	0.00 %	91			\$31,995
B1020	Roof Construction	\$16.26	S.F.	1,620	100	2008	2108		91.00 %	0.00 %	91			\$26,341
B2010	Exterior Walls	\$29.79	S.F.	1,620	100	2008	2108		91.00 %	3.56 %	91		\$1,716.53	\$48,260
B2030	Exterior Doors	\$8.66	S.F.	1,620	30	2008	2038		70.00 %	0.00 %	21			\$14,029
B3010140	Asphalt Shingles	\$4.32	S.F.	1,620	20	2008	2028		55.00 %	0.00 %	11			\$6,998
C1010	Partitions	\$10.34	S.F.	1,620	40	2008	2048		77.50 %	0.00 %	31			\$16,751
C1020	Interior Doors	\$2.20	S.F.	1,620	30	2008	2038		70.00 %	0.00 %	21			\$3,564
D5020	Branch Wiring	\$3.58	S.F.	1,620	30	2008	2038		70.00 %	0.00 %	21			\$5,800
D5020	Lighting	\$9.58	S.F.	1,620	30	2008	2038		70.00 %	0.00 %	21			\$15,520
Total									84.58 %	0.85 %			\$1,716.53	\$201,869

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B1020 - Roof Construction



Note:

System: B2010 - Exterior Walls



Note:

System: B2030 - Exterior Doors



Note:


Campus Assessment Report - 2008 Storage Building

System: B3010140 - Asphalt Shingles




Note:

System: C1010 - Partitions



Note:

System: C1020 - Interior Doors



Note:

Campus Assessment Report - 2008 Storage Building

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.


Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$1,717	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,717
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$1,717	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,717
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010140 - Asphalt Shingles	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

** Indicates non-renewable system*


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.




Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$1,716.53


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
B2010	Exterior Walls	\$1,716.53	\$0.00	\$0.00	\$0.00	\$0.00	\$1,716.53
	Total:	\$1,716.53	\$0.00	\$0.00	\$0.00	\$0.00	\$1,716.53

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$1,716.53

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 1 - Currently Critical (Immediate):

System: B2010 - Exterior Walls



Location: Exterior Walls
Distress: Damaged
Category: Deferred Maintenance / Building Code Compliance
Priority: 1 - Currently Critical (Immediate)
Correction: Replace hardboard panels, 1st floor
Qty: 2.00
Unit of Measure: C.S.F.
Estimate: \$1,716.53
Assessor Name: Eduardo Lopez
Date Created: 01/12/2017

Notes: The exterior siding is falling off and it is in poor condition and it should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	435
Year Built:	2009
Last Renovation:	
Replacement Value:	\$96,169
Repair Cost:	\$0.00
Total FCI:	0.00 %
Total RSLI:	75.92 %
FCA Score:	100.00



Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary


Function:	HS -High School	Gross Area:	435
Year Built:	2009	Last Renovation:	
Repair Cost:	\$0	Replacement Value:	\$96,169
FCI:	0.00 %	RSLI%:	75.92 %

No data found for this asset

No data found for this asset

No data found for this asset

10 Year Investment Forecast



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	92.00 %	0.00 %	\$0.00
B10 - Superstructure	92.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	85.71 %	0.00 %	\$0.00
B30 - Roofing	60.00 %	0.00 %	\$0.00
C10 - Interior Construction	76.13 %	0.00 %	\$0.00
C30 - Interior Finishes	58.78 %	0.00 %	\$0.00
D20 - Plumbing	73.33 %	0.00 %	\$0.00
D30 - HVAC	49.96 %	0.00 %	\$0.00
D50 - Electrical	74.60 %	0.00 %	\$0.00
E20 - Furnishings	60.00 %	0.00 %	\$0.00
Totals:	75.92 %	0.00 %	\$0.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). South Elevation - Jan 12, 2017



2). East Elevation - Jan 12, 2017



3). North Elevation - Jan 12, 2017



4). West Elevation - Jan 12, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$20.13	S.F.	435	100	2009	2109		92.00 %	0.00 %	92			\$8,757
A1030	Slab on Grade	\$19.75	S.F.	435	100	2009	2109		92.00 %	0.00 %	92			\$8,591
B1020	Roof Construction	\$16.26	S.F.	435	100	2009	2109		92.00 %	0.00 %	92			\$7,073
B2010	Exterior Walls	\$29.79	S.F.	435	100	2009	2109		92.00 %	0.00 %	92			\$12,959
B2020	Exterior Windows	\$6.47	S.F.	435	30	2009	2039		73.33 %	0.00 %	22			\$2,814
B2030	Exterior Doors	\$8.66	S.F.	435	30	2009	2039		73.33 %	0.00 %	22			\$3,767
B3010140	Asphalt Shingles	\$4.32	S.F.	435	20	2009	2029		60.00 %	0.00 %	12			\$1,879
C1010	Partitions	\$10.34	S.F.	435	75	2009	2084		89.33 %	0.00 %	67			\$4,498
C1030	Fittings	\$8.47	S.F.	435	20	2009	2029		60.00 %	0.00 %	12			\$3,684
C3010	Wall Finishes	\$5.11	S.F.	435	10	2009	2019		20.00 %	0.00 %	2			\$2,223
C3020	Floor Finishes	\$20.82	S.F.	435	20	2009	2029		60.00 %	0.00 %	12			\$9,057
C3030	Ceiling Finishes	\$18.76	S.F.	435	25	2009	2034		68.00 %	0.00 %	17			\$8,161
D2010	Plumbing Fixtures	\$9.98	S.F.	435	30	2009	2039		73.33 %	0.00 %	22			\$4,341
D2020	Domestic Water Distribution	\$0.84	S.F.	435	30	2009	2039		73.33 %	0.00 %	22			\$365
D2030	Sanitary Waste	\$5.94	S.F.	435	30	2009	2039		73.33 %	0.00 %	22			\$2,584
D3050	Terminal & Package Units	\$10.63	S.F.	435	15	2009	2024		46.67 %	0.00 %	7			\$4,624
D3060	Controls & Instrumentation	\$3.48	S.F.	435	20	2009	2029		60.00 %	0.00 %	12			\$1,514
D5010	Electrical Service/Distribution	\$3.09	S.F.	435	40	2009	2049		80.00 %	0.00 %	32			\$1,344
D5020	Branch Wiring	\$3.58	S.F.	435	30	2009	2039		73.33 %	0.00 %	22			\$1,557
D5020	Lighting	\$9.58	S.F.	435	30	2009	2039		73.33 %	0.00 %	22			\$4,167
E2010	Fixed Furnishings	\$5.08	S.F.	435	20	2009	2029		60.00 %	0.00 %	12			\$2,210
Total									75.92 %					\$96,169

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls



Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:



Campus Assessment Report - 2009 Soccer Storage Building

System: B3010140 - Asphalt Shingles




Note:

System: C1010 - Partitions



Note:



System: C1030 - Fittings



Note:

Campus Assessment Report - 2009 Soccer Storage Building

System: C3010 - Wall Finishes



Note:

System: C3020 - Floor Finishes



Note:

System: C3030 - Ceiling Finishes



Note:

Campus Assessment Report - 2009 Soccer Storage Building

System: D2010 - Plumbing Fixtures




Note:

System: D2020 - Domestic Water Distribution



Note:


System: D2030 - Sanitary Waste



Note:


Campus Assessment Report - 2009 Soccer Storage Building

System: D3050 - Terminal & Package Units



Note:

System: D3060 - Controls & Instrumentation



Note:


System: D5010 - Electrical Service/Distribution



Note:

Campus Assessment Report - 2009 Soccer Storage Building

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$0	\$0	\$2,594	\$0	\$0	\$0	\$0	\$6,255	\$0	\$0	\$0	\$8,849
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010140 - Asphalt Shingles	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$2,594	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,594
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Campus Assessment Report - 2009 Soccer Storage Building

D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$6,255	\$0	\$0	\$0	\$6,255
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

* Indicates non-renewable system

Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.

No data found for this asset

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

No data found for this asset

Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

No data found for this asset

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:

No data found for this asset

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

No data found for this asset

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	490
Year Built:	2009
Last Renovation:	
Replacement Value:	\$85,775
Repair Cost:	\$0.00
Total FCI:	0.00 %
Total RSLI:	80.99 %
FCA Score:	100.00



Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary


Function:	HS -High School	Gross Area:	490
Year Built:	2009	Last Renovation:	
Repair Cost:	\$0	Replacement Value:	\$85,775
FCI:	0.00 %	RSLI%:	80.99 %

No data found for this asset

No data found for this asset

No data found for this asset

10 Year Investment Forecast



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	92.00 %	0.00 %	\$0.00
B10 - Superstructure	92.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	83.33 %	0.00 %	\$0.00
B30 - Roofing	60.00 %	0.00 %	\$0.00
C20 - Stairs	92.00 %	0.00 %	\$0.00
C30 - Interior Finishes	51.23 %	0.00 %	\$0.00
D50 - Electrical	74.32 %	0.00 %	\$0.00
E20 - Furnishings	60.00 %	0.00 %	\$0.00
Totals:	80.99 %	0.00 %	\$0.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). South Elevation - Jan 12, 2017



2). West Elevation - Jan 12, 2017



3). North Elevation - Jan 12, 2017



4). East Elevation - Jan 12, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$20.13	S.F.	490	100	2009	2109		92.00 %	0.00 %	92			\$9,864
A1030	Slab on Grade	\$19.75	S.F.	490	100	2009	2109		92.00 %	0.00 %	92			\$9,678
B1010	Floor Construction	\$11.44	S.F.	490	100	2009	2109		92.00 %	0.00 %	92			\$5,606
B1020	Roof Construction	\$16.26	S.F.	490	100	2009	2109		92.00 %	0.00 %	92			\$7,967
B2010	Exterior Walls	\$29.79	S.F.	490	100	2009	2109		92.00 %	0.00 %	92			\$14,597
B2020	Exterior Windows	\$17.17	S.F.	490	30	2009	2039		73.33 %	0.00 %	22			\$8,413
B2030	Exterior Doors	\$8.66	S.F.	490	30	2009	2039		73.33 %	0.00 %	22			\$4,243
B3010140	Asphalt Shingles	\$4.32	S.F.	490	20	2009	2029		60.00 %	0.00 %	12			\$2,117
C2010	Stair Construction	\$1.32	S.F.	490	100	2009	2109		92.00 %	0.00 %	92			\$647
C3010	Wall Finishes	\$5.11	S.F.	490	10	2009	2019		20.00 %	0.00 %	2			\$2,504
C3030	Ceiling Finishes	\$9.52	S.F.	490	25	2009	2034		68.00 %	0.00 %	17			\$4,665
D5010	Electrical Service/Distribution	\$3.09	S.F.	490	40	2009	2049		80.00 %	0.00 %	32			\$1,514
D5020	Branch Wiring	\$9.24	S.F.	490	30	2009	2039		73.33 %	0.00 %	22			\$4,528
D5020	Lighting	\$8.58	S.F.	490	30	2009	2039		73.33 %	0.00 %	22			\$4,204
E2010	Fixed Furnishings	\$10.67	S.F.	490	20	2009	2029		60.00 %	0.00 %	12			\$5,228
Total									80.99 %					\$85,775

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B1010 - Floor Construction



Note:

System: B2010 - Exterior Walls



Note:

System: B2020 - Exterior Windows



Note:

Campus Assessment Report - 2009 Softball Pressbox

System: B2030 - Exterior Doors






Note:

System: B3010140 - Asphalt Shingles



Note:




System: C2010 - Stair Construction



Note:

Campus Assessment Report - 2009 Softball Pressbox

System: C3010 - Wall Finishes



Note:

System: C3030 - Ceiling Finishes



Note:

System: D5010 - Electrical Service/Distribution



Note:

Campus Assessment Report - 2009 Softball Pressbox

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%


Campus Assessment Report - 2009 Softball Pressbox

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$0	\$0	\$2,922	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,922
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010140 - Asphalt Shingles	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C20 - Stairs	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C2010 - Stair Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$2,922	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,922
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

* Indicates non-renewable system

Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.

No data found for this asset

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

No data found for this asset

Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

No data found for this asset

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:

No data found for this asset

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

No data found for this asset

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	1,400
Year Built:	2012
Last Renovation:	
Replacement Value:	\$238,070
Repair Cost:	\$0.00
Total FCI:	0.00 %
Total RSLI:	87.22 %
FCA Score:	100.00



Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.


Dashboard Summary

Function:	HS -High School	Gross Area:	1,400
Year Built:	2012	Last Renovation:	
Repair Cost:	\$0	Replacement Value:	\$238,070
FCI:	0.00 %	RSLI%:	87.22 %

No data found for this asset

No data found for this asset

No data found for this asset



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	95.00 %	0.00 %	\$0.00
B10 - Superstructure	95.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	89.68 %	0.00 %	\$0.00
B30 - Roofing	75.00 %	0.00 %	\$0.00
C10 - Interior Construction	91.58 %	0.00 %	\$0.00
C30 - Interior Finishes	73.58 %	0.00 %	\$0.00
D20 - Plumbing	83.33 %	0.00 %	\$0.00
D30 - HVAC	81.96 %	0.00 %	\$0.00
D50 - Electrical	81.51 %	0.00 %	\$0.00
Totals:	87.22 %	0.00 %	\$0.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). North Elevation - Jan 12, 2017



2). East Elevation - Jan 12, 2017



3). Southeast Elevation - Jan 12, 2017



4). West Elevation - Jan 12, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$20.13	S.F.	1,400	100	2012	2112		95.00 %	0.00 %	95			\$28,182
A1030	Slab on Grade	\$19.75	S.F.	1,400	100	2012	2112		95.00 %	0.00 %	95			\$27,650
B1020	Roof Construction	\$16.26	S.F.	1,400	100	2012	2112		95.00 %	0.00 %	95			\$22,764
B2010	Exterior Walls	\$18.04	S.F.	1,400	100	2012	2112		95.00 %	0.00 %	95			\$25,256
B2020	Exterior Windows	\$6.47	S.F.	1,400	30	2012	2042		83.33 %	0.00 %	25			\$9,058
B2030	Exterior Doors	\$8.66	S.F.	1,400	30	2012	2042		83.33 %	0.00 %	25			\$12,124
B3010140	Asphalt Shingles	\$4.32	S.F.	1,400	20	2012	2032		75.00 %	0.00 %	15			\$6,048
C1010	Partitions	\$10.34	S.F.	1,400	75	2012	2087		93.33 %	0.00 %	70			\$14,476
C1020	Interior Doors	\$2.20	S.F.	1,400	30	2012	2042		83.33 %	0.00 %	25			\$3,080
C3010	Wall Finishes	\$5.11	S.F.	1,400	10	2012	2022		50.00 %	0.00 %	5			\$7,154
C3030	Ceiling Finishes	\$18.76	S.F.	1,400	25	2012	2037		80.00 %	0.00 %	20			\$26,264
D2010	Plumbing Fixtures	\$9.98	S.F.	1,400	30	2012	2042		83.33 %	0.00 %	25			\$13,972
D2020	Domestic Water Distribution	\$0.84	S.F.	1,400	30	2012	2042		83.33 %	0.00 %	25			\$1,176
D2030	Sanitary Waste	\$5.94	S.F.	1,400	30	2012	2042		83.33 %	0.00 %	25			\$8,316
D3040	Distribution Systems	\$5.35	S.F.	1,400	30	2012	2042		83.33 %	0.00 %	25			\$7,490
D3090	Other HVAC Systems/Equip	\$1.06	S.F.	1,400	20	2012	2032		75.00 %	0.00 %	15			\$1,484
D5010	Electrical Service/Distribution	\$1.47	S.F.	1,400	40	2012	2052		87.50 %	0.00 %	35			\$2,058
D5020	Branch Wiring	\$3.58	S.F.	1,400	30	2012	2042		83.33 %	0.00 %	25			\$5,012
D5020	Lighting	\$9.58	S.F.	1,400	30	2012	2042		83.33 %	0.00 %	25			\$13,412
D5030810	Security & Detection Systems	\$1.00	Ea.	1,400	15	2012	2027		66.67 %	0.00 %	10			\$1,400
D5030910	Fire Alarm Systems	\$1.21	S.F.	1,400	15	2012	2027		66.67 %	0.00 %	10			\$1,694
Total									87.22 %					\$238,070

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls



Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:



Campus Assessment Report - 2012 Concession Building

System: B3010140 - Asphalt Shingles




Note:

System: C1010 - Partitions



Note:




System: C1020 - Interior Doors



Note:


Campus Assessment Report - 2012 Concession Building

System: C3010 - Wall Finishes



Note:

System: C3030 - Ceiling Finishes



Note:


System: D2010 - Plumbing Fixtures



Note:


Campus Assessment Report - 2012 Concession Building

System: D2020 - Domestic Water Distribution





Note:

System: D2030 - Sanitary Waste



Note:

System: D3040 - Distribution Systems



Note:


Campus Assessment Report - 2012 Concession Building

System: D3090 - Other HVAC Systems/Equip




Note:

System: D5010 - Electrical Service/Distribution



Note:

System: D5020 - Branch Wiring



Note:

Campus Assessment Report - 2012 Concession Building

System: D5020 - Lighting




Note:

System: D5030810 - Security & Detection Systems



Note:

System: D5030910 - Fire Alarm Systems



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$0	\$0	\$0	\$0	\$0	\$9,122	\$0	\$0	\$0	\$0	\$4,573	\$13,696
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010140 - Asphalt Shingles	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$0	\$9,122	\$0	\$0	\$0	\$0	\$0	\$9,122
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Campus Assessment Report - 2012 Concession Building

D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3090 - Other HVAC Systems/Equip	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,070	\$2,070
D5030910 - Fire Alarm Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,504	\$2,504

* Indicates non-renewable system

Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.

No data found for this asset

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

No data found for this asset

Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

No data found for this asset

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:

No data found for this asset

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

No data found for this asset

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	235
Year Built:	2015
Last Renovation:	
Replacement Value:	\$41,535
Repair Cost:	\$0.00
Total FCI:	0.00 %
Total RSLI:	95.20 %
FCA Score:	100.00



Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary


Function:	HS -High School	Gross Area:	235
Year Built:	2015	Last Renovation:	
Repair Cost:	\$0	Replacement Value:	\$41,535
FCI:	0.00 %	RSLI%:	95.20 %

No data found for this asset

No data found for this asset

No data found for this asset

10 Year Investment Forecast



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	98.00 %	0.00 %	\$0.00
B10 - Superstructure	98.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	95.83 %	0.00 %	\$0.00
B30 - Roofing	90.00 %	0.00 %	\$0.00
C20 - Stairs	98.00 %	0.00 %	\$0.00
C30 - Interior Finishes	88.81 %	0.00 %	\$0.00
D50 - Electrical	93.58 %	0.00 %	\$0.00
Totals:	95.20 %	0.00 %	\$0.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). Northeast Elevation - Jan 12, 2017



2). Southeast Elevation - Jan 12, 2017



3). Southwest Elevation - Jan 12, 2017



4). Northwest Elevation - Jan 12, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$20.13	S.F.	235	100	2015	2115		98.00 %	0.00 %	98			\$4,731
A1030	Slab on Grade	\$19.75	S.F.	235	100	2015	2115		98.00 %	0.00 %	98			\$4,641
B1010	Floor Construction	\$11.44	S.F.	235	100	2015	2115		98.00 %	0.00 %	98			\$2,688
B1020	Roof Construction	\$16.26	S.F.	235	100	2015	2115		98.00 %	0.00 %	98			\$3,821
B2010	Exterior Walls	\$29.79	S.F.	235	100	2015	2115		98.00 %	0.00 %	98			\$7,001
B2020	Exterior Windows	\$17.17	S.F.	235	30	2015	2045		93.33 %	0.00 %	28			\$4,035
B2030	Exterior Doors	\$8.66	S.F.	235	30	2015	2045		93.33 %	0.00 %	28			\$2,035
B3010140	Asphalt Shingles	\$4.32	S.F.	235	20	2015	2035		90.00 %	0.00 %	18			\$1,015
C2010	Stair Construction	\$1.32	S.F.	235	100	2015	2115		98.00 %	0.00 %	98			\$310
C3010	Wall Finishes	\$5.11	S.F.	235	10	2015	2025		80.00 %	0.00 %	8			\$1,201
C3020	Floor Finishes	\$12.37	S.F.	235	20	2015	2035		90.00 %	0.00 %	18			\$2,907
C3030	Ceiling Finishes	\$9.52	S.F.	235	25	2015	2040		92.00 %	0.00 %	23			\$2,237
D5010	Electrical Service/Distribution	\$3.09	S.F.	235	40	2015	2055		95.00 %	0.00 %	38			\$726
D5020	Branch Wiring	\$9.24	S.F.	235	30	2015	2045		93.33 %	0.00 %	28			\$2,171
D5020	Lighting	\$8.58	S.F.	235	30	2015	2045		93.33 %	0.00 %	28			\$2,016
Total									95.20 %					\$41,535

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls




Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:

Campus Assessment Report - 2015 Baseball Pressbox

System: B3010140 - Asphalt Shingles



Note:

System: C2010 - Stair Construction



Note:


System: C3010 - Wall Finishes



Note:

Campus Assessment Report - 2015 Baseball Pressbox

System: C3020 - Floor Finishes



Note:

System: C3030 - Ceiling Finishes



Note:

System: D5010 - Electrical Service/Distribution



Note:

Campus Assessment Report - 2015 Baseball Pressbox

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Campus Assessment Report - 2015 Baseball Pressbox


Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,673	\$0	\$0	\$1,673
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010140 - Asphalt Shingles	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C20 - Stairs	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C2010 - Stair Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,673	\$0	\$0	\$1,673
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

* Indicates non-renewable system

Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.

No data found for this asset

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

No data found for this asset

Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

No data found for this asset

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:

No data found for this asset

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

No data found for this asset

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	2,000
Year Built:	2015
Last Renovation:	
Replacement Value:	\$427,460
Repair Cost:	\$0.00
Total FCI:	0.00 %
Total RSLI:	93.99 %
FCA Score:	100.00



Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.


Dashboard Summary

Function:	HS -High School	Gross Area:	2,000
Year Built:	2015	Last Renovation:	
Repair Cost:	\$0	Replacement Value:	\$427,460
FCI:	0.00 %	RSLI%:	93.99 %

No data found for this asset

No data found for this asset

No data found for this asset



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	98.00 %	0.00 %	\$0.00
B10 - Superstructure	98.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	96.69 %	0.00 %	\$0.00
B30 - Roofing	90.00 %	0.00 %	\$0.00
C10 - Interior Construction	96.57 %	0.00 %	\$0.00
C30 - Interior Finishes	89.43 %	0.00 %	\$0.00
D20 - Plumbing	93.33 %	0.00 %	\$0.00
D30 - HVAC	89.38 %	0.00 %	\$0.00
D50 - Electrical	90.52 %	0.00 %	\$0.00
E10 - Equipment	90.00 %	0.00 %	\$0.00
E20 - Furnishings	90.00 %	0.00 %	\$0.00
Totals:	93.99 %	0.00 %	\$0.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). Southeast Elevation - Jan 13, 2017



2). Northeast Elevation - Jan 13, 2017



3). North Elevation - Jan 13, 2017



4). Southwest Elevation - Jan 13, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$20.13	S.F.	2,000	100	2015	2115		98.00 %	0.00 %	98			\$40,260
A1030	Slab on Grade	\$19.75	S.F.	2,000	100	2015	2115		98.00 %	0.00 %	98			\$39,500
B1020	Roof Construction	\$16.26	S.F.	2,000	100	2015	2115		98.00 %	0.00 %	98			\$32,520
B2010	Exterior Walls	\$29.79	S.F.	2,000	100	2015	2115		98.00 %	0.00 %	98			\$59,580
B2020	Exterior Windows	\$6.93	S.F.	2,000	30	2015	2045		93.33 %	0.00 %	28			\$13,860
B2030	Exterior Doors	\$4.70	S.F.	2,000	30	2015	2045		93.33 %	0.00 %	28			\$9,400
B3010140	Asphalt Shingles	\$4.32	S.F.	2,000	20	2015	2035		90.00 %	0.00 %	18			\$8,640
C1010	Partitions	\$11.01	S.F.	2,000	75	2015	2090		97.33 %	0.00 %	73			\$22,020
C1020	Interior Doors	\$2.59	S.F.	2,000	30	2015	2045		93.33 %	0.00 %	28			\$5,180
C3010	Wall Finishes	\$5.11	S.F.	2,000	10	2015	2025		80.00 %	0.00 %	8			\$10,220
C3030	Ceiling Finishes	\$18.76	S.F.	2,000	25	2015	2040		92.00 %	0.00 %	23			\$37,520
D2010	Plumbing Fixtures	\$11.71	S.F.	2,000	30	2015	2045		93.33 %	0.00 %	28			\$23,420
D2020	Domestic Water Distribution	\$0.99	S.F.	2,000	30	2015	2045		93.33 %	0.00 %	28			\$1,980
D2030	Sanitary Waste	\$1.57	S.F.	2,000	30	2015	2045		93.33 %	0.00 %	28			\$3,140
D3040	Distribution Systems	\$6.26	S.F.	2,000	30	2015	2045		93.33 %	0.00 %	28			\$12,520
D3050	Terminal & Package Units	\$9.57	S.F.	2,000	15	2015	2030		86.67 %	0.00 %	13			\$19,140
D3060	Controls & Instrumentation	\$1.98	S.F.	2,000	20	2015	2035		90.00 %	0.00 %	18			\$3,960
D5010	Electrical Service/Distribution	\$1.73	S.F.	2,000	40	2015	2055		95.00 %	0.00 %	38			\$3,460
D5020	Branch Wiring	\$3.58	S.F.	2,000	30	2015	2045		93.33 %	0.00 %	28			\$7,160
D5020	Lighting	\$9.58	S.F.	2,000	30	2015	2045		93.33 %	0.00 %	28			\$19,160
D5030310	Data Communications	\$4.61	S.F.	2,000	15	2015	2030		86.67 %	0.00 %	13			\$9,220
D5030810	Security & Detection Systems	\$3.46	Ea.	2,000	15	2015	2030		86.67 %	0.00 %	13			\$6,920
D5030910	Fire Alarm	\$3.56	S.F.	2,000	15	2015	2030		86.67 %	0.00 %	13			\$7,120
E1010	Commercial Equipment	\$9.83	S.F.	2,000	20	2015	2035		90.00 %	0.00 %	18			\$19,660
E2010	Fixed Furnishings	\$5.95	S.F.	2,000	20	2015	2035		90.00 %	0.00 %	18			\$11,900
Total									93.99 %					\$427,460

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls




Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:




Campus Assessment Report - 2015 Laundromat Building

System: B3010140 - Asphalt Shingles






Note:

System: C1010 - Partitions



Note:



System: C1020 - Interior Doors



Note:



Campus Assessment Report - 2015 Laundromat Building

System: C3010 - Wall Finishes



Note:

System: C3030 - Ceiling Finishes



Note:

System: D2010 - Plumbing Fixtures



Note:

Campus Assessment Report - 2015 Laundromat Building

System: D2020 - Domestic Water Distribution





Note:

System: D2030 - Sanitary Waste



Note:

System: D3040 - Distribution Systems



Note:

Campus Assessment Report - 2015 Laundromat Building

System: D3050 - Terminal & Package Units



Note:

System: D3060 - Controls & Instrumentation



Note:


System: D5010 - Electrical Service/Distribution



Note:




Campus Assessment Report - 2015 Laundromat Building

System: D5020 - Branch Wiring





Note:

System: D5020 - Lighting



Note:


System: D5030310 - Data Communications



Note:

Campus Assessment Report - 2015 Laundromat Building

System: D5030810 - Security & Detection Systems



Note:

System: D5030910 - Fire Alarm



Note:

System: E1010 - Commercial Equipment



Note:

Campus Assessment Report - 2015 Laundromat Building

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$14,241	\$0	\$0	\$14,241
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010140 - Asphalt Shingles	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$14,241	\$0	\$0	\$14,241
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Campus Assessment Report - 2015 Laundromat Building

D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030310 - Data Communications	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030910 - Fire Alarm	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1010 - Commercial Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

* Indicates non-renewable system

Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.

No data found for this asset

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

No data found for this asset

Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

No data found for this asset

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:

No data found for this asset

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

No data found for this asset

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	285,240
Year Built:	1967
Last Renovation:	
Replacement Value:	\$11,480,908
Repair Cost:	\$911,533.06
Total FCI:	7.94 %
Total RSLI:	18.34 %
FCA Score:	92.06







Description:

The narrative for this site is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	285,240
Year Built:	1967	Last Renovation:	
Repair Cost:	\$911,533	Replacement Value:	\$11,480,908
FCI:	7.94 %	RSLI%:	18.34 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
G20 - Site Improvements	23.13 %	12.42 %	\$911,533.06
G30 - Site Mechanical Utilities	8.21 %	0.00 %	\$0.00
G40 - Site Electrical Utilities	13.07 %	0.00 %	\$0.00
Totals:	18.34 %	7.94 %	\$911,533.06

Photo Album

The photo album consists of the various cardinal directions of the building..

- 1). Aerial Image of Scotland High School -
Dec 30, 2016



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
G2010	Roadways	\$3.76	S.F.	285,240	25	1967	1992	2021	16.00 %	1.60 %	4		\$17,160.00	\$1,072,502
G2020	Parking Lots	\$1.61	S.F.	285,240	25	1967	1992		0.00 %	110.00 %	-25		\$505,160.00	\$459,236
G2030	Pedestrian Paving	\$1.98	S.F.	285,240	30	1967	1997	2021	13.33 %	2.25 %	4		\$12,696.06	\$564,775
G2040105	Fence & Guardrails	\$1.20	S.F.	285,240	30	1967	1997		0.00 %	110.00 %	-20		\$376,517.00	\$342,288
G2040950	Baseball Field	\$5.78	S.F.	285,240	20	1967	1987	2021	20.00 %	0.00 %	4			\$1,648,687
G2040950	Covered Walkways	\$0.81	S.F.	285,240	25	1967	1992	2021	16.00 %	0.00 %	4			\$231,044
G2040950	Football Field	\$3.38	S.F.	285,240	20	2009	2029		60.00 %	0.00 %	12			\$964,111
G2040950	Playing Field	\$1.50	S.F.	285,240	20	1967	1987	2021	20.00 %	0.00 %	4			\$427,860
G2040950	Softball Field	\$2.01	S.F.	285,240	20	1967	1987	2021	20.00 %	0.00 %	4			\$573,332
G2040950	Track	\$1.78	S.F.	285,240	20	2009	2029		60.00 %	0.00 %	12			\$507,727
G2050	Landscaping	\$1.91	S.F.	285,240	15	1967	1982		0.00 %	0.00 %	-35			\$544,808
G3010	Water Supply	\$2.42	S.F.	285,240	50	1967	2017	2021	8.00 %	0.00 %	4			\$690,281
G3020	Sanitary Sewer	\$1.52	S.F.	285,240	50	1967	2017	2021	8.00 %	0.00 %	4			\$433,565
G3030	Storm Sewer	\$4.67	S.F.	285,240	50	1967	2017	2021	8.00 %	0.00 %	4			\$1,332,071
G3060	Fuel Distribution	\$1.03	S.F.	285,240	40	1967	2007	2021	10.00 %	0.00 %	4			\$293,797
G4010	Electrical Distribution	\$2.44	S.F.	285,240	50	1967	2017	2021	8.00 %	0.00 %	4			\$695,986
G4020	Site Lighting	\$1.57	S.F.	285,240	30	1967	1997	2021	13.33 %	0.00 %	4			\$447,827
G4030	Site Communications & Security	\$0.88	S.F.	285,240	15	1967	1982	2021	26.67 %	0.00 %	4			\$251,011
Total									18.34 %	7.94 %			\$911,533.06	\$11,480,908

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: G2010 - Roadways



Note:

System: G2020 - Parking Lots



Note: The parking lot is beyond its service life and should be resealed, restriped and recoated.

System: G2030 - Pedestrian Paving



Note:

Campus Assessment Report - Site

System: G2040105 - Fence & Guardrails




Note: The fences and guardrail are rusted and beyond their service life and should be replaced.

System: G2040950 - Baseball Field



Note:

System: G2040950 - Covered Walkways



Note:

Campus Assessment Report - Site

System: G2040950 - Football Field



Note:

System: G2040950 - Playing Field



Note:


System: G2040950 - Softball Field



Note:

Campus Assessment Report - Site

System: G2040950 - Track



Note:

System: G2050 - Landscaping



Note: The landscaping is beyond its service life and should be replaced.


System: G3010 - Water Supply



Note:

Campus Assessment Report - Site

System: G3020 - Sanitary Sewer



Note:

System: G3030 - Storm Sewer



Note:

System: G3060 - Fuel Distribution



Note:

Campus Assessment Report - Site

System: G4010 - Electrical Distribution



Note:

System: G4020 - Site Lighting



Note:

System: G4030 - Site Communications & Security



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.


Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$911,533	\$0	\$0	\$0	\$10,724,988	\$0	\$0	\$0	\$0	\$0	\$0	\$11,636,521
G - Building Sitework	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G20 - Site Improvements	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2010 - Roadways	\$17,160	\$0	\$0	\$0	\$1,327,822	\$0	\$0	\$0	\$0	\$0	\$0	\$1,344,982
G2020 - Parking Lots	\$505,160	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$505,160
G2030 - Pedestrian Paving	\$12,696	\$0	\$0	\$0	\$699,226	\$0	\$0	\$0	\$0	\$0	\$0	\$711,922
G2040 - Site Development	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040105 - Fence & Guardrails	\$376,517	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$376,517
G2040950 - Baseball Field	\$0	\$0	\$0	\$0	\$2,041,173	\$0	\$0	\$0	\$0	\$0	\$0	\$2,041,173
G2040950 - Covered Walkways	\$0	\$0	\$0	\$0	\$286,047	\$0	\$0	\$0	\$0	\$0	\$0	\$286,047
G2040950 - Football Field	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040950 - Playing Field	\$0	\$0	\$0	\$0	\$529,716	\$0	\$0	\$0	\$0	\$0	\$0	\$529,716
G2040950 - Softball Field	\$0	\$0	\$0	\$0	\$709,820	\$0	\$0	\$0	\$0	\$0	\$0	\$709,820
G2040950 - Track	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* G2050 - Landscaping	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G30 - Site Mechanical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3010 - Water Supply	\$0	\$0	\$0	\$0	\$854,609	\$0	\$0	\$0	\$0	\$0	\$0	\$854,609
G3020 - Sanitary Sewer	\$0	\$0	\$0	\$0	\$536,779	\$0	\$0	\$0	\$0	\$0	\$0	\$536,779
G3030 - Storm Sewer	\$0	\$0	\$0	\$0	\$1,649,183	\$0	\$0	\$0	\$0	\$0	\$0	\$1,649,183
G3060 - Fuel Distribution	\$0	\$0	\$0	\$0	\$363,739	\$0	\$0	\$0	\$0	\$0	\$0	\$363,739
G40 - Site Electrical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4010 - Electrical Distribution	\$0	\$0	\$0	\$0	\$861,672	\$0	\$0	\$0	\$0	\$0	\$0	\$861,672
G4020 - Site Lighting	\$0	\$0	\$0	\$0	\$554,436	\$0	\$0	\$0	\$0	\$0	\$0	\$554,436
G4030 - Site Communications & Security	\$0	\$0	\$0	\$0	\$310,766	\$0	\$0	\$0	\$0	\$0	\$0	\$310,766

** Indicates non-renewable system*


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$911,533.06

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$911,533.06


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
G2010	Roadways	\$0.00	\$0.00	\$17,160.00	\$0.00	\$0.00	\$17,160.00
G2020	Parking Lots	\$0.00	\$0.00	\$505,160.00	\$0.00	\$0.00	\$505,160.00
G2030	Pedestrian Paving	\$12,696.06	\$0.00	\$0.00	\$0.00	\$0.00	\$12,696.06
G2040105	Fence & Guardrails	\$0.00	\$0.00	\$376,517.00	\$0.00	\$0.00	\$376,517.00
	Total:	\$12,696.06	\$0.00	\$898,837.00	\$0.00	\$0.00	\$911,533.06

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 1 - Currently Critical (Immediate):

System: G2030 - Pedestrian Paving



Location: Site
Distress: Failing
Category: Life Safety Code Compliance
Priority: 1 - Currently Critical (Immediate)
Correction: Remove and replace concrete sidewalk, 4' wide
Qty: 250.00
Unit of Measure: L.F.
Estimate: \$12,696.06
Assessor Name: Somnath Das
Date Created: 01/09/2017

Notes: The pedestrian paving is undulating and has become a tripping hazard, the pedestrian paving should be replaced.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: G2010 - Roadways



Location: Site
Distress: Failing
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Resurface the roadway
Qty: 100.00
Unit of Measure: L.F.
Estimate: \$17,160.00
Assessor Name: Somnath Das
Date Created: 01/09/2017

Notes: The roadways have cracks and it should be resealed and recoated.

System: G2020 - Parking Lots



Location: Site
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 285,240.00
Unit of Measure: S.F.
Estimate: \$505,160.00
Assessor Name: Somnath Das
Date Created: 12/30/2016

Notes: The parking lot is beyond its service life and should be resealed, restriped and recoated.

Campus Assessment Report - Site

System: G2040105 - Fence & Guardrails



Location: Site
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 285,240.00
Unit of Measure: S.F.
Estimate: \$376,517.00
Assessor Name: Somnath Das
Date Created: 12/30/2016

Notes: The fences and guardrail are rusted and beyond their service life and should be replaced.
