

NC School District/995 Yancey County/High School

Mountain Heritage High

Final

Campus Assessment Report

March 12, 2017



Table of Contents

Campus Executive Summary	7
Campus Dashboard Summary	10
Campus Condition Summary	11
<u>1974 Main</u>	13
Executive Summary	13
Dashboard Summary	14
Condition Summary	15
Photo Album	16
Condition Detail	17
System Listing	18
System Notes	20
Renewal Schedule	33
Forecasted Sustainment Requirement	36
Deficiency Summary By System	37
Deficiency Summary By Priority	38
Deficiency By Priority Investment	39
Deficiency Summary By Category	40
Deficiency Details By Priority	41
<u>1977 Football Press Box</u>	48
Executive Summary	48
Dashboard Summary	49
Condition Summary	50
Photo Album	51
Condition Detail	52
System Listing	53
System Notes	54
Renewal Schedule	60
Forecasted Sustainment Requirement	62
Deficiency Summary By System	63

Campus Assessment Report

Deficiency Summary By Priority	64
Deficiency By Priority Investment	65
Deficiency Summary By Category	66
Deficiency Details By Priority	67
<u>1991 Baseball Fieldhouse</u>	69
Executive Summary	69
Dashboard Summary	70
Condition Summary	71
Photo Album	72
Condition Detail	73
System Listing	74
System Notes	75
Renewal Schedule	81
Forecasted Sustainment Requirement	83
Deficiency Summary By System	84
Deficiency Summary By Priority	85
Deficiency By Priority Investment	86
Deficiency Summary By Category	87
Deficiency Details By Priority	88
<u>1998 Science Wing</u>	91
Executive Summary	91
Dashboard Summary	92
Condition Summary	93
Photo Album	94
Condition Detail	95
System Listing	96
System Notes	98
Renewal Schedule	108
Forecasted Sustainment Requirement	110
Deficiency Summary By System	111
Deficiency Summary By Priority	112

Campus Assessment Report

Deficiency By Priority Investment	113
Deficiency Summary By Category	114
Deficiency Details By Priority	115
<u>2004 EC Wing</u>	116
Executive Summary	116
Dashboard Summary	117
Condition Summary	118
Photo Album	119
Condition Detail	120
System Listing	121
System Notes	122
Renewal Schedule	131
Forecasted Sustainment Requirement	133
Deficiency Summary By System	134
Deficiency Summary By Priority	135
Deficiency By Priority Investment	136
Deficiency Summary By Category	137
Deficiency Details By Priority	138
<u>2005 Football Fieldhouse</u>	139
Executive Summary	139
Dashboard Summary	140
Condition Summary	141
Photo Album	142
Condition Detail	143
System Listing	144
System Notes	145
Renewal Schedule	152
Forecasted Sustainment Requirement	154
Deficiency Summary By System	155
Deficiency Summary By Priority	156
Deficiency By Priority Investment	157

Campus Assessment Report

Deficiency Summary By Category	158
Deficiency Details By Priority	159
<u>2009 Orr Buiding</u>	160
Executive Summary	160
Dashboard Summary	161
Condition Summary	162
Photo Album	163
Condition Detail	164
System Listing	165
System Notes	166
Renewal Schedule	169
Forecasted Sustainment Requirement	170
Deficiency Summary By System	171
Deficiency Summary By Priority	172
Deficiency By Priority Investment	173
Deficiency Summary By Category	174
Deficiency Details By Priority	175
<u>2012 Softball Fieldhouse</u>	176
Executive Summary	176
Dashboard Summary	177
Condition Summary	178
Photo Album	179
Condition Detail	180
System Listing	181
System Notes	182
Renewal Schedule	189
Forecasted Sustainment Requirement	191
Deficiency Summary By System	192
Deficiency Summary By Priority	193
Deficiency By Priority Investment	194
Deficiency Summary By Category	195

Campus Assessment Report

Deficiency Details By Priority	196
<u>Site</u>	197
Executive Summary	197
Dashboard Summary	198
Condition Summary	199
Photo Album	200
Condition Detail	201
System Listing	202
System Notes	203
Renewal Schedule	209
Forecasted Sustainment Requirement	210
Deficiency Summary By System	211
Deficiency Summary By Priority	212
Deficiency By Priority Investment	213
Deficiency Summary By Category	214
Deficiency Details By Priority	215

Campus Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Gross Area (SF):	153,113
Year Built:	1976
Last Renovation:	
Replacement Value:	\$34,317,943
Repair Cost:	\$8,290,970.00
Total FCI:	24.16 %
Total RSLI:	36.94 %
FCA Score:	75.84



Description:

GENERAL:

Mountain Herigate High School is located at 333 MTN Heritage HS Rd. in Burnsville, North Carolina. The 2 story, 153,113 square foot building was originally constructed in 1976 There have been 2 additions to the main building and 5 additional out buildings. In addition to the main building, the campus contains a 1998 science wing addition, a 2004 EC wing, a 1977 Football press box, a 1991 baseball field house, a 2005 football field house, a 2009 Orr building (housing fabrication warehouse), and a 2012 softball field house.

This report contains condition and adequacy data collected during the 2017 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report for the site and building elements.

A. SUBSTRUCTURE

The building rests on footings and foundation walls and is assumed to have standard cast-in-place concrete foundations. The building

Campus Assessment Report - Mountain Heritage High

does not have a basement.

B. SUPERSTRUCTURE

Floor construction is concrete. Roof construction is steel. The exterior envelope is composed of walls of brick veneer over CMU. Exterior windows are aluminum frame with operable panes. Exterior doors are hollow metal steel mostly with glazing. Roofing is typically low slope single ply membrane. Roof openings include roof hatches. Most building entrances appear to comply with ADA requirements.

C. INTERIORS

Interior partitions are typically CMU. Interior doors are generally solid core wood with hollow steel frames and mostly with glazing. Interior fittings include the following items: white boards, graphics and identifying devices, toilet accessories, storage shelving, handrails, fabricated toilet partitions. The interior wall finishes are typically painted CMU. Floor finishes in common areas are typically vinyl composition tile. Floor finishes in assignable spaces is typically vinyl composition tile. Some ACM tile areas still exist. Ceiling finishes in common areas are typically suspended acoustical tile. Ceiling finishes in assignable areas are typically suspended acoustical tile.

CONVEYING:

Conveying equipment includes one hydraulic elevator, and no wheelchair lifts.

D. SERVICES

PLUMBING:

Plumbing fixtures are typically non-low-flow water fixtures with manual control valves. Domestic water distribution is combination of copper and galvanized steel with gas hot water heating. Sanitary waste system is cast iron and plastic. Rain water drainage system is external with roof drains.

HVAC:

Heating is provided by 2 gas fired boilers. Cooling is supplied by 13 rooftop package units. The heating/cooling distribution system is a ductwork system utilizing air handling units. Fresh air is supplied by air handling units. Ceiling mounted exhaust fans are installed in bathrooms and other required areas. Controls and instrumentation are pneumatic and are not centrally controlled by an energy management system. This building does not have a locally controlled Building Automation System.

FIRE PROTECTION:

The building does not have a fire sprinkler system. The building does have a fire suppression system in the kitchen. Standpipes are not included within fire stairs. Fire extinguishers and cabinets are distributed near fire exits and corridors.

ELECTRICAL:

The main electrical service is fed from a pad mounted transformer to the main switchboard/distribution panel located in the building. Lighting is lay-in, recessed and surface type, fluorescent and LED light fixtures. Branch circuit wiring is typically copper serving electrical switches and receptacles. Emergency and life safety egress lighting systems are installed and exit signs are present at exit doors and near stairways and are typically illuminated.

COMMUNICATIONS AND SECURITY:

The fire alarm system consists of audible/visual strobe annunciators in common spaces, balconies and interior corridors. The system is activated by manual pull stations and smoke detectors and the system is centrally monitored. The telephone and data systems are segregated and include dedicated equipment closets. This building does have a local area network (LAN). The building includes an internal security system that is actuated by the following items: contacts, infrared, optical or a combination of all devices. The building has controlled entry doors access provided by card readers; entry doors are secured with magnetic door locks. The security system has CCTV cameras and is not centrally monitored; this building has a public address and paging system separate from the telephone system.

OTHER ELECTRICAL SYSTEMS:

This building does not have a separately derived emergency power system.

E. EQUIPMENT & FURNISHINGS:

This building includes the following items and equipment: fixed food service, library equipment, athletic equipment, theater and stage, audio-visual, vehicle equipment, fixed casework, window treatment, floor grilles and mats, and multiple seating furnishings.

G.

SITE

Campus Assessment Report - Mountain Heritage High

Campus site features include paved driveways and parking lots, pedestrian pavement, flag pole, landscaping, play areas, and fencing. Site mechanical and electrical features include water, sewer, natural gas, and site lighting.

Attributes:

General Attributes:





Condition Assessor:	Matt Mahaffey	Assessment Date:	1/19/2017
Suitability Assessor:			

School Information:

HS Attendance Area:		LEA School No.:	
No. of Mobile Units:	1	No. of Bldgs.:	1
SF of Mobile Units:		Status:	
School Grades:	123.7	Site Acreage:	123.7

Campus Dashboard Summary

Gross Area:	153,113	Last Renovation:	
Year Built:	1976	Replacement Value:	\$34,317,943
Repair Cost:	\$8,290,970	RSLI%:	36.94 %
FCI:	24.16 %		



Campus Condition Summary

The Table below shows the RSLI and FCI for each major system shown at the UNIFORMAT II classification Level 2. Note that Systems with lower FCIs require less investment than systems with higher FCIs.


Current Investment Requirement and Condition by Unifomat Classification

UNIFORMAT Classification	RSLI%	FCI %	Current Repair
A10 - Foundations	71.27 %	0.00 %	\$0.00
B10 - Superstructure	63.71 %	0.00 %	\$0.00
B20 - Exterior Enclosure	36.83 %	46.43 %	\$1,709,508.00
B30 - Roofing	28.30 %	0.00 %	\$0.00
C10 - Interior Construction	32.15 %	38.39 %	\$520,953.00
C20 - Stairs	57.00 %	0.00 %	\$0.00
C30 - Interior Finishes	18.02 %	68.43 %	\$2,742,252.00
D10 - Conveying	83.33 %	0.00 %	\$0.00
D20 - Plumbing	10.65 %	84.84 %	\$1,757,786.00
D30 - HVAC	56.00 %	0.00 %	\$0.00
D40 - Fire Protection	0.00 %	110.00 %	\$650,757.00
D50 - Electrical	39.67 %	14.12 %	\$576,234.00
E10 - Equipment	31.95 %	0.00 %	\$0.00
E20 - Furnishings	16.28 %	0.00 %	\$0.00
G20 - Site Improvements	34.91 %	8.64 %	\$333,480.00
G30 - Site Mechanical Utilities	31.71 %	0.00 %	\$0.00
G40 - Site Electrical Utilities	33.04 %	0.00 %	\$0.00
Totals:	36.94 %	24.16 %	\$8,290,970.00

Condition Deficiency Priority

Facility Name	Gross Area (S.F.)	FCI %	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance
1974 Main	112,000	36.47	\$0.00	\$80,080.00	\$7,118,496.00	\$527,296.00	\$0.00
1977 Football Press Box	1,954	18.91	\$0.00	\$0.00	\$54,379.00	\$0.00	\$0.00
1991 Baseball Fieldhouse	1,200	27.50	\$0.00	\$0.00	\$39,244.00	\$11,180.00	\$0.00
1998 Science Wing	17,000	2.62	\$0.00	\$0.00	\$0.00	\$83,776.00	\$0.00
2004 EC Wing	8,053	2.96	\$0.00	\$0.00	\$0.00	\$39,685.00	\$0.00
2005 Football Fieldhouse	2,520	0.86	\$0.00	\$0.00	\$3,354.00	\$0.00	\$0.00
2009 Orr Buiding	9,000	0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2012 Softball Fieldhouse	1,386	0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
Site	153,113	5.48	\$0.00	\$0.00	\$333,480.00	\$0.00	\$0.00
Total:		24.16	\$0.00	\$80,080.00	\$7,548,953.00	\$661,937.00	\$0.00

Deficiencies By Priority



- 1 - Currently Critical (Immediate)
- 2 - Potentially Critical (Year 1) - \$80,080.00
- 3 - Necessary/Not Yet Critical (Years 2-5) - \$7,548,953.00
- 4 - Recommended (Years 6-10) - \$661,937.00
- 5 - Codes or Standards Compliance

Budget Estimate Total: \$8,290,970.00

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	112,000
Year Built:	1974
Last Renovation:	
Replacement Value:	\$21,181,440
Repair Cost:	\$7,725,872.00
Total FCI:	36.47 %
Total RSLI:	32.45 %
FCA Score:	63.53







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	112,000
Year Built:	1974	Last Renovation:	
Repair Cost:	\$7,725,872	Replacement Value:	\$21,181,440
FCI:	36.47 %	RSLI%:	32.45 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	57.00 %	0.00 %	\$0.00
B10 - Superstructure	57.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	22.49 %	66.61 %	\$1,707,552.00
B30 - Roofing	25.44 %	0.00 %	\$0.00
C10 - Interior Construction	23.28 %	49.99 %	\$491,568.00
C20 - Stairs	57.00 %	0.00 %	\$0.00
C30 - Interior Finishes	7.44 %	98.31 %	\$2,703,008.00
D10 - Conveying	83.33 %	0.00 %	\$0.00
D20 - Plumbing	0.80 %	108.83 %	\$1,723,568.00
D30 - HVAC	61.34 %	0.00 %	\$0.00
D40 - Fire Protection	0.00 %	110.00 %	\$527,296.00
D50 - Electrical	36.00 %	18.16 %	\$572,880.00
E10 - Equipment	35.00 %	0.00 %	\$0.00
E20 - Furnishings	15.00 %	0.00 %	\$0.00
Totals:	32.45 %	36.47 %	\$7,725,872.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). North Elevation - Feb 01, 2017



2). East Elevation - Feb 01, 2017



3). South Elevation - Feb 01, 2017



4). West Elevation - Feb 01, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Campus Assessment Report - 1974 Main

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$2.22	S.F.	112,000	100	1974	2074		57.00 %	0.00 %	57			\$248,640
A1030	Slab on Grade	\$4.16	S.F.	112,000	100	1974	2074		57.00 %	0.00 %	57			\$465,920
B1010	Floor Construction	\$11.66	S.F.	112,000	100	1974	2074		57.00 %	0.00 %	57			\$1,305,920
B1020	Roof Construction	\$7.76	S.F.	112,000	100	1974	2074		57.00 %	0.00 %	57			\$869,120
B2010	Exterior Walls	\$9.03	S.F.	112,000	100	1974	2074		57.00 %	0.00 %	57			\$1,011,360
B2020	Exterior Windows	\$13.04	S.F.	112,000	30	1974	2004		0.00 %	110.00 %	-13		\$1,606,528.00	\$1,460,480
B2030	Exterior Doors	\$0.82	S.F.	112,000	30	1974	2004		0.00 %	110.00 %	-13		\$101,024.00	\$91,840
B3010120	Single Ply Membrane	\$6.98	S.F.	112,000	20	2002	2022		25.00 %	0.00 %	5			\$781,760
B3020	Roof Openings	\$0.21	S.F.	112,000	25	2002	2027		40.00 %	0.00 %	10			\$23,520
C1010	Partitions	\$4.79	S.F.	112,000	75	1974	2049		42.67 %	0.00 %	32			\$536,480
C1020	Interior Doors	\$2.49	S.F.	112,000	30	1974	2004		0.00 %	110.00 %	-13		\$306,768.00	\$278,880
C1030	Fittings	\$1.50	S.F.	112,000	20	1974	1994		0.00 %	110.00 %	-23		\$184,800.00	\$168,000
C2010	Stair Construction	\$1.32	S.F.	112,000	100	1974	2074		57.00 %	0.00 %	57			\$147,840
C3010	Wall Finishes	\$2.61	S.F.	112,000	10	2014	2024		70.00 %	0.00 %	7			\$292,320
C3020	Floor Finishes	\$11.17	S.F.	112,000	20	1974	1994		0.00 %	110.00 %	-23		\$1,376,144.00	\$1,251,040
C3030	Ceiling Finishes	\$10.77	S.F.	112,000	25	1989	2014		0.00 %	110.00 %	-3		\$1,326,864.00	\$1,206,240
D1010	Elevators and Lifts	\$0.99	S.F.	112,000	30	2012	2042		83.33 %	0.00 %	25			\$110,880
D2010	Plumbing Fixtures	\$9.02	S.F.	112,000	30	1974	2004		0.00 %	110.00 %	-13		\$1,111,264.00	\$1,010,240
D2020	Domestic Water Distribution	\$1.68	S.F.	112,000	30	1974	2004		0.00 %	110.00 %	-13		\$206,976.00	\$188,160
D2030	Sanitary Waste	\$2.64	S.F.	112,000	30	1974	2004		0.00 %	110.00 %	-13		\$325,248.00	\$295,680
D2040	Rain Water Drainage	\$0.65	S.F.	112,000	30	1974	2004		0.00 %	110.00 %	-13		\$80,080.00	\$72,800
D2090	Other Plumbing Systems -Nat Gas	\$0.15	S.F.	112,000	40	2007	2047		75.00 %	0.00 %	30			\$16,800
D3020	Heat Generating Systems	\$7.08	S.F.	112,000	30	2002	2032		50.00 %	0.00 %	15			\$792,960
D3030	Cooling Generating Systems	\$8.84	S.F.	112,000	25	2008	2033		64.00 %	0.00 %	16			\$990,080
D3040	Distribution Systems	\$8.54	S.F.	112,000	30	2008	2038		70.00 %	0.00 %	21			\$956,480
D3060	Controls & Instrumentation	\$2.71	S.F.	112,000	20	2008	2028		55.00 %	0.00 %	11			\$303,520
D4010	Sprinklers	\$3.71	S.F.	112,000	30			2017	0.00 %	110.00 %	0		\$457,072.00	\$415,520
D4020	Standpipes	\$0.57	S.F.	112,000	30			2017	0.00 %	110.00 %	0		\$70,224.00	\$63,840
D5010	Electrical Service/Distribution	\$1.62	S.F.	112,000	40	2004	2044		67.50 %	0.00 %	27			\$181,440
D5020	Branch Wiring	\$4.65	S.F.	112,000	30	1974	2004		0.00 %	110.00 %	-13		\$572,880.00	\$520,800
D5020	Lighting	\$10.85	S.F.	112,000	30	1989	2019		6.67 %	0.00 %	2			\$1,215,200
D5030810	Security & Detection Systems	\$2.01	S.F.	112,000	15	2013	2028		73.33 %	0.00 %	11			\$225,120
D5030910	Fire & Alarm Systems	\$3.64	S.F.	112,000	15	2013	2028		73.33 %	0.00 %	11			\$407,680
D5030920	Data Communication	\$4.70	S.F.	112,000	15	2015	2030		86.67 %	0.00 %	13			\$526,400
D5090	Other Electrical Systems	\$0.69	S.F.	112,000	20	1998	2018	2020	15.00 %	0.00 %	3			\$77,280
E1020	Institutional Equipment	\$13.31	S.F.	112,000	20	2004	2024		35.00 %	0.00 %	7			\$1,490,720
E1090	Other Equipment	\$5.46	S.F.	112,000	20	2004	2024		35.00 %	0.00 %	7			\$611,520
E2010	Fixed Furnishings	\$5.08	S.F.	112,000	20	1998	2018	2020	15.00 %	0.00 %	3			\$568,960
Total									32.45 %	36.47 %			\$7,725,872.00	\$21,181,440

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B1020 - Roof Construction



Note:

Campus Assessment Report - 1974 Main

System: B2010 - Exterior Walls



Note:



System: B2020 - Exterior Windows



Note:

Campus Assessment Report - 1974 Main

System: B2030 - Exterior Doors



Note:

System: B3010120 - Single Ply Membrane



Note:




System: B3020 - Roof Openings



Note:


Campus Assessment Report - 1974 Main

System: C1010 - Partitions



Note:

System: C1020 - Interior Doors



Note:

System: C1030 - Fittings



Note:



Campus Assessment Report - 1974 Main

System: C2010 - Stair Construction





Note:

System: C3010 - Wall Finishes



Note:


System: C3020 - Floor Finishes



Note:

Campus Assessment Report - 1974 Main

System: C3030 - Ceiling Finishes




Note:

System: D1010 - Elevators and Lifts



Note:

System: D2010 - Plumbing Fixtures



Note:


Campus Assessment Report - 1974 Main

System: D2020 - Domestic Water Distribution



Note:

System: D2030 - Sanitary Waste



Note:

System: D2040 - Rain Water Drainage



Note:

Campus Assessment Report - 1974 Main

System: D2090 - Other Plumbing Systems -Nat Gas



Note:

System: D3020 - Heat Generating Systems



Note:

System: D3030 - Cooling Generating Systems



Note:

Campus Assessment Report - 1974 Main

System: D3040 - Distribution Systems



Note:

System: D3060 - Controls & Instrumentation



Note:


System: D5010 - Electrical Service/Distribution



Note:




Campus Assessment Report - 1974 Main

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:


System: D5030810 - Security & Detection Systems



Note:


Campus Assessment Report - 1974 Main

System: D5030910 - Fire & Alarm Systems



Note:

System: D5030920 - Data Communication



Note:

System: D5090 - Other Electrical Systems



Note:




Campus Assessment Report - 1974 Main

System: E1020 - Institutional Equipment



Note:

System: E1090 - Other Equipment



Note:

Campus Assessment Report - 1974 Main

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$7,725,872	\$0	\$1,418,126	\$776,780	\$0	\$1,359,411	\$0	\$3,239,507	\$0	\$0	\$34,770	\$14,554,467
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$1,606,528	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,606,528
B2030 - Exterior Doors	\$101,024	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$101,024
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010120 - Single Ply Membrane	\$0	\$0	\$0	\$0	\$0	\$1,359,411	\$0	\$0	\$0	\$0	\$0	\$1,359,411
B3020 - Roof Openings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$34,770	\$34,770
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$306,768	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$306,768
C1030 - Fittings	\$184,800	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$184,800
C20 - Stairs	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C2010 - Stair Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$395,468	\$0	\$0	\$0	\$395,468

Campus Assessment Report - 1974 Main

C3020 - Floor Finishes	\$1,376,144	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,376,144
C3030 - Ceiling Finishes	\$1,326,864	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,326,864
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D10 - Conveying	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D1010 - Elevators and Lifts	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$1,111,264	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,111,264
D2020 - Domestic Water Distribution	\$206,976	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$206,976
D2030 - Sanitary Waste	\$325,248	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$325,248
D2040 - Rain Water Drainage	\$80,080	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$80,080
D2090 - Other Plumbing Systems -Nat Gas	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3030 - Cooling Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$457,072	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$457,072
D4020 - Standpipes	\$70,224	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$70,224
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$572,880	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$572,880
D5020 - Lighting	\$0	\$0	\$1,418,126	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,418,126
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030910 - Fire & Alarm Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030920 - Data Communication	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5090 - Other Electrical Systems	\$0	\$0	\$0	\$92,891	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$92,891
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,016,737	\$0	\$0	\$0	\$0	\$2,016,737
E1090 - Other Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$827,302	\$0	\$0	\$0	\$0	\$827,302
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Campus Assessment Report - 1974 Main

E2010 - Fixed Furnishings	\$0	\$0	\$0	\$683,890	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$683,890
---------------------------	-----	-----	-----	-----------	-----	-----	-----	-----	-----	-----	-----	-----------

** Indicates non-renewable system*


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$7,725,872.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$7,725,872.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
B2020	Exterior Windows	\$0.00	\$0.00	\$1,606,528.00	\$0.00	\$0.00	\$1,606,528.00
B2030	Exterior Doors	\$0.00	\$0.00	\$101,024.00	\$0.00	\$0.00	\$101,024.00
C1020	Interior Doors	\$0.00	\$0.00	\$306,768.00	\$0.00	\$0.00	\$306,768.00
C1030	Fittings	\$0.00	\$0.00	\$184,800.00	\$0.00	\$0.00	\$184,800.00
C3020	Floor Finishes	\$0.00	\$0.00	\$1,376,144.00	\$0.00	\$0.00	\$1,376,144.00
C3030	Ceiling Finishes	\$0.00	\$0.00	\$1,326,864.00	\$0.00	\$0.00	\$1,326,864.00
D2010	Plumbing Fixtures	\$0.00	\$0.00	\$1,111,264.00	\$0.00	\$0.00	\$1,111,264.00
D2020	Domestic Water Distribution	\$0.00	\$0.00	\$206,976.00	\$0.00	\$0.00	\$206,976.00
D2030	Sanitary Waste	\$0.00	\$0.00	\$325,248.00	\$0.00	\$0.00	\$325,248.00
D2040	Rain Water Drainage	\$0.00	\$80,080.00	\$0.00	\$0.00	\$0.00	\$80,080.00
D4010	Sprinklers	\$0.00	\$0.00	\$0.00	\$457,072.00	\$0.00	\$457,072.00
D4020	Standpipes	\$0.00	\$0.00	\$0.00	\$70,224.00	\$0.00	\$70,224.00
D5020	Branch Wiring	\$0.00	\$0.00	\$572,880.00	\$0.00	\$0.00	\$572,880.00
	Total:	\$0.00	\$80,080.00	\$7,118,496.00	\$527,296.00	\$0.00	\$7,725,872.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$7,725,872.00

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 2 - Potentially Critical (Year 1):

System: D2040 - Rain Water Drainage



Location: Throughout
Distress: Failing
Category: Deferred Maintenance
Priority: 2 - Potentially Critical (Year 1)
Correction: Renew System
Qty: 112,000.00
Unit of Measure: S.F.
Estimate: \$80,080.00
Assessor Name: Terence Davis
Date Created: 01/25/2017

Notes: The rain water drainage system is aged, in poor condition, and should be replaced.
Roof drains were not replaced with latest roof replacement and are causing interior leaks.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):


System: B2020 - Exterior Windows



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance / Energy
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 112,000.00
Unit of Measure: S.F.
Estimate: \$1,606,528.00
Assessor Name: Terence Davis
Date Created: 01/25/2017

Notes: The aluminum frame, operable, single pane windows are aged, rusted, not energy efficient, and should be replaced.

System: B2030 - Exterior Doors



Location: Throughout
Distress: Failing
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 112,000.00
Unit of Measure: S.F.
Estimate: \$101,024.00
Assessor Name: Terence Davis
Date Created: 01/25/2017

Notes: The original exterior doors are aged, rusted, and should be replaced.

System: C1020 - Interior Doors



Location: Throughout
Distress: Failing
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 112,000.00
Unit of Measure: S.F.
Estimate: \$306,768.00
Assessor Name: Terence Davis
Date Created: 01/25/2017

Notes: The interior doors are aged, failing, most hardware is not ADA or code compliant and should be replaced.

System: C1030 - Fittings



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance / Accessibility Code Compliance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 112,000.00
Unit of Measure: S.F.
Estimate: \$184,800.00
Assessor Name: Terence Davis
Date Created: 01/25/2017

Notes: The fittings throughout the building are aged, in marginal condition, handrails and room signage are ADA non-compliance and system should be replaced.

System: C3020 - Floor Finishes



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 112,000.00
Unit of Measure: S.F.
Estimate: \$1,376,144.00
Assessor Name: Terence Davis
Date Created: 01/25/2017

Notes: The quarry tile in corridor spaces is chipped, cracked, and failing due to installation over existing damaged VCT. Full removal and replacement is recommended.
The carpet is aged, stained, frayed, and should be replaced.
The VCT flooring is aged, cracked, worn, and should be replaced.

System: C3030 - Ceiling Finishes



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 112,000.00
Unit of Measure: S.F.
Estimate: \$1,326,864.00
Assessor Name: Terence Davis
Date Created: 01/25/2017

Notes: The original ceiling finishes are aged, failing and should be replaced.

System: D2010 - Plumbing Fixtures



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance / Accessibility Code Compliance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 112,000.00
Unit of Measure: S.F.
Estimate: \$1,111,264.00
Assessor Name: Terence Davis
Date Created: 01/25/2017

Notes: Plumbing fixtures are in operational conditions. However, they are aged, not ADA compliant and should be replaced with a low-flow water fixtures.

System: D2020 - Domestic Water Distribution



Location: Various
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 112,000.00
Unit of Measure: S.F.
Estimate: \$206,976.00
Assessor Name: Terence Davis
Date Created: 01/25/2017

Notes: The domestic water distribution system is aged and should be replaced.
Some hot water heating systems have failed and are abandoned in place and service not restored in those areas.

System: D2030 - Sanitary Waste



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 112,000.00
Unit of Measure: S.F.
Estimate: \$325,248.00
Assessor Name: Terence Davis
Date Created: 01/25/2017

Notes: The sanitary waste system is aged, has reported periodic failures, and should be replaced.

System: D5020 - Branch Wiring



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 112,000.00
Unit of Measure: S.F.
Estimate: \$572,880.00
Assessor Name: Terence Davis
Date Created: 01/25/2017

Notes: The branch wiring system is operating, but is aged, in poor condition, and should be replaced.

Priority 4 - Recommended (Years 6-10):

System: D4010 - Sprinklers

This deficiency has no image.

Location: Throughout
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 112,000.00
Unit of Measure: S.F.
Estimate: \$457,072.00
Assessor Name: Terence Davis
Date Created: 01/25/2017

Notes: A Sprinkler system is missing and is recommended to be provided to comply with current codes.

System: D4020 - Standpipes

This deficiency has no image.

Location: Throughout
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 112,000.00
Unit of Measure: S.F.
Estimate: \$70,224.00
Assessor Name: Terence Davis
Date Created: 01/25/2017

Notes: A Sprinkler system is missing and is recommended to be provided to comply with current codes.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	1,954
Year Built:	1977
Last Renovation:	
Replacement Value:	\$287,549
Repair Cost:	\$54,379.00
Total FCI:	18.91 %
Total RSLI:	40.71 %
FCA Score:	81.09







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	1,954
Year Built:	1977	Last Renovation:	
Repair Cost:	\$54,379	Replacement Value:	\$287,549
FCI:	18.91 %	RSLI%:	40.71 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	60.00 %	0.00 %	\$0.00
B10 - Superstructure	60.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	57.85 %	3.94 %	\$1,956.00
B30 - Roofing	40.00 %	0.00 %	\$0.00
C10 - Interior Construction	29.25 %	44.35 %	\$18,205.00
C30 - Interior Finishes	48.87 %	0.00 %	\$0.00
D20 - Plumbing	3.01 %	104.49 %	\$34,218.00
D30 - HVAC	20.00 %	0.00 %	\$0.00
D50 - Electrical	61.93 %	0.00 %	\$0.00
E20 - Furnishings	40.00 %	0.00 %	\$0.00
Totals:	40.71 %	18.91 %	\$54,379.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). Southwest Elevation - Feb 01, 2017



2). East Elevation - Feb 01, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$6.93	S.F.	1,954	100	1977	2077		60.00 %	0.00 %	60			\$13,541
A1030	Slab on Grade	\$7.37	S.F.	1,954	100	1977	2077		60.00 %	0.00 %	60			\$14,401
B1020	Roof Construction	\$5.98	S.F.	1,954	100	1977	2077		60.00 %	0.00 %	60			\$11,685
B2010	Exterior Walls	\$18.04	S.F.	1,954	100	1977	2077		60.00 %	0.00 %	60			\$35,250
B2020	Exterior Windows	\$6.47	S.F.	1,954	30	2005	2035		60.00 %	0.00 %	18			\$12,642
B2030	Exterior Doors	\$0.91	S.F.	1,954	30	1977	2007		0.00 %	110.01 %	-10		\$1,956.00	\$1,778
B3010140	Asphalt Shingles	\$4.32	S.F.	1,954	20	2005	2025		40.00 %	0.00 %	8			\$8,441
C1010	Partitions	\$10.34	S.F.	1,954	75	1977	2052		46.67 %	0.00 %	35			\$20,204
C1020	Interior Doors	\$2.20	S.F.	1,954	30	2005	2035		60.00 %	0.00 %	18			\$4,299
C1030	Fittings	\$8.47	S.F.	1,954	20	1977	1997		0.00 %	110.00 %	-20		\$18,205.00	\$16,550
C3010	Wall Finishes	\$7.46	S.F.	1,954	10	2013	2023		60.00 %	0.00 %	6			\$14,577
C3020	Floor Finishes	\$12.74	S.F.	1,954	20	2005	2025		40.00 %	0.00 %	8			\$24,894
C3030	Ceiling Finishes	\$9.53	S.F.	1,954	25	2005	2030		52.00 %	0.00 %	13			\$18,622
D2010	Plumbing Fixtures	\$9.98	S.F.	1,954	30	1977	2007		0.00 %	110.00 %	-10		\$21,451.00	\$19,501
D2020	Domestic Water Distribution	\$0.84	S.F.	1,954	30	2005	2035		60.00 %	0.00 %	18			\$1,641
D2030	Sanitary Waste	\$5.94	S.F.	1,954	30	1977	2007		0.00 %	109.99 %	-10		\$12,767.00	\$11,607
D3050	Terminal & Package Units	\$16.96	S.F.	1,954	15	2005	2020		20.00 %	0.00 %	3			\$33,140
D5010	Electrical Service/Distribution	\$1.47	S.F.	1,954	40	2005	2045		70.00 %	0.00 %	28			\$2,872
D5020	Branch Wiring	\$2.55	S.F.	1,954	30	2005	2035		60.00 %	0.00 %	18			\$4,983
D5020	Lighting	\$3.58	S.F.	1,954	30	2005	2035		60.00 %	0.00 %	18			\$6,995
E2010	Fixed Furnishings	\$5.08	S.F.	1,954	20	2005	2025		40.00 %	0.00 %	8			\$9,926
Total									40.71 %	18.91 %			\$54,379.00	\$287,549

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls




Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:

Campus Assessment Report - 1977 Football Press Box

System: B3010140 - Asphalt Shingles



Note:

System: C1010 - Partitions



Note:


System: C1020 - Interior Doors



Note:

Campus Assessment Report - 1977 Football Press Box

System: C1030 - Fittings



Note:

System: C3010 - Wall Finishes



Note:

System: C3020 - Floor Finishes



Note:

Campus Assessment Report - 1977 Football Press Box

System: C3030 - Ceiling Finishes




Note:

System: D2010 - Plumbing Fixtures



Note:

System: D2020 - Domestic Water Distribution



Note:

Campus Assessment Report - 1977 Football Press Box

System: D2030 - Sanitary Waste



Note:

System: D3050 - Terminal & Package Units



Note:

System: D5010 - Electrical Service/Distribution



Note:

Campus Assessment Report - 1977 Football Press Box

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$54,379	\$0	\$0	\$39,834	\$0	\$0	\$19,147	\$0	\$64,132	\$0	\$0	\$177,491
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$1,956	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,956
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010140 - Asphalt Shingles	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$15,612	\$0	\$0	\$15,612
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$18,205	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$18,205
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$19,147	\$0	\$0	\$0	\$0	\$19,147
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$34,688	\$0	\$0	\$34,688
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Campus Assessment Report - 1977 Football Press Box

D2010 - Plumbing Fixtures	\$21,451	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$21,451
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2030 - Sanitary Waste	\$12,767	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$12,767
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$39,834	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$39,834
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$13,832	\$0	\$0	\$13,832

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.




Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$54,379.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
B2030	Exterior Doors	\$0.00	\$0.00	\$1,956.00	\$0.00	\$0.00	\$1,956.00
C1030	Fittings	\$0.00	\$0.00	\$18,205.00	\$0.00	\$0.00	\$18,205.00
D2010	Plumbing Fixtures	\$0.00	\$0.00	\$21,451.00	\$0.00	\$0.00	\$21,451.00
D2030	Sanitary Waste	\$0.00	\$0.00	\$12,767.00	\$0.00	\$0.00	\$12,767.00
	Total:	\$0.00	\$0.00	\$54,379.00	\$0.00	\$0.00	\$54,379.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$54,379.00

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):


System: B2030 - Exterior Doors



Location: Concession
Distress: Failing
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 1,954.00
Unit of Measure: S.F.
Estimate: \$1,956.00
Assessor Name: Eduardo Lopez
Date Created: 01/25/2017

Notes: The original exterior doors are aged, rusted, and should be replaced.

System: C1030 - Fittings



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 1,954.00
Unit of Measure: S.F.
Estimate: \$18,205.00
Assessor Name: Eduardo Lopez
Date Created: 01/25/2017

Notes: The fittings throughout the building are aged, in marginal condition, and should be replaced.

System: D2010 - Plumbing Fixtures



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance / Accessibility Code Compliance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 1,954.00
Unit of Measure: S.F.
Estimate: \$21,451.00
Assessor Name: Eduardo Lopez
Date Created: 01/25/2017

Notes: Plumbing fixtures are in operational conditions. However, they are aged, not ADA compliant and should be replaced with a low-flow water fixtures.

System: D2030 - Sanitary Waste



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 1,954.00
Unit of Measure: S.F.
Estimate: \$12,767.00
Assessor Name: Eduardo Lopez
Date Created: 01/25/2017

Notes: The sanitary waste system is aged, has reported periodic failures, and should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	1,200
Year Built:	1991
Last Renovation:	
Replacement Value:	\$183,348
Repair Cost:	\$50,424.00
Total FCI:	27.50 %
Total RSLI:	30.61 %
FCA Score:	72.50







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	1,200
Year Built:	1991	Last Renovation:	
Repair Cost:	\$50,424	Replacement Value:	\$183,348
FCI:	27.50 %	RSLI%:	30.61 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	74.00 %	0.00 %	\$0.00
B10 - Superstructure	74.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	56.39 %	0.00 %	\$0.00
B30 - Roofing	13.33 %	0.00 %	\$0.00
C10 - Interior Construction	35.91 %	49.53 %	\$11,180.00
C30 - Interior Finishes	0.00 %	110.00 %	\$39,244.00
D20 - Plumbing	13.33 %	0.00 %	\$0.00
D30 - HVAC	20.00 %	0.00 %	\$0.00
D50 - Electrical	29.65 %	0.00 %	\$0.00
E20 - Furnishings	15.00 %	0.00 %	\$0.00
Totals:	30.61 %	27.50 %	\$50,424.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). East Elevation - Feb 01, 2017



2). West Elevation - Feb 01, 2017



3). North Elevation - Feb 01, 2017



4). South Elevation - Feb 01, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

Campus Assessment Report - 1991 Baseball Fieldhouse

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$6.93	S.F.	1,200	100	1991	2091		74.00 %	0.00 %	74			\$8,316
A1030	Slab on Grade	\$7.37	S.F.	1,200	100	1991	2091		74.00 %	0.00 %	74			\$8,844
B1020	Roof Construction	\$5.98	S.F.	1,200	100	1991	2091		74.00 %	0.00 %	74			\$7,176
B2010	Exterior Walls	\$18.04	S.F.	1,200	100	1991	2091		74.00 %	0.00 %	74			\$21,648
B2020	Exterior Windows	\$6.47	S.F.	1,200	30	1991	2021		13.33 %	0.00 %	4			\$7,764
B2030	Exterior Doors	\$0.91	S.F.	1,200	30	1991	2021		13.33 %	0.00 %	4			\$1,092
B3010130	Preformed Metal Roofing	\$9.66	S.F.	1,200	30	1991	2021		13.33 %	0.00 %	4			\$11,592
C1010	Partitions	\$10.34	S.F.	1,200	75	1991	2066		65.33 %	0.00 %	49			\$12,408
C1030	Fittings	\$8.47	S.F.	1,200	20	1991	2011		0.00 %	110.00 %	-6		\$11,180.00	\$10,164
C3010	Wall Finishes	\$7.46	S.F.	1,200	10	2001	2011		0.00 %	110.00 %	-6		\$9,847.00	\$8,952
C3020	Floor Finishes	\$12.74	S.F.	1,200	20	1991	2011		0.00 %	110.00 %	-6		\$16,817.00	\$15,288
C3030	Ceiling Finishes	\$9.53	S.F.	1,200	25	1991	2016		0.00 %	110.00 %	-1		\$12,580.00	\$11,436
D2010	Plumbing Fixtures	\$9.98	S.F.	1,200	30	1991	2021		13.33 %	0.00 %	4			\$11,976
D2020	Domestic Water Distribution	\$0.84	S.F.	1,200	30	1991	2021		13.33 %	0.00 %	4			\$1,008
D2030	Sanitary Waste	\$5.94	S.F.	1,200	30	1991	2021		13.33 %	0.00 %	4			\$7,128
D3050	Terminal & Package Units	\$16.96	S.F.	1,200	15	2005	2020		20.00 %	0.00 %	3			\$20,352
D5010	Electrical Service/Distribution	\$1.47	S.F.	1,200	40	1991	2031		35.00 %	0.00 %	14			\$1,764
D5020	Branch Wiring	\$2.55	S.F.	1,200	30	1991	2021		13.33 %	0.00 %	4			\$3,060
D5020	Lighting	\$3.58	S.F.	1,200	30	1991	2021		13.33 %	0.00 %	4			\$4,296
D5030920	Data Communication	\$2.49	S.F.	1,200	15	2012	2027		66.67 %	0.00 %	10			\$2,988
E2010	Fixed Furnishings	\$5.08	S.F.	1,200	20	1991	2011	2020	15.00 %	0.00 %	3			\$6,096
Total									30.61 %	27.50 %			\$50,424.00	\$183,348

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls




Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:

Campus Assessment Report - 1991 Baseball Fieldhouse

System: B3010130 - Preformed Metal Roofing



Note:

System: C1010 - Partitions



Note:


System: C1030 - Fittings



Note:


Campus Assessment Report - 1991 Baseball Fieldhouse

System: C3010 - Wall Finishes




Note:

System: C3020 - Floor Finishes



Note:

System: C3030 - Ceiling Finishes



Note:

Campus Assessment Report - 1991 Baseball Fieldhouse

System: D2010 - Plumbing Fixtures



Note:

System: D2020 - Domestic Water Distribution



Note:



System: D2030 - Sanitary Waste



Note:

Campus Assessment Report - 1991 Baseball Fieldhouse

System: D3050 - Terminal & Package Units



Note:

System: D5010 - Electrical Service/Distribution



Note:



System: D5020 - Branch Wiring



Note:

Campus Assessment Report - 1991 Baseball Fieldhouse

System: D5020 - Lighting



Note:

System: D5030920 - Data Communication



Note:

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$50,424	\$0	\$0	\$31,791	\$62,977	\$0	\$0	\$0	\$0	\$0	\$17,651	\$162,842
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$9,612	\$0	\$0	\$0	\$0	\$0	\$0	\$9,612
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$1,352	\$0	\$0	\$0	\$0	\$0	\$0	\$1,352
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010130 - Preformed Metal Roofing	\$0	\$0	\$0	\$0	\$18,005	\$0	\$0	\$0	\$0	\$0	\$0	\$18,005
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$11,180	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$11,180
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$9,847	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$13,234	\$23,081
C3020 - Floor Finishes	\$16,817	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$16,817
C3030 - Ceiling Finishes	\$12,580	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$12,580
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$14,827	\$0	\$0	\$0	\$0	\$0	\$0	\$14,827


Campus Assessment Report - 1991 Baseball Fieldhouse

D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$1,248	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,248
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$8,825	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$8,825
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$24,463	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$24,463
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$3,788	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$3,788
D5020 - Lighting	\$0	\$0	\$0	\$0	\$5,319	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$5,319
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030920 - Data Communication	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$4,417	\$4,417
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$7,328	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$7,328

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.




Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$50,424.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
C1030	Fittings	\$0.00	\$0.00	\$0.00	\$11,180.00	\$0.00	\$11,180.00
C3010	Wall Finishes	\$0.00	\$0.00	\$9,847.00	\$0.00	\$0.00	\$9,847.00
C3020	Floor Finishes	\$0.00	\$0.00	\$16,817.00	\$0.00	\$0.00	\$16,817.00
C3030	Ceiling Finishes	\$0.00	\$0.00	\$12,580.00	\$0.00	\$0.00	\$12,580.00
	Total:	\$0.00	\$0.00	\$39,244.00	\$11,180.00	\$0.00	\$50,424.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$50,424.00

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):


System: C3010 - Wall Finishes



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 1,200.00
Unit of Measure: S.F.
Estimate: \$9,847.00
Assessor Name: Eduardo Lopez
Date Created: 01/25/2017

Notes: The wall paint is damaged, fading, stained, and should be re-painted.

System: C3020 - Floor Finishes



Location: Locker rooms
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 1,200.00
Unit of Measure: S.F.
Estimate: \$16,817.00
Assessor Name: Eduardo Lopez
Date Created: 01/25/2017

Notes: The carpet is aged, stained, frayed, and should be replaced.

System: C3030 - Ceiling Finishes



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 1,200.00
Unit of Measure: S.F.
Estimate: \$12,580.00
Assessor Name: Eduardo Lopez
Date Created: 01/25/2017

Notes: The original ceiling finishes are aged, failing and should be replaced.

Priority 4 - Recommended (Years 6-10):

System: C1030 - Fittings



Location: Throughout
Distress: Inadequate
Category: Deferred Maintenance / Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 1,200.00
Unit of Measure: S.F.
Estimate: \$11,180.00
Assessor Name: Eduardo Lopez
Date Created: 01/25/2017

Notes: The fittings throughout the building are aged, in marginal condition, handrails and room signage are ADA non-compliance and system should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	17,000
Year Built:	1998
Last Renovation:	
Replacement Value:	\$3,200,930
Repair Cost:	\$83,776.00
Total FCI:	2.62 %
Total RSLI:	39.94 %
FCA Score:	97.38







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	17,000
Year Built:	1998	Last Renovation:	
Repair Cost:	\$83,776	Replacement Value:	\$3,200,930
FCI:	2.62 %	RSLI%:	39.94 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	81.00 %	0.00 %	\$0.00
B10 - Superstructure	81.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	54.16 %	0.00 %	\$0.00
B30 - Roofing	5.58 %	0.00 %	\$0.00
C10 - Interior Construction	51.97 %	0.00 %	\$0.00
C30 - Interior Finishes	20.27 %	0.00 %	\$0.00
D20 - Plumbing	36.84 %	0.00 %	\$0.00
D30 - HVAC	29.71 %	0.00 %	\$0.00
D40 - Fire Protection	0.00 %	110.00 %	\$83,776.00
D50 - Electrical	52.37 %	0.00 %	\$0.00
E10 - Equipment	5.00 %	0.00 %	\$0.00
E20 - Furnishings	5.00 %	0.00 %	\$0.00
Totals:	39.94 %	2.62 %	\$83,776.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). Northeast Elevation - Feb 01, 2017



2). South Elevation - Feb 01, 2017



3). West Elevation - Feb 01, 2017



4). East Elevation - Feb 01, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Campus Assessment Report - 1998 Science Wing

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$2.32	S.F.	17,000	100	1998	2098		81.00 %	0.00 %	81			\$39,440
A1030	Slab on Grade	\$4.36	S.F.	17,000	100	1998	2098		81.00 %	0.00 %	81			\$74,120
B1010	Floor Construction	\$12.22	S.F.	17,000	100	1998	2098		81.00 %	0.00 %	81			\$207,740
B1020	Roof Construction	\$8.14	S.F.	17,000	100	1998	2098		81.00 %	0.00 %	81			\$138,380
B2010	Exterior Walls	\$9.48	S.F.	17,000	100	1998	2098		81.00 %	0.00 %	81			\$161,160
B2020	Exterior Windows	\$13.69	S.F.	17,000	30	1998	2028		36.67 %	0.00 %	11			\$232,730
B2030	Exterior Doors	\$0.86	S.F.	17,000	30	1998	2028		36.67 %	0.00 %	11			\$14,620
B3010120	Single Ply Membrane	\$6.98	S.F.	17,000	20	1998	2018		5.00 %	0.00 %	1			\$118,660
B3020	Roof Openings	\$0.22	S.F.	17,000	25	1998	2023		24.00 %	0.00 %	6			\$3,740
C1010	Partitions	\$5.03	S.F.	17,000	75	1998	2073		74.67 %	0.00 %	56			\$85,510
C1020	Interior Doors	\$2.61	S.F.	17,000	30	1998	2028		36.67 %	0.00 %	11			\$44,370
C1030	Fittings	\$1.58	S.F.	17,000	20	1998	2018		5.00 %	0.00 %	1			\$26,860
C3010	Wall Finishes	\$2.75	S.F.	17,000	10	2014	2024		70.00 %	0.00 %	7			\$46,750
C3020	Floor Finishes	\$11.72	S.F.	17,000	20	1998	2018		5.00 %	0.00 %	1			\$199,240
C3030	Ceiling Finishes	\$11.30	S.F.	17,000	25	1998	2023		24.00 %	0.00 %	6			\$192,100
D2010	Plumbing Fixtures	\$9.46	S.F.	17,000	30	1998	2028		36.67 %	0.00 %	11			\$160,820
D2020	Domestic Water Distribution	\$1.76	S.F.	17,000	30	1998	2028		36.67 %	0.00 %	11			\$29,920
D2030	Sanitary Waste	\$2.77	S.F.	17,000	30	1998	2028		36.67 %	0.00 %	11			\$47,090
D2040	Rain Water Drainage	\$0.67	S.F.	17,000	30	1998	2028		36.67 %	0.00 %	11			\$11,390
D2090	Other Plumbing Systems -Nat Gas	\$0.16	S.F.	17,000	40	1998	2038		52.50 %	0.00 %	21			\$2,720
D3020	Heat Generating Systems	\$7.42	S.F.	17,000	30	1998	2028		36.67 %	0.00 %	11			\$126,140
D3030	Cooling Generating Systems	\$7.68	S.F.	17,000	25	1998	2023		24.00 %	0.00 %	6			\$130,560
D3040	Distribution Systems	\$8.96	S.F.	17,000	30	1998	2028		36.67 %	0.00 %	11			\$152,320
D3060	Controls & Instrumentation	\$2.84	S.F.	17,000	20	1998	2018		5.00 %	0.00 %	1			\$48,280
D4010	Sprinklers	\$3.89	S.F.	17,000	30			2017	0.00 %	110.00 %	0		\$72,743.00	\$66,130
D4020	Standpipes	\$0.59	S.F.	17,000	30			2017	0.00 %	110.00 %	0		\$11,033.00	\$10,030
D5010	Electrical Service/Distribution	\$1.70	S.F.	17,000	40	1998	2038		52.50 %	0.00 %	21			\$28,900
D5020	Branch Wiring	\$4.87	S.F.	17,000	30	1998	2028		36.67 %	0.00 %	11			\$82,790
D5020	Lighting	\$11.38	S.F.	17,000	30	1998	2028		36.67 %	0.00 %	11			\$193,460
D5030810	Security & Detection Systems	\$2.10	S.F.	17,000	15	2013	2028		73.33 %	0.00 %	11			\$35,700
D5030910	Fire Alarm Systems	\$3.83	S.F.	17,000	15	2013	2028		73.33 %	0.00 %	11			\$65,110
D5030920	Data Communication	\$4.92	S.F.	17,000	15	2015	2030		86.67 %	0.00 %	13			\$83,640
D5090	Other Electrical Systems	\$0.73	S.F.	17,000	20			2017	0.00 %	0.00 %	0			\$12,410
E1020	Institutional Equipment	\$13.97	S.F.	17,000	20	1998	2018		5.00 %	0.00 %	1			\$237,490
E2010	Fixed Furnishings	\$5.33	S.F.	17,000	20	1998	2018		5.00 %	0.00 %	1			\$90,610
Total									39.94 %	2.62 %			\$83,776.00	\$3,200,930

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls




Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:

Campus Assessment Report - 1998 Science Wing

System: B3010120 - Single Ply Membrane





Note:

System: B3020 - Roof Openings



Note:

System: C1010 - Partitions



Note:

Campus Assessment Report - 1998 Science Wing

System: C1020 - Interior Doors





Note:

System: C1030 - Fittings



Note:


System: C3010 - Wall Finishes



Note:

Campus Assessment Report - 1998 Science Wing

System: C3020 - Floor Finishes




Note:

System: C3030 - Ceiling Finishes



Note:

System: D2010 - Plumbing Fixtures



Note:

Campus Assessment Report - 1998 Science Wing

System: D2020 - Domestic Water Distribution



Note:

System: D2030 - Sanitary Waste



Note:

System: D2040 - Rain Water Drainage



Note:

Campus Assessment Report - 1998 Science Wing

System: D2090 - Other Plumbing Systems -Nat Gas



Note:

System: D3020 - Heat Generating Systems



Note:

System: D3030 - Cooling Generating Systems



Note:

Campus Assessment Report - 1998 Science Wing

System: D3040 - Distribution Systems



Note:

System: D3060 - Controls & Instrumentation



Note:

System: D5010 - Electrical Service/Distribution



Note:



Campus Assessment Report - 1998 Science Wing

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:



System: D5030810 - Security & Detection Systems



Note:

Campus Assessment Report - 1998 Science Wing

System: D5030910 - Fire Alarm Systems



Note:

System: D5030920 - Data Communication



Note:

System: E1020 - Institutional Equipment



Note:

Campus Assessment Report - 1998 Science Wing

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$83,776	\$865,940	\$0	\$0	\$0	\$0	\$428,713	\$63,246	\$0	\$0	\$0	\$1,441,674
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010120 - Single Ply Membrane	\$0	\$183,330	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$183,330
B3020 - Roof Openings	\$0	\$0	\$0	\$0	\$0	\$0	\$4,912	\$0	\$0	\$0	\$0	\$4,912
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$0	\$30,432	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$30,432
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$63,246	\$0	\$0	\$0	\$63,246
C3020 - Floor Finishes	\$0	\$225,739	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$225,739
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$252,315	\$0	\$0	\$0	\$0	\$252,315


Campus Assessment Report - 1998 Science Wing

D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2040 - Rain Water Drainage	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2090 - Other Plumbing Systems -Nat Gas	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3030 - Cooling Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$171,485	\$0	\$0	\$0	\$0	\$0	\$171,485
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3060 - Controls & Instrumentation	\$0	\$54,701	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$54,701
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$72,743	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$72,743
D4020 - Standpipes	\$11,033	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$11,033
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030910 - Fire Alarm Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030920 - Data Communication	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5090 - Other Electrical Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$0	\$269,076	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$269,076
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$102,661	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$102,661

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.




Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$83,776.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
D4010	Sprinklers	\$0.00	\$0.00	\$0.00	\$72,743.00	\$0.00	\$72,743.00
D4020	Standpipes	\$0.00	\$0.00	\$0.00	\$11,033.00	\$0.00	\$11,033.00
	Total:	\$0.00	\$0.00	\$0.00	\$83,776.00	\$0.00	\$83,776.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 4 - Recommended (Years 6-10):

System: D4010 - Sprinklers

This deficiency has no image.

Location: Throughout
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 17,000.00
Unit of Measure: S.F.
Estimate: \$72,743.00
Assessor Name: Eduardo Lopez
Date Created: 01/25/2017

Notes: A Sprinkler system is missing and is recommended to be provided to comply with current codes.

System: D4020 - Standpipes

This deficiency has no image.

Location: Throughout
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 17,000.00
Unit of Measure: S.F.
Estimate: \$11,033.00
Assessor Name: Eduardo Lopez
Date Created: 01/25/2017

Notes: A Sprinkler system is missing and is recommended to be provided to comply with current codes.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	8,053
Year Built:	2004
Last Renovation:	
Replacement Value:	\$1,340,986
Repair Cost:	\$39,685.00
Total FCI:	2.96 %
Total RSLI:	55.47 %
FCA Score:	97.04







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	8,053
Year Built:	2004	Last Renovation:	
Repair Cost:	\$39,685	Replacement Value:	\$1,340,986
FCI:	2.96 %	RSLI%:	55.47 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	87.00 %	0.00 %	\$0.00
B10 - Superstructure	87.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	68.63 %	0.00 %	\$0.00
B30 - Roofing	35.00 %	0.00 %	\$0.00
C10 - Interior Construction	67.14 %	0.00 %	\$0.00
C30 - Interior Finishes	45.50 %	0.00 %	\$0.00
D20 - Plumbing	56.67 %	0.00 %	\$0.00
D30 - HVAC	50.09 %	0.00 %	\$0.00
D40 - Fire Protection	0.00 %	110.00 %	\$39,685.00
D50 - Electrical	40.83 %	0.00 %	\$0.00
E20 - Furnishings	35.00 %	0.00 %	\$0.00
Totals:	55.47 %	2.96 %	\$39,685.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). North Elevation - Feb 01, 2017



2). West Elevation - Feb 01, 2017



3). South Elevation - Feb 01, 2017



4). East Elevation - Feb 01, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$2.32	S.F.	8,053	100	2004	2104		87.00 %	0.00 %	87			\$18,683
A1030	Slab on Grade	\$4.36	S.F.	8,053	100	2004	2104		87.00 %	0.00 %	87			\$35,111
B1010	Floor Construction	\$12.22	S.F.	8,053	100	2004	2104		87.00 %	0.00 %	87			\$98,408
B1020	Roof Construction	\$8.14	S.F.	8,053	100	2004	2104		87.00 %	0.00 %	87			\$65,551
B2010	Exterior Walls	\$9.48	S.F.	8,053	100	2004	2104		87.00 %	0.00 %	87			\$76,342
B2020	Exterior Windows	\$13.69	S.F.	8,053	30	2004	2034		56.67 %	0.00 %	17			\$110,246
B2030	Exterior Doors	\$0.86	S.F.	8,053	30	2004	2034		56.67 %	0.00 %	17			\$6,926
B3010120	Single Ply Membrane	\$6.98	S.F.	8,053	20	2004	2024		35.00 %	0.00 %	7			\$56,210
C1010	Partitions	\$5.03	S.F.	8,053	75	2004	2079		82.67 %	0.00 %	62			\$40,507
C1020	Interior Doors	\$2.61	S.F.	8,053	30	2004	2034		56.67 %	0.00 %	17			\$21,018
C1030	Fittings	\$1.58	S.F.	8,053	20	2004	2024		35.00 %	0.00 %	7			\$12,724
C3010	Wall Finishes	\$2.75	S.F.	8,053	10	2015	2025		80.00 %	0.00 %	8			\$22,146
C3020	Floor Finishes	\$11.72	S.F.	8,053	20	2004	2024		35.00 %	0.00 %	7			\$94,381
C3030	Ceiling Finishes	\$11.30	S.F.	8,053	25	2004	2029		48.00 %	0.00 %	12			\$90,999
D2010	Plumbing Fixtures	\$9.46	S.F.	8,053	30	2004	2034		56.67 %	0.00 %	17			\$76,181
D2020	Domestic Water Distribution	\$1.76	S.F.	8,053	30	2004	2034		56.67 %	0.00 %	17			\$14,173
D2030	Sanitary Waste	\$2.77	S.F.	8,053	30	2004	2034		56.67 %	0.00 %	17			\$22,307
D2040	Rain Water Drainage	\$0.67	S.F.	8,053	30	2004	2034		56.67 %	0.00 %	17			\$5,396
D3030	Cooling Generating Systems	\$7.68	S.F.	8,053	25	2004	2029		48.00 %	0.00 %	12			\$61,847
D3040	Distribution Systems	\$8.96	S.F.	8,053	30	2004	2034		56.67 %	0.00 %	17			\$72,155
D3060	Controls & Instrumentation	\$2.84	S.F.	8,053	20	2004	2024		35.00 %	0.00 %	7			\$22,871
D4010	Sprinklers	\$3.89	S.F.	8,053	30			2017	0.00 %	110.00 %	0		\$34,459.00	\$31,326
D4020	Standpipes	\$0.59	S.F.	8,053	30			2017	0.00 %	110.00 %	0		\$5,226.00	\$4,751
D5010	Electrical Service/Distribution	\$1.70	S.F.	8,053	40	2004	2044		67.50 %	0.00 %	27			\$13,690
D5020	Branch Wiring	\$4.87	S.F.	8,053	30	2004	2034		56.67 %	0.00 %	17			\$39,218
D5020	Lighting	\$11.38	S.F.	8,053	30	2004	2034		56.67 %	0.00 %	17			\$91,643
D5030810	Security & Detection Systems	\$2.10	S.F.	8,053	15	2004	2019		13.33 %	0.00 %	2			\$16,911
D5030910	Fire Alarm Systems	\$3.83	S.F.	8,053	15	2004	2019		13.33 %	0.00 %	2			\$30,843
D5030920	Data Communication	\$4.92	S.F.	8,053	15	2004	2019		13.33 %	0.00 %	2			\$39,621
D5090	Other Electrical Systems	\$0.73	S.F.	8,053	20	2004	2024		35.00 %	0.00 %	7			\$5,879
E2010	Fixed Furnishings	\$5.33	S.F.	8,053	20	2004	2024		35.00 %	0.00 %	7			\$42,922
Total									55.47 %	2.96 %			\$39,685.00	\$1,340,986

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls




Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:



Campus Assessment Report - 2004 EC Wing

System: B3010120 - Single Ply Membrane




Note:

System: C1010 - Partitions



Note:




System: C1020 - Interior Doors



Note:



Campus Assessment Report - 2004 EC Wing

System: C1030 - Fittings





Note:

System: C3010 - Wall Finishes



Note:

System: C3020 - Floor Finishes



Note:

Campus Assessment Report - 2004 EC Wing

System: C3030 - Ceiling Finishes



Note:

System: D2010 - Plumbing Fixtures



Note:

System: D2020 - Domestic Water Distribution



Note:

Campus Assessment Report - 2004 EC Wing

System: D2030 - Sanitary Waste



Note:

System: D2040 - Rain Water Drainage



Note:

System: D3030 - Cooling Generating Systems



Note:


Campus Assessment Report - 2004 EC Wing

System: D3040 - Distribution Systems



Note:

System: D3060 - Controls & Instrumentation



Note:


System: D5010 - Electrical Service/Distribution



Note:



Campus Assessment Report - 2004 EC Wing

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:


System: D5030810 - Security & Detection Systems



Note:

Campus Assessment Report - 2004 EC Wing

System: D5030910 - Fire Alarm Systems



Note:

System: D5030920 - Data Communication



Note:

System: D5090 - Other Electrical Systems



Note:

Campus Assessment Report - 2004 EC Wing

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$39,685	\$0	\$101,965	\$0	\$0	\$0	\$0	\$345,558	\$30,859	\$0	\$0	\$518,066
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010120 - Single Ply Membrane	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$103,697	\$0	\$0	\$0	\$103,697
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$17,213	\$0	\$0	\$0	\$17,213
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$30,859	\$0	\$0	\$30,859
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$127,684	\$0	\$0	\$0	\$127,684
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Campus Assessment Report - 2004 EC Wing

D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2040 - Rain Water Drainage	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3030 - Cooling Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$30,941	\$0	\$0	\$0	\$0	\$30,941
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$34,459	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$34,459
D4020 - Standpipes	\$5,226	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$5,226
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$19,735	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$19,735
D5030910 - Fire Alarm Systems	\$0	\$0	\$35,993	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$35,993
D5030920 - Data Communication	\$0	\$0	\$46,237	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$46,237
D5090 - Other Electrical Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$7,954	\$0	\$0	\$0	\$0	\$7,954
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$58,068	\$0	\$0	\$0	\$0	\$58,068

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.




Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$39,685.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
D4010	Sprinklers	\$0.00	\$0.00	\$0.00	\$34,459.00	\$0.00	\$34,459.00
D4020	Standpipes	\$0.00	\$0.00	\$0.00	\$5,226.00	\$0.00	\$5,226.00
	Total:	\$0.00	\$0.00	\$0.00	\$39,685.00	\$0.00	\$39,685.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 4 - Recommended (Years 6-10):

System: D4010 - Sprinklers

This deficiency has no image.

Location: Throughout
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 8,053.00
Unit of Measure: S.F.
Estimate: \$34,459.00
Assessor Name: Eduardo Lopez
Date Created: 01/25/2017

Notes: A Sprinkler system is missing and is recommended to be provided to comply with current codes.

System: D4020 - Standpipes

This deficiency has no image.

Location: Throughout
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 8,053.00
Unit of Measure: S.F.
Estimate: \$5,226.00
Assessor Name: Eduardo Lopez
Date Created: 01/25/2017

Notes: A Sprinkler system is missing and is recommended to be provided to comply with current codes.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	2,520
Year Built:	2005
Last Renovation:	
Replacement Value:	\$388,938
Repair Cost:	\$3,354.00
Total FCI:	0.86 %
Total RSLI:	59.20 %
FCA Score:	99.14







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	2,520
Year Built:	2005	Last Renovation:	
Repair Cost:	\$3,354	Replacement Value:	\$388,938
FCI:	0.86 %	RSLI%:	59.20 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	88.00 %	0.00 %	\$0.00
B10 - Superstructure	88.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	79.87 %	0.00 %	\$0.00
B30 - Roofing	40.00 %	0.00 %	\$0.00
C10 - Interior Construction	63.75 %	0.00 %	\$0.00
C30 - Interior Finishes	53.88 %	0.00 %	\$0.00
D20 - Plumbing	60.00 %	0.00 %	\$0.00
D30 - HVAC	23.41 %	0.00 %	\$0.00
D50 - Electrical	46.06 %	11.78 %	\$3,354.00
E20 - Furnishings	40.00 %	0.00 %	\$0.00
Totals:	59.20 %	0.86 %	\$3,354.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). North Elevation - Feb 01, 2017



2). West Elevation - Feb 01, 2017



3). South Elevation - Feb 01, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing


The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$6.93	S.F.	2,520	100	2005	2105		88.00 %	0.00 %	88			\$17,464
A1030	Slab on Grade	\$7.37	S.F.	2,520	100	2005	2105		88.00 %	0.00 %	88			\$18,572
B1020	Roof Construction	\$5.98	S.F.	2,520	100	2005	2105		88.00 %	0.00 %	88			\$15,070
B2010	Exterior Walls	\$18.04	S.F.	2,520	100	2005	2105		88.00 %	0.00 %	88			\$45,461
B2020	Exterior Windows	\$6.47	S.F.	2,520	30	2005	2035		60.00 %	0.00 %	18			\$16,304
B2030	Exterior Doors	\$0.91	S.F.	2,520	30	2005	2035		60.00 %	0.00 %	18			\$2,293
B3010140	Asphalt Shingles	\$4.32	S.F.	2,520	20	2005	2025		40.00 %	0.00 %	8			\$10,886
C1010	Partitions	\$10.34	S.F.	2,520	75	2005	2080		84.00 %	0.00 %	63			\$26,057
C1020	Interior Doors	\$2.20	S.F.	2,520	30	2005	2035		60.00 %	0.00 %	18			\$5,544
C1030	Fittings	\$8.47	S.F.	2,520	20	2005	2025		40.00 %	0.00 %	8			\$21,344
C3010	Wall Finishes	\$7.46	S.F.	2,520	10	2015	2025		80.00 %	0.00 %	8			\$18,799
C3020	Floor Finishes	\$12.74	S.F.	2,520	20	2005	2025		40.00 %	0.00 %	8			\$32,105
C3030	Ceiling Finishes	\$9.53	S.F.	2,520	25	2005	2030		52.00 %	0.00 %	13			\$24,016
D2010	Plumbing Fixtures	\$9.98	S.F.	2,520	30	2005	2035		60.00 %	0.00 %	18			\$25,150
D2020	Domestic Water Distribution	\$0.84	S.F.	2,520	30	2005	2035		60.00 %	0.00 %	18			\$2,117
D2030	Sanitary Waste	\$5.94	S.F.	2,520	30	2005	2035		60.00 %	0.00 %	18			\$14,969
D3050	Terminal & Package Units	\$16.96	S.F.	2,520	15	2005	2020		20.00 %	0.00 %	3			\$42,739
D3060	Controls & Instrumentation	\$3.48	S.F.	2,520	20	2005	2025		40.00 %	0.00 %	8			\$8,770
D5010	Electrical Service/Distribution	\$1.47	S.F.	2,520	40	2005	2045		70.00 %	0.00 %	28			\$3,704
D5020	Branch Wiring	\$2.55	S.F.	2,520	30	2005	2035		60.00 %	0.00 %	18			\$6,426
D5020	Lighting	\$3.58	S.F.	2,520	30	2005	2035		60.00 %	0.00 %	18			\$9,022
D5030910	Fire Alarm Systems	\$1.21	S.F.	2,520	15			2017	0.00 %	110.00 %	0		\$3,354.00	\$3,049
D5030920	Data Communication	\$2.49	S.F.	2,520	15	2005	2020		20.00 %	0.00 %	3			\$6,275
E2010	Fixed Furnishings	\$5.08	S.F.	2,520	20	2005	2025		40.00 %	0.00 %	8			\$12,802
Total									59.20 %	0.86 %			\$3,354.00	\$388,938

System Notes


The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls





Note:

System: B2020 - Exterior Windows



Note:


System: B2030 - Exterior Doors



Note:


Campus Assessment Report - 2005 Football Fieldhouse

System: B3010140 - Asphalt Shingles



Note:

System: C1010 - Partitions



Note:

System: C1020 - Interior Doors



Note:


Campus Assessment Report - 2005 Football Fieldhouse

System: C1030 - Fittings




Note:

System: C3010 - Wall Finishes



Note:

System: C3020 - Floor Finishes



Note:


Campus Assessment Report - 2005 Football Fieldhouse

System: C3030 - Ceiling Finishes




Note:

System: D2010 - Plumbing Fixtures



Note:


System: D2020 - Domestic Water Distribution



Note:


Campus Assessment Report - 2005 Football Fieldhouse

System: D2030 - Sanitary Waste




Note:

System: D3050 - Terminal & Package Units



Note:


System: D3060 - Controls & Instrumentation



Note:

Campus Assessment Report - 2005 Football Fieldhouse

System: D5010 - Electrical Service/Distribution






Note:

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:


Campus Assessment Report - 2005 Football Fieldhouse

System: D5030920 - Data Communication



Note:

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$3,354	\$0	\$0	\$58,914	\$0	\$0	\$0	\$0	\$150,867	\$0	\$0	\$213,136
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010140 - Asphalt Shingles	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$20,134	\$0	\$0	\$20,134
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$29,742	\$0	\$0	\$29,742
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$26,196	\$0	\$0	\$26,196
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$44,736	\$0	\$0	\$44,736
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Campus Assessment Report - 2005 Football Fieldhouse

D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$51,372	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$51,372
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$12,221	\$0	\$12,221
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030910 - Fire Alarm Systems	\$3,354	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$3,354
D5030920 - Data Communication	\$0	\$0	\$0	\$7,542	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$7,542
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$17,839	\$0	\$17,839

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$3,354.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$3,354.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
D5030910	Fire Alarm Systems	\$0.00	\$0.00	\$3,354.00	\$0.00	\$0.00	\$3,354.00
	Total:	\$0.00	\$0.00	\$3,354.00	\$0.00	\$0.00	\$3,354.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: D5030910 - Fire Alarm Systems

This deficiency has no image.

Location: Throughout
Distress: Missing
Category: Building Code Compliance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 2,520.00
Unit of Measure: S.F.
Estimate: \$3,354.00
Assessor Name: Eduardo Lopez
Date Created: 01/25/2017

Notes: A fire alarm system is missing and is recommended to be provided to comply with current codes.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	9,000
Year Built:	2009
Last Renovation:	
Replacement Value:	\$1,458,900
Repair Cost:	\$0.00
Total FCI:	0.00 %
Total RSLI:	79.22 %
FCA Score:	100.00



Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary


Function:	HS -High School	Gross Area:	9,000
Year Built:	2009	Last Renovation:	
Repair Cost:	\$0	Replacement Value:	\$1,458,900
FCI:	0.00 %	RSLI%:	79.22 %

No data found for this asset

No data found for this asset

No data found for this asset

10 Year Investment Forecast



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	92.00 %	0.00 %	\$0.00
B10 - Superstructure	92.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	87.80 %	0.00 %	\$0.00
B30 - Roofing	73.33 %	0.00 %	\$0.00
C30 - Interior Finishes	58.78 %	0.00 %	\$0.00
D50 - Electrical	73.33 %	0.00 %	\$0.00
Totals:	79.22 %	0.00 %	\$0.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). Southeast Elevation - Feb 01, 2017



2). Northwest Elevation - Feb 01, 2017



3). Northeast Elevation - Feb 01, 2017



4). Southwest Elevation - Feb 01, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$20.13	S.F.	9,000	100	2009	2109		92.00 %	0.00 %	92			\$181,170
A1030	Slab on Grade	\$19.75	S.F.	9,000	100	2009	2109		92.00 %	0.00 %	92			\$177,750
B1020	Roof Construction	\$16.26	S.F.	9,000	100	2009	2109		92.00 %	0.00 %	92			\$146,340
B2010	Exterior Walls	\$29.79	S.F.	9,000	100	2009	2109		92.00 %	0.00 %	92			\$268,110
B2030	Exterior Doors	\$8.66	S.F.	9,000	30	2009	2039		73.33 %	0.00 %	22			\$77,940
B3010130	Preformed Metal Roofing	\$9.66	S.F.	9,000	30	2009	2039		73.33 %	0.00 %	22			\$86,940
C3010	Wall Finishes	\$5.11	S.F.	9,000	10	2009	2019		20.00 %	0.00 %	2			\$45,990
C3020	Floor Finishes	\$20.82	S.F.	9,000	20	2009	2029		60.00 %	0.00 %	12			\$187,380
C3030	Ceiling Finishes	\$18.76	S.F.	9,000	25	2009	2034		68.00 %	0.00 %	17			\$168,840
D5020	Branch Wiring	\$3.58	S.F.	9,000	30	2009	2039		73.33 %	0.00 %	22			\$32,220
D5020	Lighting	\$9.58	S.F.	9,000	30	2009	2039		73.33 %	0.00 %	22			\$86,220
Total									79.22 %					\$1,458,900

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B1020 - Roof Construction



Note:

System: B2010 - Exterior Walls



Note:

System: B2030 - Exterior Doors



Note:



Campus Assessment Report - 2009 Orr Buiding

System: B3010130 - Preformed Metal Roofing




Note:

System: C3010 - Wall Finishes



Note:

System: C3020 - Floor Finishes



Note:

Campus Assessment Report - 2009 Orr Buiding

System: C3030 - Ceiling Finishes



Note:

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.


Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$0	\$0	\$53,670	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$53,670
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010130 - Preformed Metal Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$53,670	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$53,670
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

* Indicates non-renewable system

Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.

No data found for this asset

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

No data found for this asset

Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

No data found for this asset

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:

No data found for this asset

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

No data found for this asset

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	1,386
Year Built:	2012
Last Renovation:	
Replacement Value:	\$191,142
Repair Cost:	\$0.00
Total FCI:	0.00 %
Total RSLI:	83.27 %
FCA Score:	100.00



Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary


Function:	HS -High School	Gross Area:	1,386
Year Built:	2012	Last Renovation:	
Repair Cost:	\$0	Replacement Value:	\$191,142
FCI:	0.00 %	RSLI%:	83.27 %

No data found for this asset

No data found for this asset

No data found for this asset

10 Year Investment Forecast



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	95.00 %	0.00 %	\$0.00
B10 - Superstructure	95.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	94.44 %	0.00 %	\$0.00
B30 - Roofing	83.33 %	0.00 %	\$0.00
C10 - Interior Construction	85.08 %	0.00 %	\$0.00
C30 - Interior Finishes	70.33 %	0.00 %	\$0.00
D20 - Plumbing	83.33 %	0.00 %	\$0.00
D30 - HVAC	80.05 %	0.00 %	\$0.00
D50 - Electrical	80.20 %	0.00 %	\$0.00
E20 - Furnishings	75.00 %	0.00 %	\$0.00
Totals:	83.27 %	0.00 %	\$0.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). Southwest Elevation - Feb 01, 2017



2). Southwest Elevation - Feb 01, 2017



3). Northwest Elevation - Feb 01, 2017



4). Southeast Elevation - Feb 01, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$6.93	S.F.	1,386	100	2012	2112		95.00 %	0.00 %	95			\$9,605
A1030	Slab on Grade	\$7.37	S.F.	1,386	100	2012	2112		95.00 %	0.00 %	95			\$10,215
B1020	Roof Construction	\$5.98	S.F.	1,386	100	2012	2112		95.00 %	0.00 %	95			\$8,288
B2010	Exterior Walls	\$18.04	S.F.	1,386	100	2012	2112		95.00 %	0.00 %	95			\$25,003
B2030	Exterior Doors	\$0.91	S.F.	1,386	30	2012	2042		83.33 %	0.00 %	25			\$1,261
B3010130	Preformed Metal Roofing	\$9.66	S.F.	1,386	30	2012	2042		83.33 %	0.00 %	25			\$13,389
C1010	Partitions	\$10.34	S.F.	1,386	75	2012	2087		93.33 %	0.00 %	70			\$14,331
C1030	Fittings	\$8.47	S.F.	1,386	20	2012	2032		75.00 %	0.00 %	15			\$11,739
C3010	Wall Finishes	\$7.46	S.F.	1,386	10	2012	2022		50.00 %	0.00 %	5			\$10,340
C3020	Floor Finishes	\$12.74	S.F.	1,386	20	2012	2032		75.00 %	0.00 %	15			\$17,658
C3030	Ceiling Finishes	\$9.53	S.F.	1,386	25	2012	2037		80.00 %	0.00 %	20			\$13,209
D2010	Plumbing Fixtures	\$9.98	S.F.	1,386	30	2012	2042		83.33 %	0.00 %	25			\$13,832
D2020	Domestic Water Distribution	\$0.84	S.F.	1,386	30	2012	2042		83.33 %	0.00 %	25			\$1,164
D2030	Sanitary Waste	\$5.94	S.F.	1,386	30	2012	2042		83.33 %	0.00 %	25			\$8,233
D3040	Distribution Systems	\$5.35	S.F.	1,386	30	2012	2042		83.33 %	0.00 %	25			\$7,415
D3060	Controls & Instrumentation	\$3.48	S.F.	1,386	20	2012	2032		75.00 %	0.00 %	15			\$4,823
D5010	Electrical Service/Distribution	\$1.47	S.F.	1,386	40	2012	2052		87.50 %	0.00 %	35			\$2,037
D5020	Branch Wiring	\$2.55	S.F.	1,386	30	2012	2042		83.33 %	0.00 %	25			\$3,534
D5020	Lighting	\$3.58	S.F.	1,386	30	2012	2042		83.33 %	0.00 %	25			\$4,962
D5030810	Security & Detection Systems	\$1.00	Ea.	1,386	15	2012	2027		66.67 %	0.00 %	10			\$1,386
D5030910	Fire Alarm Systems	\$1.21	S.F.	1,386	15	2012	2027		66.67 %	0.00 %	10			\$1,677
E2010	Fixed Furnishings	\$5.08	S.F.	1,386	20	2012	2032		75.00 %	0.00 %	15			\$7,041
Total									83.27 %					\$191,142

System Notes


The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B1020 - Roof Construction



Note:

System: B2010 - Exterior Walls



Note:

System: B2030 - Exterior Doors



Note:


Campus Assessment Report - 2012 Softball Fieldhouse

System: B3010130 - Preformed Metal Roofing




Note:

System: C1010 - Partitions



Note:


System: C1030 - Fittings



Note:

Campus Assessment Report - 2012 Softball Fieldhouse

System: C3010 - Wall Finishes



Note:

System: C3020 - Floor Finishes



Note:

System: C3030 - Ceiling Finishes



Note:


Campus Assessment Report - 2012 Softball Fieldhouse

System: D2010 - Plumbing Fixtures



Note:

System: D2020 - Domestic Water Distribution



Note:

System: D2030 - Sanitary Waste



Note:

Campus Assessment Report - 2012 Softball Fieldhouse

System: D3040 - Distribution Systems




Note:

System: D3060 - Controls & Instrumentation



Note:

System: D5010 - Electrical Service/Distribution



Note:

Campus Assessment Report - 2012 Softball Fieldhouse

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

System: D5030810 - Security & Detection Systems



Note:

Campus Assessment Report - 2012 Softball Fieldhouse

System: D5030910 - Fire Alarm Systems



Note:

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$0	\$0	\$0	\$0	\$0	\$13,186	\$0	\$0	\$0	\$0	\$4,529	\$17,715
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010130 - Preformed Metal Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$0	\$13,186	\$0	\$0	\$0	\$0	\$0	\$13,186
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Campus Assessment Report - 2012 Softball Fieldhouse

D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,049	\$2,049
D5030910 - Fire Alarm Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,480	\$2,480
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

* Indicates non-renewable system

Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.

No data found for this asset

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

No data found for this asset

Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

No data found for this asset

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:

No data found for this asset

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

No data found for this asset

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	153,113
Year Built:	1976
Last Renovation:	
Replacement Value:	\$6,084,710
Repair Cost:	\$333,480.00
Total FCI:	5.48 %
Total RSLI:	33.91 %
FCA Score:	94.52







Description:

The narrative for this site is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	153,113
Year Built:	1976	Last Renovation:	
Repair Cost:	\$333,480	Replacement Value:	\$6,084,710
FCI:	5.48 %	RSLI%:	33.91 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
G20 - Site Improvements	34.91 %	8.64 %	\$333,480.00
G30 - Site Mechanical Utilities	31.71 %	0.00 %	\$0.00
G40 - Site Electrical Utilities	33.04 %	0.00 %	\$0.00
Totals:	33.91 %	5.48 %	\$333,480.00

Photo Album

The photo album consists of the various cardinal directions of the building..

- 1). Aerial Image of Mountain Heritage High School - Feb 24, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
G2010	Roadways	\$3.76	S.F.	153,113	25	2005	2030		52.00 %	0.00 %	13			\$575,705
G2020	Parking Lots	\$1.61	S.F.	153,113	25	2005	2030		52.00 %	0.00 %	13			\$246,512
G2030	Pedestrian Paving	\$1.98	S.F.	153,113	30	1976	2006		0.00 %	110.00 %	-11		\$333,480.00	\$303,164
G2040105	Fence & Guardrails	\$1.20	S.F.	153,113	30	2005	2035		60.00 %	0.00 %	18			\$183,736
G2040950	Baseball Field	\$5.78	S.F.	153,113	20	1991	2011	2021	20.00 %	0.00 %	4			\$884,993
G2040950	Football Field	\$3.38	S.F.	153,113	20	2005	2025		40.00 %	0.00 %	8			\$517,522
G2040950	Softball Field	\$2.01	S.F.	153,113	20	2012	2032		75.00 %	0.00 %	15			\$307,757
G2040950	Tennis Courts	\$1.80	S.F.	153,113	20	1999	2019		10.00 %	0.00 %	2			\$275,603
G2040950	Track	\$1.78	S.F.	153,113	20	2005	2025		40.00 %	0.00 %	8			\$272,541
G2050	Landscaping	\$1.91	S.F.	153,113	15	2005	2020		20.00 %	0.00 %	3			\$292,446
G3010	Water Supply	\$2.42	S.F.	153,113	50	2005	2055		76.00 %	0.00 %	38			\$370,533
G3020	Sanitary Sewer	\$1.52	S.F.	153,113	50	1976	2026		18.00 %	0.00 %	9			\$232,732
G3030	Storm Sewer	\$4.67	S.F.	153,113	50	1976	2026		18.00 %	0.00 %	9			\$715,038
G3060	Fuel Distribution	\$1.03	S.F.	153,113	40	1976	2016	2021	10.00 %	0.00 %	4			\$157,706
G4010	Electrical Distribution	\$2.44	S.F.	153,113	50	1976	2026		18.00 %	0.00 %	9			\$373,596
G4020	Site Lighting	\$1.57	S.F.	153,113	30	2005	2035		60.00 %	0.00 %	18			\$240,387
G4030	Site Communications & Security	\$0.88	S.F.	153,113	15	2013	2028	2021	26.67 %	0.00 %	4			\$134,739
Total									33.91 %	5.48 %			\$333,480.00	\$6,084,710

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: G2010 - Roadways



Note:

System: G2020 - Parking Lots



Note:

Campus Assessment Report - Site

System: G2030 - Pedestrian Paving



Note:

System: G2040105 - Fence & Guardrails



Note:

System: G2040950 - Baseball Field



Note:

Campus Assessment Report - Site

System: G2040950 - Football Field



Note:

System: G2040950 - Softball Field



Note:

System: G2040950 - Tennis Courts



Note:

Campus Assessment Report - Site

System: G2040950 - Track



Note:

System: G2050 - Landscaping



Note:

System: G3010 - Water Supply



Note:

Campus Assessment Report - Site

System: G3020 - Sanitary Sewer



Note:

System: G3030 - Storm Sewer



Note:


System: G3060 - Fuel Distribution



Note:

Campus Assessment Report - Site

System: G4010 - Electrical Distribution



Note:

System: G4020 - Site Lighting



Note:

System: G4030 - Site Communications & Security



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.


Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$333,480	\$0	\$321,627	\$0	\$1,457,739	\$0	\$0	\$0	\$1,100,911	\$1,896,489	\$0	\$5,110,245
G - Building Sitework	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G20 - Site Improvements	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2010 - Roadways	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2020 - Parking Lots	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2030 - Pedestrian Paving	\$333,480	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$333,480
G2040 - Site Development	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040105 - Fence & Guardrails	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040950 - Baseball Field	\$0	\$0	\$0	\$0	\$1,095,674	\$0	\$0	\$0	\$0	\$0	\$0	\$1,095,674
G2040950 - Football Field	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$721,139	\$0	\$0	\$721,139
G2040950 - Softball Field	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040950 - Tennis Courts	\$0	\$0	\$321,627	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$321,627
G2040950 - Track	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$379,771	\$0	\$0	\$379,771
* G2050 - Landscaping	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G30 - Site Mechanical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3010 - Water Supply	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3020 - Sanitary Sewer	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$334,028	\$0	\$334,028
G3030 - Storm Sewer	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,026,258	\$0	\$1,026,258
G3060 - Fuel Distribution	\$0	\$0	\$0	\$0	\$195,250	\$0	\$0	\$0	\$0	\$0	\$0	\$195,250
G40 - Site Electrical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4010 - Electrical Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$536,203	\$0	\$536,203
G4020 - Site Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4030 - Site Communications & Security	\$0	\$0	\$0	\$0	\$166,815	\$0	\$0	\$0	\$0	\$0	\$0	\$166,815

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.




Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$333,480.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
G2030	Pedestrian Paving	\$0.00	\$0.00	\$333,480.00	\$0.00	\$0.00	\$333,480.00
	Total:	\$0.00	\$0.00	\$333,480.00	\$0.00	\$0.00	\$333,480.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$333,480.00

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: G2030 - Pedestrian Paving



Location: Multiple areas
Distress: Failing
Category: Deferred Maintenance / Safety
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 153,113.00
Unit of Measure: S.F.
Estimate: \$333,480.00
Assessor Name: Matt Mahaffey
Date Created: 01/25/2017

Notes: The pedestrian paving and walkways are aged and showing inclement weather damage and should be replaced.
